



Vehicle History Summary

Fleet #	ATT 069
Registration	
Make	Mack
Model	Metroliner
VIN / Chassis #	6FMU15D71JD810079
Build Date	2018

Date	Reading / Units	Type / Repairer Notes	Repairer
27/07/2025	3,678,779 kms 111,767 hrs	head gasket R-18218 remove hardware - remove all compent around cylinder head -remove cylinder - found head gasket cracked - create notes and parts list for further repairs	Maxx Truck Repairs Pty Ltd
10/07/2025		coolant R-17414 Engine rebuild in progress	Simon Wade
08/06/2025	3,678,779 kms 111,767 hrs	puncture repair T-3511 PUNCTURE REPAIR	All Tyres Australia
29/04/2025		auto transmission R-17456 test run and check trans	Simon Wade (Mechanic)
29/04/2025		axle brakes R-17457 check all brake adjustments and test-ok	Simon Wade (Mechanic)
29/04/2025		beacon faulty R-17415 awaiting parts and time after rebuild	Simon Wade (Mechanic)
04/04/2025	365,615 kms	A - 15/30 days S-13071 INSTALLED 7 LTR ENGINE OIL-DONE INSTALL 3 LTR COOLANT-DONE DIFF FILTER HOUSING LEAK 6 X WHEEL NUT INDICATORS NEEDED 3 X TAILGATE GREASE NIPPLES-DONE NEXT B SERVICE 387,970	Simon Wade (Mechanic)
04/04/2025	365,615 kms	U BOLTS R-17365 INSTALL 2 X NEW AXLE 4 N/S U-BOLTS WITH ALL NUTS,WASHERS AND CONED SPACERS	Simon Wade (Mechanic)
27/03/2025		Air Leak R-17189 No air leak	Blair Wade
27/03/2025		uhf clip R-17348 install new uhf handpiece clip	Simon Wade (Mechanic)
27/03/2025		uhf clip R-17347 install new uhf handpiece clip	Simon Wade (Mechanic)
27/03/2025		camera monitor R-17160 Replaced fuse	Blair Wade
20/03/2025		air leak tyre R-17553 Tyre repaired by all tyres aus	Simon Wade (Mechanic)
19/03/2025	359,692 kms	C - 100k/ Annual S-12735	multispares

Date	Reading / Units	Type / Repairer Notes	Repairer
		WF2074 WATER FILTER 12 UNITS D256C1 28.18 28.18 1 1 LF3311 DIFF FILTER D255C2 20.71 20.71 1 1 AS2474 ADBLUE FILTER - SPIN ON D255C1 15.30 15.30 1 1 57P4600 CABIN FILTER D163A1 24.74 24.74 1 1 8PK1956HD MICRO V BELT - GATES FLEETRANNER D410C4 74.30 74.30 1 1 9412HD GATES FLEETRANNER V-BELT 13A1040 D415C3 38.61 38.61 1 1 49G8733KNORR AIR DRYER OIL SEPARATOR CARTRIDGE - BLUE D107E1 108.38 108.38 1 1 29558329 GEARBOX FILTER KIT - ALLISON OE D256B1 131.33 131.33	
13/03/2025		Air Leak R-17243 checked for air leaks none found, noted adblue doser makes noise after shut down.	Blair Wade
13/03/2025		monitor R-17239 Install fuse for monitor	Blair Wade
13/03/2025		faulty UHF R-17215 TEST UHF IN YARD NO FAULT FOUND	Simon Wade (Mechanic)
03/03/2025		fuel R-17154 Ray has fueled tonight	Simon Wade (Mechanic)
26/02/2025		air leak tyre R-16925 Tyre repaired by all tyres aus	Simon Wade (Mechanic)
26/02/2025		air con vents R-15529 air vent installed	Christopher Watson-Mechanic
26/02/2025		Airbags R-16924 Install axle 4 n/s airbag	Simon Wade (Mechanic)
26/02/2025		Air leak R-16923 Replace n/s axle 4 airbag	Simon Wade (Mechanic)
26/02/2025		Airbags R-16926 new axle 4 n/s airbag installed	Simon Wade (Mechanic)
19/02/2025		no fuel R-16817 not a mechanical defect	Simon Wade (Mechanic)
10/02/2025	359,692 kms	engine light R-16173 At time of service no fault found	
10/02/2025	359,692 kms	engine light R-16287 At time of service no fault found	
10/02/2025	359,692 kms	Airbags R-16790 Install new axle 4 n/s airbag	Blair Wade
10/02/2025	359,692 kms	seat belt R-15528 New seat belt installed	Christopher Watson-Mechanic
10/02/2025	359,692 kms	A - 15/30 days S-12908 A SERVICE NEXT B - 387,970 - New airbag installed - 3L of coolant added	Blair Wade
10/02/2025	359,692 kms	Coolant leak R-15718 At time of service no fault found	
10/02/2025	359,692 kms	low power R-16126 Test drove truck to check for low power Brought truck into workshop and used scan tool to help diagnose low power issue, Found engine was having issues with ecu communication of injectors on cylinders 4,5&6. Have advised to replace engine harness or send to an auto electrician Also need a new abs sensor for 1st drive O/S to fix abs faults.	Christopher Watson-Mechanic
06/02/2025		electrical faults R-16772 Cleared any faults	Simon Wade (Mechanic)
06/02/2025		wiper blades R-16737	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
		new wiper blades installed	
30/01/2025	360,766 kms	axle brake booster R-16622 Install new axle 5 n/s brake booster	Simon Wade (Mechanic)
30/01/2025		air leak, R-16625 Install new n/s axle 5 booster	Simon Wade (Mechanic)
29/01/2025		faulty wipers R-16626 Install new wiper blades	Simon Wade (Mechanic)
25/01/2025	357,920 kms	B - 30k S-12949 B SERVICE NEXT B - 387,920	Blair Wade
25/01/2025	357,920 kms	C - 100k/ Annual S-12950 C SERVICE NEXT B - 387,920	Blair Wade
21/01/2025		faulty wipers R-16592 Replace wiper blade	Simon Wade (Mechanic)
21/01/2025		faulty wipers R-16593 Install new wiper blade	Simon Wade (Mechanic)
20/01/2025		fuel R-16535 This is not a defect	Simon Wade (Mechanic)
15/01/2025		Load cover motor R-16644 Labour to locate and replace faulty load cover motor and test. 105.00 GST 10.50 105.00 12v Load Cover Motor (32352) 1 300.00 GST 30.00 300.00 Workshop Consumables 15.00 GST 1.50 15.00	Ace Air Auto Electrical
14/01/2025		batteries R-16645 123102 2.00 N70ZZH MF Century 200.00 400.00	
07/01/2025	356,322 kms	A - 15/30 days S-12781 2 X NEW BATTERIES INSTALLED NEXT B 354,313	Simon Wade (Mechanic)
07/01/2025		Flat batteries R-16489 Install 2 new batteries	Blair Wade
19/12/2024		Blocked cabin filters R-16462 Install new cabin filter	Simon Wade (Mechanic)
19/12/2024		overtaking sign R-16461 Remove and glue n/s overtaking sign	Simon Wade (Mechanic)
19/12/2024	356,159 kms 111,767 hrs	Puncture T-3294 Puncture repair	All Tyres Australia
16/12/2024	356,159 kms 111,767 hrs	Horton fan clutch R-16469 57N0908 ATT061 UPGRADE KIT - FAN CLUTCH HORTON D103B4 1026.09 1,026.09	multispares
13/12/2024	355,766 kms	tarp bearing R-16452 Install new o/s tarp tensioner bearing	Simon Wade (Mechanic)
09/12/2024		faulty wipers R-16395 Install new wiper blades	Simon Wade (Mechanic)
09/12/2024	355,147 kms	Batteries R-16381 Check batteries ok	Simon Wade (Mechanic)
09/12/2024		Electrical R-16393	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
		Replace headlight globe install new beacon complete	
09/12/2024		beacon faulty R-16401	Simon Wade (Mechanic)
		Install new beacon	
09/12/2024		faulty wipers R-16398	Simon Wade (Mechanic)
		Install new wiper blades	
09/12/2024		blown headlight R-16397	Simon Wade (Mechanic)
		Install new headlight globe install new beacon	
05/12/2024	354,714 kms	A - 15/30 days S-12709	Christopher Watson-Mechanic
23/11/2024	353,724 kms	trailer tyres T-3256	All Tyres Australia
		Fitted 4 x Evergreen11R22.5 148/145L EDL12 - Solid Shoulder 4 POS 13-14-15-16 2 x Tyre Disposal	
22/11/2024		check tyres R-16360	Simon Wade (Mechanic)
		Tyres booked Sunday all tyres aus	
05/11/2024	349,863 kms	A - 15/30 days S-12635	
		A SERVICE NEXT B - 354,313	
04/11/2024		Coolant leak R-16463	Simon Wade (Mechanic)
		Tighten loose hose clamp	
29/10/2024		jump start R-16172	Simon Wade (Mechanic)
		noted-no fault found with batteries	
28/10/2024		coolant, R-16169	Simon Wade (Mechanic)
		Tighten coolant hoses at n/s of engine	
16/10/2024		Exhaust R-16040	Christopher Watson-Mechanic
		Install new manifold gaskets	
16/10/2024	347,904 kms	exhaust manifold R-16025	Christopher Watson-Mechanic
		Stripped down exhaust manifold, Sand down exhaust manifold on a piece of glass to get it all level and true, Re assemble exhaust manifold with new gaskets,bolts & spacers. Start up and recheck for any leaks.	
16/10/2024		check exhaust leak R-16034	Christopher Watson-Mechanic
		Install manifold gaskets	
16/10/2024		Exhaust R-16044	Simon Wade (Mechanic)
		Install new manifold gaskets	
14/10/2024	347,596 kms	repair,strip and fit T-3214	All Tyres Australia
		Fitted 4 x Customer Runout - POS 5-6-7-8	
10/10/2024	347,422 kms	A - 15/30 days S-12503	Blair Wade
		A SERVICE NEXT B - 354,313	
16/09/2024		new tyres R-15886	Simon Wade (Mechanic)
		Tyres replaced by all tyres australia	
16/09/2024		mirror tint scratched R-15717	Simon Wade (Mechanic)
		Removed window tint	
11/09/2024		Welding R-15966	sloanbuilt
		carried out welding required	
06/09/2024	342,255 kms	A - 15/30 days S-12372	Christopher Watson-Mechanic

Date	Reading / Units	Type / Repairer Notes	Repairer
06/09/2024	342,255 kms	hub and wheel nut covers R-15822 Replace wheel nut indicators on axle 3,4,5 Replace hub caps on axles 4&5	Christopher Watson-Mechanic
30/08/2024	341,546 kms	trailer tyres T-3137 Fitted 2 x Evergreen 295/80R22.5 152/149M EG901 - Steer - POS3-4 also fitted 4 x customer runouts - POS 5-6-7-8	All Tyres Australia
30/08/2024	341,546 kms	A - 15/30 days S-13923	Blair Wade, Simon Wade
20/08/2024		trailer tyres T-3120 Fitted 4 x Greentour 11R22.5 149/146K GDM601	All Tyres Australia
14/08/2024		window tint R-15764 Remove window tint	Simon Wade (Mechanic)
14/08/2024		window tint R-15765 remove window tint	Simon Wade (Mechanic)
14/08/2024		window tint R-15766 Remove window tint	Simon Wade (Mechanic)
02/08/2024		Coolant leak R-15628 Install new header tank	Blair Wade
18/07/2024	335,205 kms 12,336 hrs	Bent tarp bows R-15570 Removed the last 5 tarp bows and straightened them then refitted them and replace the tarp cables.	Christopher Watson-Mechanic
11/07/2024	333,680 kms	seat belt R-15533 Install new drivers seat belt	Simon Wade (Mechanic)
10/07/2024	333,680 kms 12,267 hrs	Dual Weight Gauge R-15527 Repaired weight gauge	Christopher Watson-Mechanic
10/07/2024	333,680 kms 12,267 hrs	Adjusted tarp R-15522 Adjusted tarp will do for the time being will need new tarp bows asap.	Christopher Watson-Mechanic
10/07/2024	333,680 kms 12,199 hrs	camera R-15492 Fitted new wires and camera tested ok	Christopher Watson-Mechanic
10/07/2024	333,680 kms 12,209 hrs	camera R-15491 Fitted new wires and camera tested ok	Christopher Watson-Mechanic
10/07/2024	333,680 kms 12,101 hrs	adjust tarp R-15405 Adjusted tarp will work for the time being will need new tarp bows asap	Christopher Watson-Mechanic
10/07/2024	333,680 kms 111,767 hrs	coolant leak R-15295 Repaired	
10/07/2024	333,680 kms	check camera function R-15293 Fitted new wires and camera tested ok	Christopher Watson-Mechanic
10/07/2024	333,680 kms	dash lights R-15288 Already repaired	Christopher Watson-Mechanic
10/07/2024	333,680 kms	axle brakes R-15103 Checked over all ok	Christopher Watson-Mechanic

Date	Reading / Units	Type / Repairer Notes	Repairer
10/07/2024	333,680 kms	air conditioner compressor, axle shocks, dolly tyres, engine sump weep, tarp bows, windscreens bullseye R-15103 Already been repaired	Blair Wade, Simon Wade
01/07/2024	332,324 kms	A - 15/30 days S-12258 Inspected and diagnosed fault with reverse camera, parts ordered.	Christopher Watson-Mechanic
28/06/2024	330,631 kms 12,125 hrs	Amber beacon R-15483 Already repaired	Christopher Watson-Mechanic
24/06/2024		repair,strip and fit T-3099 strip & fit x 1 2 x Drive tyres, fittings & disposals	Eagle Truck Centre
20/06/2024	330,468 kms 12,101 hrs	numberplate flasher R-15404 Repaired broken wires to flasher light and reset flashing pattern to be the same as the rest	
20/06/2024	331,011 kms	King pin & bushes R-15426 Removed and replaced king pin sets on both steer axles and grease.	Christopher Watson-Mechanic
20/06/2024		check tyres R-15381 Tyres had already been replaced at time of inspection	
20/06/2024		Cruise control, engine brake,ABS fault R-15290 Checked at time of inspection all ok	
20/06/2024	330,493 kms 12,113 hrs	numberplate flasher R-15406 Repaired broken wires for flasher light and reset flasher mode to be the same as others	
04/06/2024		blown headlight R-15331 Replaced bulb	Jacob Rennex-Apprentice Mechanic
04/06/2024	329,786 kms	A - 15/30 days S-12169	Blair Wade
03/06/2024		air con compressor & brackets, drive shocks, Faulty Bonnet Blinker R-15197 Air conditioner system. Replaced faulty compressor, dryer and air con bracket. Replaced valves, pressure test, regas & test ABS faults-	Blair Wade
03/06/2024		camera R-15303	
03/06/2024		camera R-15304	
03/06/2024		belt squealing R-15277	
31/05/2024	329,758 kms	Fault codes R-15549 Short in wiring to engine brake switch repair short & replace fuse, clear all codes	Ace Air Auto Electrical
17/05/2024	327,512 kms	shock absorber, turbo R-15264 completed	Christopher Watson-Mechanic
10/05/2024		Front windscreen R-15433 supply & fit l/h & r/h front windscreens	
08/05/2024	327,018 kms	A - 15/30 days S-12069 Service completed Attached is repairs to be done	Blair Wade
15/04/2024		Airbag R-14867 centre bolt came out from airbag, replaced/repaired	Phillip Axisa

Date	Reading / Units	Type / Repairer Notes	Repairer
15/04/2024		Airbag R-14870 replaced 5th axle airbags	Phillip Axisa
12/04/2024	324,624 kms	Airbags R-14853 Install 2 x new axle 3 airbags	Blair Wade, Phillip Axisa
08/04/2024	324,313 kms	B - 30k S-11967 Service completed See attached repairs that need to be done	Blair Wade
08/04/2024	324,313 kms	A - 15/30 days S-11966 Service completed	Blair Wade
29/03/2024		air compressor R-14974 bracket repaired	
28/03/2024		seat not locking in R-14973 seat made to slide- no repair	
13/03/2024		air leak tyre R-14656 repair leak in n/s axle 2 tyre	Simon Wade (Mechanic)
11/03/2024		Lift axle airbags R-14635 completed by Blair	Blair Wade
08/03/2024	317,890 kms	A - 15/30 days S-11870 Service completed	Blair Wade
29/02/2024		leaks, Tyres, washer sprayers R-14413	Jacob Rennex-Apprentice Mechanic
29/02/2024		R-14413 Windscreen repaired Tyres changed wiper washer replaced	
15/02/2024		Registration O-3370	
12/02/2024	313,551 kms	A - 15/30 days S-11781 Service completed	Simon Wade (Mechanic)
05/02/2024		overtaking sign R-14357 Re rivet rear overtaking signs	Jacob Rennex-Apprentice Mechanic
05/02/2024		overtaking sign R-14358 Rerivet overtaking signs	Jacob Rennex-Apprentice Mechanic
01/02/2024		Parts O-3449 VCV Latch strap	
09/01/2024	308,416 kms	roof light R-14032 Install new middle clearance light complete Repair drivers weather shield straighten rear post	Simon Wade (Mechanic)
09/01/2024	308,416 kms	Welding aluminium R-14031 Install and weld bin floor Install plates and weld bin rock walls Weld and install tailgate internal foot plates	Simon Wade (Mechanic)
09/01/2024	308,416 kms	A - 15/30 days S-13922	Blair Wade, Simon Wade
03/01/2024		Amber beacon R-14105 Install new strobe light	Simon Wade (Mechanic)
25/12/2023		beacon R-14159 install new beacon	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
22/12/2023		axle shocks, diff leaking, lift axle, PTO Leaking, sump gasket leak, Valve R-14252 18/12/2023 Replaced both N/S & O/S 1st axle steer has had flat spot and gauges Replace outer 3rd tyre with runout as on indicators Replaced both rear overtaking signs	Jacob Rennex-Apprentice Mechanic, Simon Wade
18/12/2023	309,000 kms	C - 100k/ Annual S-11645 Annual service completed	Simon Wade (Mechanic)
18/12/2023	309,000 kms	A - 15/30 days S-11663 Service completed	Simon Wade (Mechanic)
15/12/2023	308,415 kms	Weld tailgate R-14008 Weld crack inside tailgate Weld 2 new inner tailgate steps	Simon Wade (Mechanic)
14/12/2023	308,415 kms	strobe light R-14007 Install new o/s/r strobe light	Simon Wade (Mechanic)
08/12/2023		Bullbar polishing R-14001 completed	Jacob Rennex-Apprentice Mechanic
22/11/2023	307,720 kms	starter motor R-14014 replace isolator and starter motor	Ace Air Auto Electrical
20/11/2023	307,890 kms	truck wont start R-13866 Checked fuses and relays Checked isolator Checked battery voltage Started truck	Blair Wade
10/11/2023		adjust fan belts R-13928 Adjust fanbelts	Simon Wade
03/11/2023	306,956 kms	A - 5k/ 21 days S-11521 Service completed R13528 for repairs	Simon Wade (Mechanic)
02/11/2023		Bumper bar damaged R-13782 Damage noted	
02/11/2023		Dash camera R-13768 Rob spoke to Phil who is organising to have this done today. Rob didnt ask Phil like he said, Simon will book in with C&A Mobile to rectify problem	
27/10/2023		Coolant leak R-13801 Phil repaired	Phillip Axisa
27/10/2023		Parts O-3245 sensor- oil pressure x 1	multispares
16/10/2023	304,353 kms	puncture repair T-2963 Call out fee x 1 hr Puncture repair Position 3	All Tyres Australia
09/10/2023	302,583 kms	A - 5k/ 21 days S-11427 service completed 1 x rear reflector replaced 1 x bonnet mirror replaced	Simon Wade (Mechanic)
06/10/2023		Bonnet mirror R-13598 Replaced screws for mirror	
06/10/2023		Cameras R-13227 Booked with C&A Mobile Completed	
06/10/2023		Warning Signs R-13458 Lights on dash repaired	
06/10/2023		Windshield R-13459 Ordered windshield	

Date	Reading / Units	Type / Repairer Notes	Repairer
25/09/2023		PTO oil leak, pyro sender unit, windscreen bulls eyes R-13528 11/9/2023 Pyro sender needed PTO Oil Leak 2 x windscreens bulls eyes 3/11/2023 air compressor eyes have snapped PTO still leaking tyres with flatspots	Blair Wade, Simon Wade
15/09/2023		Dash camera R-13516 Dash camera ,to be booked in	C&A Moblie
11/09/2023	297,953 kms	A - 5k/ 21 days S-11369 Service completed Has 2 x windscreen bulls eyes tightened axle 3 ubolts 2 x o/s steer hub caps 1 x o/s axle 5 hub cap	Simon Wade (Mechanic)
11/09/2023	297,953 kms	Coolant leak R-13414 Tightened & repaired all hose pipe mounts	
01/09/2023	295,868 kms	Batteries R-13404 Replace	Blair Wade
30/08/2023	295,348 kms	maintenance R-13364 Drilled tested spot to put it works fine Bolted together adjusted works great	Corey Lonergan
21/08/2023	292,709 kms	brake linings R-13308 Reline axle 4 N/S and O/S brakes and new drums Reline axle 5 N/S and O/S brakes and new drums Adjust brakes and check	Blair Wade, Simon Wade
18/08/2023	292,709 kms	B - 20k S-11332 B service completed 4 x relines done 1 ltr coolant top up 20 x wheel nut covers replaced Gearbox Leak-will monitor back steps leaking-will monitor	Simon Wade
14/08/2023		Under run protection R-13362 completed	sloanebuilt Trailers
14/08/2023		damaged Tailgate, reflective tape, safety stickers R-13475 Jacob did all repairs	Jacob Rennex-Apprentice Mechanic
11/08/2023	291,320 kms	Engine Lights R-13275 Checked lights on dashboard	Simon Wade
07/08/2023	290,599 kms	starting faults R-13233 Fault checked,found no problem	
02/08/2023	289,795 kms	A - 5k/ 21 days S-11269 Service completed	Blair Wade
31/07/2023	287,326 kms	Coolant leak, Oil leak R-13184	
31/07/2023	284,858 kms	Coolant leak R-13149	
31/07/2023		axle shocks, brake relines , PTO Weap R-13240 axle 4 & 5 relines done 17/7/2023	Simon Wade
17/07/2023	285,178 kms	A - 5k/ 21 days S-11198 A service completed Repair list attached	Simon Wade
30/06/2023	281,454 kms	Transmission Warning Light R-13113 Checked fault codes	
28/06/2023		Parts O-3043 horton air fitting	sloanebuilt Trailers
28/06/2023		Parts O-3038 water pump with oring 20litre coolant premix	multispares

Date	Reading / Units	Type / Repairer Notes	Repairer
22/06/2023		air con system R-13259 Completed	Ace Air Auto Electrical
22/06/2023	282,693 kms	A - 5k/ 21 days S-11152 A service Completed axle 4 & 5 Linings next service	Simon Wade
22/06/2023		air compressor R-13053 Organised replacement air compressor through Ace Air Installed New compressor waiting to be regassed by Ace Air	DLTL Haulage & Repairs
02/06/2023		Adjusted tarp, Tailgate, Transmission R-13038 Completed	A&C Heavy Repairs Pty Ltd
29/05/2023		Parts O-3000 hose	Volvo
23/05/2023		Parts O-2999 2 x Gasket PTO	Volvo
22/05/2023		puncture repair, tyres T-2849 2 x tyres,balance bead bags and 1 x disposal psoition 1,2 puncture repair pos 7	All Tyres Australia
20/05/2023		Parts O-2998 ubolts nuts bolts hoses & clamps	
05/05/2023	273,557 kms	gasket, weeping R-13019 Monitoring All Below Oil Cooler Sump 1st Drive diff,topped up oil Cooling housing gasket 90* elbow replaced Transmission	Sean (Mechanic)
05/05/2023	273,557 kms	Beacon, diff weeping, engine oil, reflector, roof lights R-12827 fix/replace 2 x roof clearance lights - Blair 24/3/2023 Monitoring diff weep	Sean (Mechanic)
05/05/2023	273,557 kms	A - 5k/ 21 days S-11007 Service completed Faults attached from service	Sean (Mechanic)
30/04/2023		Chip on windscreen, diff weeps, grain shute in, horton fan R-12925 Grain Shute in-done Monitoring chip in windscreen and diff weeping	Simon Wade
12/04/2023	269,937 kms	A - 5k/ 21 days S-10938 Service completed	Simon Wade
12/04/2023	269,937 kms	B - 20k S-10939 Service completed	Simon Wade
12/04/2023	269,937 kms	Mud guard poles R-12643 Completed by Sean	Sean (Mechanic)
31/03/2023	259,810 kms	New tyres, rotations, Valve Extension T-2801 4 x tyres & disposals positions 9,10,11,12 4 x tyre rotation 9,10,11,12 to 5,6,7,8 6 x valve extensions positions 6,7,10,11,14,15	All Tyres Australia
24/03/2023	267,715 kms	computer codes, Tarp cables R-12885 completed	Blair Wade
23/03/2023		runout tyre T-2809 1 x runout & disposal after hrs call out x 1 & call out fee	All Tyres Australia
10/03/2023	265,473 kms	A - 5k/ 21 days S-10837 service completed repair list attached	Sean (Mechanic)
22/02/2023		Tailgate R-12780 see attached	sloanebuilt Trailers

Date	Reading / Units	Type / Repairer Notes	Repairer
21/02/2023	263,086 kms	Reverse camera R-12753 completed	Simon Wade
17/02/2023		Registration O-2791	
10/02/2023	261,347 kms	Clearance Lights R-12734 repaired	Simon Wade
10/02/2023	261,347 kms	A - 15/30 days S-13921	Blair Wade, Simon Wade
27/01/2023	260,378 kms	A - 5k/ 21 days S-10653 Completed See attached Repair for Defects	Sean (Mechanic)
11/01/2023	254,394 kms	New tyres T-2779 4 x new tyres & disposals positions 13,14,15,16	All Tyres Australia
15/12/2022	252,321 kms	C - 100k/ Annual S-10566 Completed	Sean (Mechanic)
30/11/2022	251,800 kms	B - 20k S-10531 Completed	Sean (Mechanic)
30/11/2022	251,961 kms	A - 5k/ 21 days S-10561 Completed with B service	Sean (Mechanic)
26/10/2022	245,770 kms	tyres,strip & fit T-2714 New tyres position 1,2 strip & fit x 2 psotions 5,6 runout tyres position 7 3 x disposals	All Tyres Australia
21/10/2022		Parts O-2675 2 x batteries	Ace Air Auto Electrical
21/10/2022	246,617 kms	starter motor R-12509 completed	Ace Air Auto Electrical
17/10/2022	245,770 kms	A - 5k/ 21 days S-10416 Completed defect list attached	Simon Wade
07/10/2022		Defect Notice O-2682 Defect Clearance	pro axle
06/10/2022	244,629 kms	Diff R-12570 see attached	DLTL Haulage & Repairs
30/09/2022		Defect Notice O-2616 NHVR Defect Notice	
30/09/2022	242,728 kms	run out tyre T-2703 1 x runout tyre position 5 1 x disposal	All Tyres Australia
24/09/2022		fire extinguisher and bracket R-12474 completed	sloanebuilt Trailers
19/09/2022	242,399 kms	A - 5k/ 21 days S-10356 completed o/s windscreen pyro sender	Simon Wade
05/09/2022		Prestart fault R-12423 globe replaced	Simon Wade
22/08/2022	237,869 kms	Air Horn Switch, globe, Tyre R-12385 completed	Simon Wade

Date	Reading / Units	Type / Repairer Notes	Repairer
22/08/2022	237,869 kms	B - 20k S-10301 completed Tail gate bent 2 x windscreen bulls eyes	Simon Wade
22/08/2022	237,869 kms	A - 5k/ 21 days S-10300 completed	Simon Wade
05/08/2022	234,798 kms	A - 5k/ 21 days S-10287 completed	Jayden Haule
03/08/2022		Parts O-2622 grainlock crank	sloanbuilt trailers
12/07/2022	232,430 kms	aftertreatment codes, Intake leak R-12318 Completed	Cummins South Pacific Pty Ltd
25/06/2022	231,851 kms	See attached R-12267 completed	Simon Wade
24/06/2022		Parts O-2464 Level sensor	Volvo
21/06/2022		Fault codes R-12300 completed	Ace Air Auto Electrical
20/06/2022		Parts O-2463 tube cpr water outlet	Volvo
10/06/2022	231,281 kms	Limp Mode R-12266 completed	Volvo
18/05/2022	227,400 kms	Adjusted Lifting Axle R-12194 completed	Jayden Haule
16/05/2022	226,952 kms	Auto axle not dropping R-12193 Diff cooler had fallen onto the levelling valve and put a kink	Jayden Haule
13/05/2022	226,709 kms	A - 5k/ 21 days S-10077 completed Compressor Head Leaking- Warranty	Simon Wade
10/05/2022		Parts O-2455 2 x spotter clamp on mirrors	multispares
02/05/2022	224,386 kms	4 x runouts T-2627 4 x runouts & disposals	All Tyres Australia
26/04/2022	223,884 kms	fanbelt R-12115 completed	Corey Lonergan
07/04/2022	221,209 kms	UHF handpiece, UHF RADIO R-12114 completed	Simon Wade
04/04/2022		Defects R-12052	Simon Wade
04/04/2022	220,959 kms	B - 30k S-9969 completed	Simon Wade
30/03/2022	220,043 kms	New tyres T-2609 3 x tyres positions 3,4,12 3 x disposals	All Tyres Australia
29/03/2022	219,526 kms	A - 5k/ 21 days S-9956 Completed Defects also found at time of service	Simon Wade

Date	Reading / Units	Type / Repairer Notes	Repairer
29/03/2022	219,526 kms	Defects R-12051 completed	Simon Wade
28/03/2022	219,266 kms	NOX sensor R-12113 Completed	Simon Wade
25/03/2022		Engine codes R-12112 completed	A&C Heavy Repairs Pty Ltd
05/03/2022		Defects R-11997	Corey Lonergan
05/03/2022		A - 5k/ 21 days S-9891	Corey Lonergan
03/03/2022		Parts O-2368 see attached	Volvo
01/03/2022	214,324 kms	Tyre off bead R-11986 completed	Corey Lonergan
26/02/2022	213,921 kms	tarp dash switch R-11985 completed	Simon Wade
25/02/2022		Parts O-2369 Tarp switch	Volvo
16/02/2022		Registration O-2343	
14/02/2022		spotter mirror R-10919 replaced	A&C Heavy Repairs Pty Ltd
24/01/2022		A - 5k/ 21 days S-9120 A service	Corey Lonergan
13/01/2022		Maint. Repairs R-11922 Install new n/s headlight globe Install new o/s wiper blade	Simon Wade
17/12/2021		Maint. Repairs R-11880 See attached some still open,waiting on parts	Corey Lonergan
02/12/2021	201,233 kms	C - 100k/ Annual S-9176 done while on Fleet	Andrew Grindrod
01/12/2021		B - 30k S-9195 Manually generated 30000 km service	Andrew Grindrod, Simon Wade
29/11/2021		Maint. Repairs R-11832 Install 4 new axle 4&5 shocks Install new blinker globes	Blair Wade, Simon Wade
19/11/2021		Maint. Repairs R-11789 Repaired with Simon	Andrew Grindrod
19/11/2021		Maint. Repairs R-11776 Install and weld 2m x 1m alluminium plate to rear section of bin floor Make tailgate swing pin.	Simon Wade
10/11/2021		A - 5k/ 21 days S-9260 A service	
30/10/2021		Maint. Repairs R-11695 Prestart Defect - Reverse Camera,Dash Cam,Indicators, Hazard,	Deepinder Puar
20/10/2021		A - 5k/ 21 days S-9583	

Date	Reading / Units	Type / Repairer Notes	Repairer
		A service	
05/10/2021		A - 5k/ 21 days S-9610 Manually generated 5000 km service	
09/09/2021		Maint. Repairs R-11254 checked	David Thow
02/09/2021		Maint. Repairs R-11615 done	
24/08/2021		Maint. Repairs R-11456 done	Simon Wade
04/08/2021		Maint. Repairs R-11411 done	Simon Wade
29/07/2021		A - 5k/ 21 days S-9749 A service	Simon Wade
16/07/2021		A - 5k/ 21 days S-9763 A service	Andrew Grindrod
08/07/2021		A - 5k/ 21 days S-9307 A service	Simon Wade
19/06/2021		Maint. Repairs R-11368 done	
15/06/2021		Maint. Repairs R-11294 done	Simon Wade
15/06/2021		A - 5k/ 21 days S-9368 A service	Simon Wade
07/06/2021		Tyre Repair T-2467 done	Simon Wade
02/06/2021		Maint. Repairs R-11369 done	
01/06/2021		A - 5k/ 21 days S-9398 A service	Simon Wade
08/05/2021		Tyre Repair T-2452 done	Maya Scarcella
06/05/2021		B - 30k S-9447 B Service - Manually generated 30000 km service	Simon Wade
15/04/2021		A - 5k/ 21 days S-9493 A service	Simon Wade
23/03/2021		A - 5k/ 21 days S-9494 A service	Simon Wade
18/03/2021		Maint. Repairs R-11118 completed	
01/03/2021	138,490 kms	A - 15/30 days S-8119 completed rotated tyres and put new ones across front	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
01/03/2021		Maint. Repairs R-11054 Completed	
01/03/2021		lock up hub R-9719	James Hendry (Mechanic)
01/03/2021		A - 5k/ 21 days S-9553 A service	
19/02/2021		Registration O-2008	
08/02/2021		A - 5k/ 21 days S-9787 A service	
08/02/2021	134,306 kms	A - 15/30 days S-8065 completed Tyres very Soon	Simon Wade (Mechanic)
25/01/2021		A - 5k/ 21 days S-9849 A service	
25/01/2021	129,666 kms	bolts, Guard, tyre R-9580 also changed tyre	Simon Wade (Mechanic)
25/01/2021		Maint. Repairs R-10994 Completed	
25/01/2021	129,666 kms	A - 15/30 days S-7988 completed	Simon Wade (Mechanic)
12/01/2021		Misc O-1889 WCX3B truck & trailer audit checklist	
18/12/2020		run out tyre T-2293 completed	JK Vella Earthwerx Pty Ltd
14/12/2020		A - 15/30 days S-7917	Simon Wade (Mechanic)
10/12/2020		GPS Tracker R-9373 completed	Simon Wade (Mechanic)
04/12/2020		Parts O-1841 sealrings oring grommet seal	multispares
04/12/2020		Parts O-1842 seal	multispares
01/12/2020	124,000 kms	B - 40k S-7859 completed Front orange blinker globes faded	Simon Wade (Mechanic)
23/11/2020	122,381 kms	A - 15/30 days S-7836 completed	Simon Wade (Mechanic)
23/11/2020	122,381 kms	engine pyro sender R-9241	Simon Wade (Mechanic)
04/11/2020	118,284 kms	A - 15/30 days S-7755 completed Air filter needed	Simon Wade (Mechanic)
28/10/2020	116,471 kms	Tyres R-9078 completed	Simon Wade (Mechanic)
21/10/2020	114,218 kms	coolant fault on dash R-9212 completed	Volvo

Date	Reading / Units	Type / Repairer Notes	Repairer
15/10/2020	113,166 kms	A - 15/30 days S-7688 completed	Simon Wade (Mechanic)
23/09/2020	109,035 kms	Computer faults, Coolant sender unit R-8931 completed	Simon Wade (Mechanic)
23/09/2020	109,035 kms	A - 15/30 days S-7617 completed	Simon Wade (Mechanic)
04/09/2020		Parts O-1587 adblue cap	multispares
02/09/2020	104,254 kms	A - 15/30 days S-7548 completed Needs new airfilter	Simon Wade (Mechanic)
19/08/2020	102,447 kms	computer fault codes R-8738 completed	Simon Wade (Mechanic)
11/08/2020		Truckwash O-1484 10 wheeler wash	
10/08/2020	101,051 kms	A - 15/30 days S-7467 completed	Simon Wade (Mechanic)
27/07/2020	98,218 kms	pyro sender unit R-8616	Simon Wade (Mechanic)
27/07/2020	98,218 kms	A - 15/30 days S-7406 completed	Simon Wade (Mechanic)
22/07/2020		Truckwash O-1406 truck wash	
08/07/2020		Truckwash O-1355 S&S Fleet truck wash	
02/07/2020		airfilter, amber blinker globes R-8477	Simon Wade (Mechanic)
01/07/2020	94,725 kms	A - 15/30 days S-7341 completed	Simon Wade (Mechanic)
25/06/2020	93,792 kms	Tyres R-8448 completed	Simon Wade (Mechanic)
25/06/2020	93,792 kms	B - 40k S-7313 completed	Simon Wade (Mechanic)
24/06/2020		Truckwash O-1258 truck wash	
11/06/2020	89,206 kms	A - 15/30 days S-7275 completed	Simon Wade (Mechanic)
11/06/2020		strip & fit,runout T-2227 2 x strip & fit 1 x runout	Southwest Car & Truck Tyres
11/06/2020		Truckwash O-1208 S&S Fleet truck wash	
05/06/2020		tyre T-2229 cookes truck tyre centre 1 x tyre	

Date	Reading / Units	Type / Repairer Notes	Repairer
30/05/2020		front tyres low R-8233	
29/05/2020	85,461 kms	engine oil, revving R-8269 completed	Volvo
20/05/2020	82,526 kms	A - 15/30 days S-7201 completed	Simon Wade (Mechanic)
28/04/2020	78,624 kms	A - 15/30 days S-7142 com-pleted	Simon Wade (Mechanic)
24/04/2020		Truckwash O-1042 tipper truck wash	Narellan Truck Wash Services
16/04/2020	77,487 kms	repair,runout T-2196 call out fee x 2 runout x 1B disposal valve	JK Vella Earthwerx Pty Ltd
16/04/2020	72,741 kms	rotate tyres R-8053 completed	Simon Wade (Mechanic)
14/04/2020		Splits in floor sheet R-9217 completed	sloanebuilt Trailers
07/04/2020	76,582 kms	A - 15/30 days S-7071 completed	Simon Wade (Mechanic)
20/03/2020	71,226 kms	A - 15/30 days S-7010 completed	Simon Wade (Mechanic)
06/03/2020	68,352 kms	A - 15/30 days S-6949 completed	Simon Wade (Mechanic)
06/03/2020		reverse alarm R-7705	Simon Wade (Mechanic)
24/02/2020		truck tyre repair T-2151 1 x strip & fit tyre repair	Southwest Car & Truck Tyres
18/02/2020		Registration O-900	
06/02/2020	65,814 kms	A - 15/30 days S-6887 completed	Simon Wade (Mechanic)
05/02/2020		Misc O-798 cab air blower 37.80 1/4 tee 14.04	multispares
03/02/2020		Misc O-800 battery cover damaged by Rob Woolnough	Volvo
23/01/2020	54,330 kms	Batteries R-7434	Simon Wade (Mechanic)
15/01/2020	63,887 kms	A - 15/30 days S-6817 completed	Simon Wade (Mechanic)
21/12/2019	58,691 kms	vibration from front pulley area R-7447 completed	Volvo
19/12/2019	61,119 kms	A - 15/30 days S-6762 completed	Simon Wade (Mechanic)
12/12/2019		Misc O-808 full truck pressure check	Southwest Car & Truck Tyres

Date	Reading / Units	Type / Repairer Notes	Repairer
27/11/2019	57,242 kms	A - 15/30 days S-6689 completed	Simon Wade (Mechanic)
12/11/2019	54,188 kms	turn tyre on rim T-2084 1 x turn tyre on rim position 12	
11/11/2019	54,015 kms	A - 15/30 days S-6612 completed	Simon Wade (Mechanic)
18/10/2019	49,243 kms	A - 15/30 days S-6550 completed	Simon Wade (Mechanic)
14/10/2019		puncture repair T-2002 puncture repair repair position 1	Tyrreright
14/10/2019		turn tyre on rim T-2006 flip tyre on rim position 11	Tyrreright
02/10/2019	46,640 kms	B - 40k S-6502 completed	Simon Wade (Mechanic)
30/09/2019	44,970 kms	engine light on R-7149 completed	Volvo
26/09/2019	45,529 kms	A - 15/30 days S-6500 completed	Simon Wade (Mechanic)
20/09/2019		mud flap on drivers side R-6504	Simon Wade (Mechanic)
20/09/2019		drivers steer tyre flat & off rim R-6774	Simon Wade (Mechanic)
04/09/2019	40,458 kms	A - 15/30 days S-6433 completed	Simon Wade (Mechanic)
14/08/2019	36,258 kms	A - 15/30 days S-6363 completed	Simon Wade (Mechanic)
24/07/2019	32,043 kms	A - 15/30 days S-6293 completed	Simon Wade (Mechanic)
18/07/2019		puncture repair T-1905 puncture repair position 13	Tyrreright
12/07/2019		truck tyre repair T-1885 truck tyre repair	Southwest Car & Truck Tyres
03/07/2019	26,919 kms	A - 15/30 days S-6223 completed	Simon Wade (Mechanic)
13/06/2019	23,911 kms	A - 15/30 days S-6170 completed	Simon Wade (Mechanic)
24/05/2019	21,568 kms	A - 15/30 days S-6096 completed	Simon Wade (Mechanic)
06/05/2019	19,048 kms	puncture repair T-1787 puncture repair position 11	Tyrreright
29/04/2019	18,622 kms	A - 15/30 days S-6046 completed	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
02/04/2019	13,463 kms	A - 15/30 days S-5973 completed	Simon Wade (Mechanic)
19/03/2019	8,032 kms	A - 15/30 days S-5872 completed	Simon Wade (Mechanic)
18/02/2019	4,771 kms	A - 15/30 days S-5855 completed	Simon Wade (Mechanic)
23/01/2019		Cameras R-6270 com[pleted]	sloanebuilt Trailers
22/01/2019		anderson plug R-6246 completed	Ace Air Auto Electrical
08/01/2019		battery isolator switch R-6237	Ace Air Auto Electrical

Signed: _____

Name: _____

Date: _____