



Commercial Vehicle Inspection Report

Decal Number: GN87735
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21843257

Inspection Result:

PASS

FACILITY: SUMMIT TRAILER LTD. / S13050
INSPECTOR: Mosser, Alvin Leroy / 111705
WORK ORDER #: RA264000293

INSPECTION TYPE: Complete
INSPECTION CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSPECTION REASON: Semi-annual

INSPECTION START: 2026-Jul-10 11:09 AM PDT
INSPECTION COMPLETE: 2026-Jul-10 12:09 PM PDT

VEHICLE JURISDICTION: British Columbia
VEHICLE REGISTRATION #: RD5172

VEHICLE BODY STYLE: Truck Tractor
VEHICLE ODOMETER: 810526 KM
VEHICLE HUB ODOMETER:
VEHICLE BRAKE TYPE: Air
VEHICLE FUEL TYPE:

VIN: 3AKJHLD2MSMT7135
OWNER/LESSEE NAME: All can express LTD, DBA ace courier services
ADDRESS: 760 crowley ave, 760 crowley ave
Kelowna, British Columbia
V1Y7G7, Canada

VEHICLE LICENSED GVW(kg): 39500
VEHICLE YEAR: 2021
VEHICLE MAKE: FREIGHTLIN
VEHICLE MODEL:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	30	30	12			12	✓
2	Clamp	30	Automatic	38	38	8	8	5	10	
3	Clamp	30	Automatic	38	38	12	11	11	11	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	30	30	Lining (Shoe)	20	20	Drum			
2	50	50	Lining (Shoe)	18	18	Drum			
3	40	40	Lining (Shoe)	16	17	Drum			

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: Mosser, Alvin Leroy

Signature:

This Inspection Report was submitted to CVSE on 2026-Jul-10 12:10 PMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSED014

7/10/2026 12:10:48 PMPDT