

03935160

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATEManitoba Vehicle Standards and Inspect
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba 
A932003

Date Inspection Started DAY: 11 MO: 08 YR: 25	Station Number A B D 11 7	Station Name Lucky's Wash & Detailing	City Winnipeg
Date Inspection Completed DAY: 12 MO: 08 YR: 25	Mechanic Number M1 0220	Mechanic Signature Mike Baum	Station Phone Number 204-571-1531
Inspection Expiry Date DAY: 31 MO: 08 YR: 26	Vehicle Owner Double Diamond Farm Supply Company LTD		
	Address Box 776 Hwy #10 South Brissevain MB R0H0E0		
	City Winnipeg	Province MB	Postal Code R0H0E0
	Phone 204-571-1531		
☒ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number T A 4309	Prov. MB	NSC # N/A
	Odometer Reading N/A	Odom. Type km	mi
	Vehicle Identification Number 21AFA181A4615R101011412	Make Alfa Romeo	Model Maserati
	Year 1988	Unit # 5410B	
☒ Confirmed legible Vehicle Identification Number on vehicle			

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type X-14B-R5 Park brake apply spring broken																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>11</td><td>8</td><td>16.537</td><td>16.571</td><td>1 1/2</td><td>1 1/2</td></tr><tr><td>2</td><td>9</td><td>12</td><td>16.553</td><td>16.534</td><td>1 1/2</td><td>1 1/2</td></tr><tr><td>3</td><td colspan="2">16"</td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11	8	16.537	16.571	1 1/2	1 1/2	2	9	12	16.553	16.534	1 1/2	1 1/2	3	16"						4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	11	8	16.537	16.571	1 1/2	1 1/2																																																																		
2	9	12	16.553	16.534	1 1/2	1 1/2																																																																		
3	16"																																																																							
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any) X-1A-LHS & RHS marker lamp inoperative X-3A-Rear bumper reflective tape missing																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X	X	Section 9 - Tire & Wheel: Defects (if any) X-6A-R4 & R5 wheel bearing has excessive play																																																																						
		<table border="1"><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>15</td><td>13</td><td>13</td><td>17</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>2</td><td>16</td><td>17</td><td>20</td><td>20</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td colspan="2">32"</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	15	13	13	17	100	100	100	100	2	16	17	20	20	100	100	100	100	3	32"								4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	15	13	13	17	100	100	100	100																																																																
2	16	17	20	20	100	100	100	100																																																																
3	32"																																																																							
4																																																																								
5																																																																								
		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not