



Commercial Vehicle Inspection Report

Decal Number: GK59370
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21514467

D08-1 Inspection Result:
PASS

FACILITY: P & R TRUCK CENTRE LTD. / S20328
INSPECTOR: Renouf, Dwayne James / 203604
WORK ORDER #: 4257
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Annual
INSP. START: 2025-Sep-29 01:32 PM PDT
INSP. COMPLETE: 2025-Sep-29 02:32 PM PDT

VEHICLE JUR: British Columbia
PLATE #: VG1221
REGI: 13179612
UNIT/FLEET#: 006760
VIN: 5PVN8JV3C4S52113
OWNER/LESSEE NAME: OLD VICTORIA WATER COMPANY, OLD VICTORIA WATER COMPANY
LICENCED GVW(kg): 14500
VEHICLE YEAR: 2012
MAKE: HINO
MODEL:
BODY STYLE: Box Truck
ODOMETER: 348613 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
ADDRESS: 2200BKEATING CROSS RD
Saanichton, British Columbia
V8M2A6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPAIR COOLANT LEAK
Section 2 - Suspension	Repaired (same day) REPAIR REAR SUSPENSION
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACE MAXI ON #2 RIGHT
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) REPLACR DRAG LINK
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPAIR LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	32	32	8			10	✓
2	Clamp	30	Automatic	34	34	8	5	8	9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	90	75
2	60	60

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	17
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: Renouf, Dwayne James

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-29 02:32 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVF at the Commercial Vehicle Safety Enforcement

CVSE0014

9/29/2025 2:32:36 PM PDT