



# Commercial Vehicle Inspection Report

Decal Number: GJ80754  
Decal Expiry Date: 2026-Jul-31  
Inspection Number: 21437416

DOB-2 Inspection Result:  
**PASS**

FACILITY: BERK'S INTERTRUCK LTD. / S2211 INSP. TYPE: Complete INSP. START: 2025-Jul-24 07:52 AM PDT  
INSPECTOR: PURCHASE, ANDREW / 300290 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Jul-24 09:52 AM PDT  
WORK ORDER #: 6886 INSP. REASON: Annual

VEHICLE JUR: British Columbia REGI: 07499178 VIN: 2W9HA2838MG001093  
PLATE #: 10319B UNIT/FLEET#: TS5 OWNER/LESSEE NAME: TOP SHELF FEEDS INC., TOP SHELF FEEDS INC.  
LICENCED GWW(kg): 999999 BODY STYLE: Tank Trailer ADDRESS: 2800 ROBERTS RD, 2800 ROBERTS RD  
VEHICLE YEAR: 1992 ODOMETER: Duncan, British Columbia  
MAKE: WALINGA HUB ODOMETER: V9L6W3, Canada  
MODEL: HAT28 BRAKE TYPE: Air  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPAIRED MISC AIR LEAKS
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPAIRED MISC LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	31	31	7.1	6.4	8.7	7.9	
2	Clamp	30	Automatic	31	31	11.1	9.5	12.7	12.7	
3	Clamp	30	Automatic	31	31	6.4	7.1	4.8	4.8	

Comment:

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	55	75	Lining (Shoe)	15	14	Drum		
2	65	20	Lining (Shoe)	17	20	Drum		
3	20	20	Lining (Shoe)	20	20	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. WHEELS NOT PULLED

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: PURCHASE, ANDREW

Road Test Date:  
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jul-24 02:52 PMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

CVSE014

7/24/2025 2:52:41 PM PDT