



Commercial Vehicle Inspection Report

Decal Number: GK55739
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21475403

DOB: 3
Inspection Result: **PASS**

FACILITY: BAYSIDE MACHINE SERVICES / S6760
INSPECTOR: Gorle, Brian James / 203504
WORK ORDER #: 15462
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2025-Aug-28 06:00 AM PDT
INSP. COMPLETE: 2025-Aug-29 11:54 AM PDT

VEHICLE JUR: British Columbia
PLATE #: PD4600
REGI: 10887752
UNIT/FLEET#: 14
VIN: 1M1AW07YXDM035593
OWNED/LESSEE NAME: Top Shelf Feeds Inc., Top Shelf Feeds Inc.
PERMITTED GVW(kg): 63500
VEHICLE YEAR: 2013
MAKE: MACK
MODEL:
BODY STYLE: Truck Tractor
ADDRESS: 2800 Roberts Rd., 2800 Roberts Rd. Duncan, British Columbia
ODOMETER: 705021 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VEHICLE YEAR: 2013
VEHICLE MAKE: MACK
VEHICLE MODEL:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) Rear shock lower bolts replaced
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed Customer Advised Axel # 3 right tires need replacing soon
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	29	31
2	Clamp	30L	Automatic	33	34
3	Clamp	30L	Automatic	34	34

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
6.31			7.48	✓
12.42	7.98	12.66	10.28	
5.28	5.53	3.67	3	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	29	88
2	71	89
3	56	64

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	15
Lining (Shoe)	14	13
Lining (Shoe)	17	17

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Gorle, Brian James

Road Test Date:
Signature: _____

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-29 11:55 AMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE014

8/29/2025 11:55:58 AMPDT

