SERVICE & REPAIR RECORDS

Plant / Equipment Service & Repair Records			
Make:	VOLVO	**Type:**	30T EXCAVATOR
Model:	EC300DL	**Terreco Plant ID:**	TR2016
Rego / Serial #:		**Year of Manufacture:**	2019

Date of Service / Repaired	Km / Hours	Service Type	Repairs Conducted	Comments
23.05.24			Replace Final Dve Sprocket	
13.06.24	5872	SVCE	General Svce	Next Svce 6372
13.07.24		Maint	Belt & Tensioner	WO 1694
13.07.24		Maint	Replaced Dve Belt & A/Con Belt	WO 1694
23.08.24		Maint	Measure Up,Design & Draw Undercarriage Cleaning Plate – Start to fabricate	WO 177
26.08.24		Maint	Fab up Plate	WO 177
27.08.24		Maint	Test Fit & Trial	WO 177
02.09.24		Maint	Diagnose on-going fault – upgraded water pump to be fitted as per CJD Prod Support	WO 181
05.09.24		Repair	Replaced Water Pump Tensioner Dvce Belt & A/C Belt	WO 181
12.09.24		Repair	Pins for Terreco	WO 177
22.10.24		Repair	Repair Floors of skip bin	WO
03.04.2025	6827	Service	Service as per list	Wo 384 Next service due 7327
22.12.2025	8011	Service	Final drives oil is black, o-ring on hammer line on control valve needs replacing, sprockets worn	Next service due: 8500 hrs
15.05.2026	8592	Service	Service as per list Tracks will need work	Next service due 9000hr
29.0702026	9054	Service	1000hr service done & replace cooler hose	Next service due 9500hr

SERVICE & REPAIR RECORDS

Date of Service / Repaired	Km / Hours	Service Type	Repairs Conducted	Comments
26.10.2026	9608	Service	500hrs service done replace fan belt next service	Next service due 10000hr