SERVICE & REPAIR RECORDS

Plant / Equipment Service & Repair Records			
Make:	Hino	**Type:**	Water Cart
Model:	FM1J	**Terreco Plant ID:**	TR1004
Rego / Serial #:	JHDFM1JLLXXX10037	**Year of Manufacture:**	

Date of Service / Repaired	Km / Hours	Service Type	Repairs Conducted	Comments
01/08/2025		Service & air tank	Carry out service due to time & replace tank valve	Service done on time not kms
18/09/2025		Hyd oil leak	Replace PTO hose	
13/10/2025		Check on air leaks	Replace control valve on tank	
18/02/2026		Check on non-start	Found battery cables loose tightened up & topped up hyd oil	
04/07/2026		Check on loss of drive	Clutch replaced worn out carried out annual service	
19/10/2026		Water pipes bad leaks	Carried out repair to rear tank pipes	