



Commercial Vehicle Inspection Report

Decal Number:
Decal Expiry Date:
Inspection Number:

21903064

Inspection Result:

FAIL

FACILITY: OCEAN TRAILER / S6173
INSPECTOR: Mihajlovic, Dejan / 202707
WORK ORDER #: WO129536
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2026-Sep-01 03:00 AM PDT
INSP. COMPLETE: 2026-Sep-01 04:00 AM PDT

VEHICLE JUR: Alberta
PLATE #:
REGI:
UNIT/FLEET#: 35925
VIN: 1UYVS25377G023521
OWNER/LESSEE NAME: C KEAY INVESTMENT LTD OCEAN TRAILER, C KEAY OCEAN TRAILER
ADDRESS: 234136 84 ST SE, 234136 84 ST SE
ROCKY VIEW, Alberta
T1X0K2, Canada
LICENCED GWV(kg): 0
VEHICLE YEAR: 2007
MAKE: UTILITY
MODEL: HEATER
BODY STYLE:
ODOMETER:
HUB ODOMETER: 92759 KM
BRAKE TYPE: Air
FUEL TYPE: Not Applicable

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Failed BRAKES LOW LEFT REAR,RIGHT FRONT,,
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Failed LIGHTS NOT WORKING LEFT REAR,LEFT CENTER,RIGHT FRONT TOP,,
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Failed BOTH LEGS STUCKS NOY GOING UP-DOWN,,
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Failed KING PIN WORN OUT,,
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	31.8	31.8
2	Clamp	30	Automatic	31.8	31.8

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
3.2	4	4.8	4.8	
4.8	4.8	4.8	4.8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	62	113
2	116	98

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15.9	7.9
Lining (Shoe)	7.9	11.1

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: Mihajlovic, Dejan

Signature:

This Inspection Report was submitted to CVSE on 2026-Sep-01 08:24 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE0014

9/1/2026 8:24:07 AM PDT