D12-1

BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GP06752
Decal Expiry Date: 2027-Jul-31
Inspection Number: 21852579 2026282

Inspection Result: **PASS**

FACILITY:	SPEED TRUCK & TRAILER REPAIR (ABBY) LTD. / S20520	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Jul-18 09:00 AM PDT
INSPECTOR:	DHALIWAL, HARPINDER SINGH / 300434	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Jul-18 11:00 AM PDT
WORK ORDER #:		**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REGI:**	06751153	**VIN:**	3FRPF75CX8V681315
PLATE #:	WH8904	**UNIT/FLEET#:**		**OWNER/LESSEE NAME:**	COMMERCE COURT EQUIPMENT, CO.
LICENCED GVW(kg):	23000	**BODY STYLE:**	Winch Truck	**ADDRESS:**	450 NANAIMO STREET
VEHICLE YEAR:	2008	**ODOMETER:**	337035 KM		Vancouver, British Columbia
MAKE:	FORD	**HUB ODOMETER:**			V5L 4W3, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	**Repaired (same day)**	REPLACED TIE ROD END.
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Repaired (same day)**	REPAIRED A BATTERY BOX.
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Disc	N/A	Not Applicable	0	0
2	Disc	N/A	Not Applicable	0	0

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13			13	✔
12	12	13	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	0	0

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	13	13
Pad	14	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: DHALIWAL, HARPINDER SINGH **Signature:** HS

This Inspection Report was submitted to CVSE on 2026-Jul-18 04:31 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSED014
7/18/2026 4:31:59 PM PDT