

2009 CHEVROLET SILVERADO C1500

Pickup | 8 Cylinders | Flexible 1GCEC19069Z171544

Country of Assembly: United States Last Reported Odometer: 333,685 KM



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



37 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 08, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2010 Jul 20	39,577 KM	Silver Service Auto Repair	Vehicle serviced
		North York, Ontario, Canada	Brakes checked
			Rear brakes serviced/adjusted
2011 Feb 25	54,805 KM	Silver Service Auto Repair	Vehicle serviced
		North York, Ontario, Canada	Air filter replaced
			Drain plug gasket replaced
			Oil and filter changed
			Windshield washer checked
2011 May 22	59,850 KM	Silver Service Auto Repair	Vehicle serviced
,	,	North York, Ontario, Canada	Drain plug gasket replaced
		North Tork, Ortano, Canada	Oil and filter changed
2011 Nov 29	75,102 KM	Silver Service Auto Repair	Vehicle serviced
		North York, Ontario, Canada	
2012 Inn 20		Cilver Camina Avita Danair	Vehicle serviced
2012 Jan 30		Silver Service Auto Repair	
		North York, Ontario, Canada	Brakes checked
			 Brake shoes replaced Brake wheel cylinder(s) replaced
			Front brakes serviced
			Front wheel bearing(s)/hub(s) replaced
			Emissions inspection performed
			Safety inspection performed
2012 Feb 23	81,993 KM	Silver Service Auto Repair	Vehicle serviced
	,	North York, Ontario, Canada	
2013 Jun 28	117,263 KM	Silver Service Auto Repair	Vehicle serviced
-		North York, Ontario, Canada	Air filter replaced
			Brakes checked
			Brake fluid flushed/changed
			Brake system bled
			Drain plug gasket replaced
			Front brake pads replaced
			 Rear brakes serviced/adjusted
			Tire repaired
2014 Feb 8	141,294 KM	Silver Service Auto Repair	Vehicle serviced
		North York, Ontario, Canada	Battery/charging system checked
		•	Battery replaced

Drain plug gasket replaced Oil and filter changed Windshield washer checked 1GCEC19069Z171544

	ODOMETER	SOURCE	DETAILS	
			Wiper(s) replaced	
2014 Jul 16	154,569 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced Exhaust repaired Fluids checked Transmission fluid changed	
2015 Sep 25	190,801 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced	
2015 Dec 2	195,450 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance inspection completed	
2016 Jun 13	213,856 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Front brake pads replaced	
2016 Oct 12	220,911 KM	Quality Automotive Services North York, Ontario, Canada	Vehicle serviced • Emissions inspection performed	
2016 Oct 30		Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced • Emissions inspection performed	
2016 Dec 20	224,083 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance reminder reset • Oil and filter changed	
2017 Mar 13	229,190 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Brake fluid flushed/changed • Front brake pads replaced • Maintenance reminder reset	
2018 Feb 22	253,631 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance reminder reset • Oil and filter changed	
2018 Apr 30	258,171 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance reminder reset • Oil and filter changed	
2018 Aug 1	264,286 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance reminder reset • Oil and filter changed	
2018 Oct 10	270,257 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced	
2018 Oct 21	270,331 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced	
2018 Nov 2		Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance reminder reset • Oil and filter changed	
2018 Nov 30	273,138 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced Exhaust manifold gasket replaced Exhaust manifold replaced Oil and filter changed Oil cooler seal(s) replaced Oil pan gasket replaced Spark plug wires replaced Spark plug(s) replaced Tire(s) mounted Tire(s) replaced	

	ODOMETER	SOURCE	DETAILS
			Wiring repaired
2019 Mar 26	278,511 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Oil and filter changed
2019 Apr 30	283,990 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle servicedMaintenance reminder resetOil and filter changed
2019 Jun 12	288,958 KM	Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed
2019 Jul 25	291,183 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced Brakes checked Front brake caliper(s) replaced Front brake pads replaced Front brake rotor(s) replaced Lower ball joint(s) replaced
2019 Dec 4	300,405 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced Battery/charging system checked Brake light switch replaced Drain plug gasket replaced Oil and filter changed Windshield washer checked
2020 Feb 14	304,438 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced Antifreeze/coolant flushed/changed Drain plug gasket replaced Drive belt idler pulley replaced Drive belt tensioner pulley replaced Drive belt(s) replaced Drive belts checked Idler pulley replaced Oil and filter changed Serpentine belt replaced Serpentine tensioner replaced Water pump gasket replaced Water pump replaced
2020 Feb 20		Kal Tire Etobicoke, Ontario, Canada	Vehicle serviced • Maintenance reminder reset • Oil and filter changed
2020 Mar 13	305,808 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced ABS system checked Front wheel bearing(s)/hub(s) replaced
2020 Aug 5		Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced
2020 Oct 14	318,663 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced • Drain plug gasket replaced • Oil and filter changed
2021 Jan 12	323,893 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced
2021 Mar 12	326,940 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced Drain plug gasket replaced Fuel injection system flushed/serviced Oil and filter changed
2021 Jun 22	333,446 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced Drain plug gasket replaced Fuel injection system flushed/serviced Oil and filter changed

1GCEC19069Z171544

	ODOMETER	SOURCE	DETAILS
2021 Jul 2	333,685 KM	Silver Service Auto Repair North York, Ontario, Canada	Vehicle serviced Airbag system checked Airbag sensor replaced Engine/powertrain computer/module checked Intake manifold gasket(s) replaced Oil pressure sender/switch replaced Throttle body cleaned/serviced Transmission filter replaced Transmission fluid changed Transmission serviced



(1) Open Recalls

Recall #: N090270 | SDM RETAINING MOISTURE Recall Date: 2009 Oct 19

Recall Description

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2007-2009 model year Chevrolet Silverado and GMC Sierra vehicles. Some of these vehicles may have a condition where the sensing and diagnostic module (SDM), located beneath the driver's seat, may corrode due to a significant quantity of snow and/or water containing road salt or other contaminants entering the vehicle and saturating the acoustical padding beneath the carpet. The SDM is located under the driver's seat underneath the acoustical padding.

Remedy

Dealers are to remove the acoustical pad above the SDM, inspect the SDM, and replace the SDM, if necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit **GM's website**. (https://my.gm.ca/gm/en/recalls)

Recall #: N212328790 | Front Passenger Airbag Takata Inflator - Priority Group 9 Recall Date: 2021 Feb 05

Recall Description

TK Holdings Inc. ("Takata") has decided that a defect which relates to motor vehicle safety exists in the passenger-side frontal airbag inflators installed as original equipment in certain 2007 to 2014 model year Cadillac Escalade, Escalade ESV, and Escalade EXT vehicles; certain Chevrolet Avalanche, Silverado 1500, Silverado 2500/3500, Suburban, and Tahoe vehicles; and certain GMC Sierra 1500, Sierra 2500/3500, Yukon, and Yukon XL vehicles. The determination was made that the propellant in these inflators may degrade after long-term exposure to high humidity and temperature cycling, which could cause the inflator to rupture during a deployment.

Remedy

Dealers will replace the passenger-side frontal airbag inflator.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit **GM's website**. (https://my.gm.ca/gm/en/recalls)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2009 Jan 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as black
2009 Oct 19		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N090270
2009 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2010 Feb 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2010 Jul 20	39,577 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2010 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2011 Feb 25	54,805 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2011 May 22	59,850 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2011 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2011 Nov 29	75,102 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2012 Jan 30		Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2012 Feb 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2012 Feb 23	81,993 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2012 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2013 Jun 28	117,263 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2013 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2014 Feb 8	141,294 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2014 Jul 16	154,569 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2014 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2015 Sep 25	190,801 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
		Etobicoke, Ontario, Canada		

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2015 Dec 2	195,450 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2016 Jun 13	213,856 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2016 Oct 12	220,911 KM	Quality Automotive Services North York, Ontario, Canada	Service Record	Vehicle serviced
2016 Oct 30		Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2016 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2016 Dec 20	224,083 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2017 Mar 13	229,190 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2018 Feb 22	253,631 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 30	258,171 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2018 Aug 1	264,286 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2018 Oct 10	270,257 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2018 Oct 21	270,331 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2018 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2018 Nov 2		Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2018 Nov 30	273,138 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 26	278,511 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2019 Apr 30	283,990 KM	Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 12	288,958 KM	Kal Tire	Service Record	Vehicle serviced

1GCEC19069Z171544

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jul 25	291,183 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2019 Dec 4	300,405 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 14	304,438 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 20		Kal Tire Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2020 Mar 13	305,808 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Aug 5		Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 14	318,663 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2021 Jan 12	323,893 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2021 Feb 5		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N212328790
2021 Mar 12	326,940 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 22	333,446 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2021 Jul 2	333,685 KM	Silver Service Auto Repair North York, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2022 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2023 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2024 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, decidarations, accident information, service records, recall information, dodmeter readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablel quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use

© 2025 CARFAX Canada ULC. All rights reserved.

