

This live tracking will be terminated at: 05 Dec 2027 23:59

+
-



i

Location: CHRISTIES RD, RAVENHALL

Serial#: KMT0D127VHA090800

Hour/Odometer: 9303

Next Service: 9500

Maintenance History

Type	Date	Comments
EXTERNAL REPAIR	5/06/2026	add blue and dpf faults
PARTS	11/05/2026	Ventilator
PARTS	6/05/2026	Lock and Element assy
PARTS	27/04/2026	Cutting edge hardware
REPAIRS	23/04/2026	1x Battery
REPAIRS	22/04/2026	Replace ad blue pump and injector
PARTS	20/04/2026	Service Kit
PARTS	30/03/2026	plates
PARTS	17/03/2026	Filters and Orings
PARTS	17/03/2026	Hydraulic oil 46
PARTS	10/03/2026	Exhaust parts

PARTS	10/03/2026	Coolant flush
EXTERNAL REPAIR	27/02/2026	
EXTERNAL REPAIR	19/02/2026	Multiple electrical faults and solenoid replaced
REPAIRS	16/02/2026	DOZER DIAGNOSTICS " WORK EQUIPMENT FAULT
SERVICE	2/02/2026	500hr service
REPAIRS	30/01/2026	Cartridge + Filter + Oil Ring
REPAIRS	9/12/2025	Repair blown hose.
REPAIRS	9/12/2025	Auto greaser replacement
REPAIRS	11/11/2025	Hydraulic fittings / hose fittings.
REPAIRS	5/11/2025	Cutting edge / nuts and bolts.
SERVICE	27/10/2025	2000hr SVC
EXTERNAL REPAIR	15/08/2025	Inspect & Repair SCR Faults
REPAIRS	11/08/2025	Blade Arm & Trunnion Repairs *Outage*
REPAIRS	17/07/2025	Flat Batteries
REPAIRS	17/07/2025	Repl Blade Cylinder Sensor
REPAIRS	5/06/2025	Bolts
REPAIRS	27/05/2025	GREASE LINES / NIPPLES
REPAIRS	22/05/2025	GREASE LINE FIXES
REPAIRS	6/05/2025	BUSHES AND PINS FOR ARMS
REPAIRS	6/05/2025	LIGHTS & BRACKET
REPAIRS	22/04/2025	Seat broken
REPAIRS	10/04/2025	SERVICE KIT
REPAIRS	4/04/2025	MULTIPLE REPAIRS, REPLACED SOLENOID / CLEARED ENGINE CODE.
EXTERNAL REPAIR	17/03/2025	LO3 DASH CODE REPAIRS.
EXTERNAL REPAIR	11/12/2024	Engine overheat
EXTERNAL REPAIR	9/12/2024	Service 7000hr
EXTERNAL REPAIR	20/11/2024	Aircon not working
SERVICE	19/09/2024	500hr service
RECORD 360	19/07/2024	Record 360
DAMAGES	18/07/2024	Grease line broken left side of blade see photo
REPAIRS	24/05/2024	Undercarriage rebuild
SERVICE	20/05/2024	6000hr service
REPAIRS	17/04/2024	L/H chain snapped
REPAIRS	1/03/2024	Belly plate damage
REPAIRS	29/02/2024	Coolant leak
REPAIRS	5/02/2024	G.E.T / cutting edges need replacing

RECORD 360	15/01/2024	Record 360
SERVICE	15/01/2024	500 hr service
EXTERNAL REPAIR	16/11/2023	GPS down, rub through cable
RECORD 360	15/11/2023	Record 360
REPAIRS	17/10/2023	Oil leak from behind front grill getting worse. Broken grease line on bank behind blade.
EXTERNAL REPAIR	19/09/2023	GPS not connecting
SERVICE	15/09/2023	5000hr service
REPAIRS	5/09/2023	Leaking fluids Right side track roller wear and tear
PARTS	18/08/2023	Keys for Komatsu machines
PARTS	9/08/2023	Cutting edge stock
OTHER	18/07/2023	GPS Monitor from Komatsu to be billed out to Lantrak Projects
REPAIRS	16/06/2023	Flip cutting edges, replace end tips- parts ordered komatsu pakenham 16/06/2023
EXTERNAL SERVICE	24/05/2023	500 hr service komatsu??
EXTERNAL REPAIR	24/05/2023	Carrier roller U/S needs changing
REPAIRS	10/03/2023	Seat belt requires Attention
EXTERNAL SERVICE	7/03/2023	4,000hr service Komatsu booked for 7/3/23 O/N 2824
EXTERNAL REPAIR	15/02/2023	S/Fit cutting edges and hardware
SERVICE	18/10/2022	3,500 hr service
OTHER	10/08/2022	risk assessment