



2016 Freightliner 108SD

Test Information

Engine	Cummins ISL (8.9)
Engine Serial	CMMNS*6L u13D0890000000*73923880
VIN	1FVHG5CY7GHHM1584
Driveline	Class 8 6x4
Body	Truck
Test Time	Sept. 4, 2026, 9:57 a.m.
File Length	40.405 s

Usage

Label	Value	Units
Engine Odometer	166,416	mi
Odometer (Instrument Cluster #1)	166,468	mi
Engine Total Hours of Operation	13,059.7	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	19	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Doser Valve 1	Current Below Normal	3
Previous	Engine #1	Engine Crankcase Pressure 1	High-least severe	57
Previous	Brakes - System Controller	Wheel Sensor ABS Axle 1 Right	Voltage Below Normal	1
Previous	Body Controller	Engine Cylinder 6 Exclude from Combustion Request	Voltage Below Normal	113
Previous	Body Controller	Over Pressure Percentage Threshold	Current Below Normal	1
Previous	Body Controller	Tire Pressure (Extended Range)	Current Below Normal	3
Previous	Body Controller	SCR System Cleaning Status	Data Error	5
Previous	Body Controller	SCR System Cleaning Inhibited Status	Data Error	2
Previous	Body Controller	SCR System Cleaning Inhibited Due to Inhibit Switch	Not Responding Properly	126
Previous	Body Controller	Tire Wireless Signal Strength Indicator	Data Error	3
Previous	Body Controller	Engine Cylinder 1 Exclude from Combustion Request	Data Error	3
Previous	Body Controller	SCR System Cleaning Inhibited Due to Out of Neutral	Not Responding Properly	5
Previous	Body Controller	Tire Location	Data Error	3
Previous	Body Controller	Over Temperature Setting	Data Error	3
Previous	Body Controller	Over Pressure Percentage Threshold Setting	Data Error	3
Previous	Body Controller	Cold Inflation Pressure Setting	Data Error	3
Previous	Body Controller	Tire Location	Data Error	3
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Erratic, Intermittent, or Incorrect	3
Emissions Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Doser Valve 1	Current Below Normal	3