

 RITCHIE BROS. Diagnostic Report
Auctioneers[®]**2018 International LT****Test Information**

Engine	Cummins X15 Signature (15.0)
Engine Serial	CMMNS*6X1u17D1500000000*79990811*8029
VIN	3HCDZAPR9JL741059
Driveline	Class 8 6x4
Body	Truck-Tractor MDHD: Conventional
Test Time	Sept. 9, 2025, 9:31 a.m.
File Length	42.192 s

Usage

Label	Value	Units
Engine Odometer	350,824	mi
Odometer (Instrument Cluster #1)	351,048	mi
Engine Total Hours of Operation	12,954.65	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	71	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Body Controller	Manufacturer Assignable SPN	Out of Calibration	1
Active	Body Controller	Manufacturer Assignable SPN	Out of Calibration	1
Previous	Engine #1	Sensor supply voltage 3	Voltage Below Normal	1
Previous	Transmission #1	Key Switch Battery Potential	Erratic, Intermittent, or Incorrect	1
Previous	Shift Console - Primary	Source Address 33	Abnormal Update Rate	6
Previous	Shift Console - Primary	Source Address 0	Abnormal Update Rate	4
Previous	Shift Console - Primary	Transmission Requested Gear	Out of Calibration	1
Previous	Body Controller	Manufacturer Assignable SPN	Special Instruction	126
Previous	Body Controller	Manufacturer Assignable SPN	Special Instruction	9
Previous	Body Controller	Brake Switch	Not Responding Properly	1
Previous	Body Controller	Disengage Differential Lock Request - Rear Axle 1	Erratic, Intermittent, or Incorrect	3
Previous	Body Controller	Manufacturer Assignable SPN	Current Below Normal	50
Previous	Lighting - Operator Controls	Source Address 33	Abnormal Update Rate	126
Previous	Proprietary	Source Address 33	Abnormal Update Rate	126
Previous	Proprietary	Source Address 33	Abnormal Update Rate	126
Emissions Previous	Engine #1	Sensor supply voltage 3	Voltage Below Normal	1