

Facility:	OCEAN TRAILER / S6173	INSP. TYPE:	Complete	INSP. START:	2024-Sep-10 06:00 AM PDT
Inspector:	Fisher, James Russell / 112930	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2024-Sep-10 07:00 AM PDT
Work Order #:	W026208	INSP. REASON:	Annual		
Vehicle Jur:	Alberta	REGI:		VIN:	2LDCC4028YT033846
Plate #:	Z35643	UNIT/FLEET#:	28824	OWNER/LESSEE NAME:	C KEAY INVESTMENTS, OCEAN TRAILER
Permitted GVW(kg):	0	BODY STYLE:	Semi Trailer	ADDRESS:	234136 84 ST SE, 234136 84 ST SE
Vehicle Year:	2000	ODOMETER:			ROCKY VIEW, Alberta
Make:	LODE KING	HUB ODOMETER:	71902 Miles		T1X0K2, Canada
Model:	CHASSIS	BRAKE TYPE:	Air		
		FUEL TYPE:	Not Applicable		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	32	32	8.7	8.7	8.7	7.9	
2	Clamp	30	Automatic	32	32	7.9	4.8	8.7	8.7	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	65	Lining (Shoe)	14	14	Drum		
2	60	75	Lining (Shoe)	13	14	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No      Road Test Date:      Road Tester:

Inspector: Fisher, James Russell      Signature: 

This Inspection Report was submitted to CVSE on 2024-Sep-10 09:03 AM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.