



Vehicle History Report # 71088839
Report Date: July 7, 2026 | 2:26 p.m. EDT
Report Status: Complete
Reference: 2026196.H22-4

2019 INTERNATIONAL LT625

Tractor truck | 6 Cylinders | Diesel
3HCDZTZR6KL473114
Country of Assembly: Mexico
Last Reported Odometer: 548,472 KM



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



8 Service Records Found



No U.S. History Found



Unable to check for recall information



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 07, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Jan 10		Krown Kitchener Kitchener, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2019 Nov 15	121,821 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Vehicle serviced - ABS system checked - Airbag system checked - Brakes checked - Cooling system hoses checked - Electrical system checked - Engine checked - Exhaust system checked - Fuel system checked - Glass checked - Emissions or safety inspection performed - Lights checked - Mirror(s) checked - Steering/suspension checked - Tire condition and pressure checked - Tire(s) mounted - Wheel bearings checked - Wipers/washers checked
2020 Nov 9	267,288 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Vehicle serviced - ABS system checked - Airbag system checked - Brakes checked - Cooling system hoses checked - Electrical system checked - Engine checked - Exhaust system checked - Fuel system checked - Glass checked - Emissions or safety inspection performed - Lights checked - Mirror(s) checked - Steering/suspension checked - Tire condition and pressure checked

ODOMETER		SOURCE	DETAILS
			• Tire(s) mounted • Wheel bearings checked • Wipers/washers checked
2021 Nov 12	365,424 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Vehicle serviced • ABS system checked • Airbag system checked • Brakes checked • Cooling system hoses checked • Electrical system checked • Engine checked • Exhaust system checked • Fuel system checked • Glass checked • Emissions or safety inspection performed • Lights checked • Mirror(s) checked • Steering/suspension checked • Tire condition and pressure checked • Tire(s) mounted • Wheel bearings checked • Wipers/washers checked
2022 Nov 3	441,374 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Vehicle serviced • ABS system checked • Brakes checked • Electrical system checked • Engine checked • Exhaust system checked • Fuel system checked • Glass checked • Emissions or safety inspection performed • Lights checked • Mirror(s) checked • Steering/suspension checked • Tire condition and pressure checked • Tire(s) mounted • Wheel bearings checked • Wipers/washers checked
2023 Nov 14	515,013 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Vehicle serviced • ABS system checked • Brakes checked • Electrical system checked • Engine checked • Exhaust system checked • Fuel system checked • Glass checked • Emissions or safety inspection performed • Lights checked • Mirror(s) checked • Steering/suspension checked • Tire condition and pressure checked • Tire(s) mounted • Wheel bearings checked • Wipers/washers checked
2024 May 21	548,472 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Vehicle serviced • ABS system checked • Brakes checked • Electrical system checked • Engine checked • Exhaust system checked • Fuel system checked • Glass checked • Emissions inspection performed • Lights checked • Mirror(s) checked • Steering/suspension checked • Tire condition and pressure checked • Wheel bearings checked

ODOMETER	SOURCE	DETAILS
		Wipers/washers checked
2024 May 22	KROWN VAUDREUIL Vaudreuil-Dorion, Québec, Canada	Vehicle serviced Undercoating/rustproofing applied



Open Recalls



We are unable to check for recall information on this vehicle. Please visit [www.saarc.ca](#) for the most current recall information on this, or any, INTERNATIONAL vehicle.



Stolen Vehicle Check



This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Dec 20		Motor Vehicle Dept. Ontario, Canada	Registration Records	Registered/Renewed
2019 Jan 10		Krown Kitchener Kitchener, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 15	121,821 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 9	267,288 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 12	365,424 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 3	441,374 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 14	515,013 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2024 May 21	548,472 KM	GLENGARRY TRUCK CENTER LTD	Service Record	Vehicle serviced

ODOMETER	SOURCE	RECORD TYPE	DETAILS
	Alexandria, Ontario, Canada		
2024 May 22	KROWN VAUDREUIL Vaudreuil-Dorion, Québec, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

