

BRITISH
COLUMBIACommercial Vehicle
Inspection ReportDecal Number: GR04261
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21923055Inspection Result:
PASS

FACILITY:	BOSTON HOLDINGS / S6084	INSP. TYPE:	Complete	INSP. START:	2026-Sep-11 07:49 AM PDT
INSPECTOR:	BOSTON, PETER ALFRED / 102946	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Sep-11 09:50 AM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual	E04-1	

VEHICLE JUR:	British Columbia	REGI:	11485742	VIN:	1FVHG3DV7FHGL7426
PLATE #:		UNIT/FLEET#:	12	OWNER/LESSEE NAME:	PEACE CREEK CONTRACTING LTD, PEACE
LICENCED GVW(kg):	13000	BODY STYLE:	Truck Tractor	ADDRESS:	10797 MARTIN RD S, 10797 MARTIN RD S Burns Lake, British Columbia v0j1e2, Canada
VEHICLE YEAR:	2015	ODOMETER:	325235 KM		
MAKE:	FREIGHTLIN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) yoke tight
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) install reflective tape
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						Steering
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	38	38	14		16	14	✓
2	Clamp	30L	Automatic	42	38	16	16	16	16	
3	Clamp	30L	Automatic	42	38	15	16	16	16	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)				Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right		Lining/Pad		Rotor/Drum	Left	Right	
1	48	38		Lining (Shoe)	20	20	Drum		
2	74	76		Lining (Shoe)	18	18	Drum		
3	82	68		Lining (Shoe)	18	18	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: BOSTON, PETER ALFREDRoad Test Date:
Signature:

Road-Tester:

This Inspection Report was submitted to CVSE on 2026-Sep-17 08:50 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

9/17/2026 8:50:42 PM PDT