

03860909

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATEManitoba Box 45084 Regent Postal Ouf
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba 
A839206

Date Inspection Started 26 DAY 08 MO 24 YR	Station Number A4185	ROAD RIG PARTS & SERVICE LTD.	
Date Inspection Completed 26 DAY 08 MO 24 YR	Mechanic Number M10279	Station Name 	City 2043314744
Inspection Expiry Date 31 DAY 08 MO 25 YR	Vehicle Owner WILSON FARMS	Address CRYSTAL CITY MB	Postal Code R0K 0N0
		City CRYSTAL CITY	Province MB
		Postal Code R0K 0N0	Phone 204-245-1111
☒ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number TH-23-47 Prov. MB NSC # Odometer Reading Odom. Type km ☐ m ☐	Vehicle Identification Number 2LDAH2839PV074158 ☒ Confirmed legible Vehicle Identification Number on vehicle	Make KODAK Model LEAD Year 2023 Unit # 4158

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Sec																																																																						
		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H ☒ Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: ☒ A ☐ B ☐ C ☐ D ☐ E Circle appropriate Letter for Internal Brake Component Inspa																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11/16</td> <td>11/16</td> <td>16.54</td> <td>16.53</td> <td>1 3/8</td> <td>1 1/2</td> </tr> <tr> <td>2</td> <td>5/8</td> <td>5/8</td> <td>16.55</td> <td>16.52</td> <td>1 3/8</td> <td>1 1/2</td> </tr> <tr> <td>3</td> <td>3/4</td> <td>5/8</td> <td>16.53</td> <td>16.53</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11/16	11/16	16.54	16.53	1 3/8	1 1/2	2	5/8	5/8	16.55	16.52	1 3/8	1 1/2	3	3/4	5/8	16.53	16.53	1 1/2	1 1/2	4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	11/16	11/16	16.54	16.53	1 3/8	1 1/2																																																																		
2	5/8	5/8	16.55	16.52	1 3/8	1 1/2																																																																		
3	3/4	5/8	16.53	16.53	1 1/2	1 1/2																																																																		
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>13</td> <td>13</td> <td>13</td> <td>12</td> <td></td> <td></td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>13</td> <td>13</td> <td>12</td> <td>13</td> <td></td> <td></td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td>12</td> <td>12</td> <td>12</td> <td>11</td> <td></td> <td></td> <td>100</td> <td>100</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1									2	13	13	13	12			100	100	3	13	13	12	13			100	100	4	12	12	12	11			100	100	5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1																																																																								
2	13	13	13	12			100	100																																																																
3	13	13	12	13			100	100																																																																
4	12	12	12	11			100	100																																																																
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not