

Commercial Vehicle  
Inspection ReportDecal Number: GK34387  
Decal Expiry Date: 2026-Jul-31  
Inspection Number: 21428349

Inspection Result:

PASS E04

FACILITY: ARSARA DIESEL TRUCK / S5708 INSP. TYPE: Complete  
INSPECTOR: SANDHU, SHAMSHER SINGH / 114059 INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
WORK ORDER #: INSP. REASON: Annual  
INSPECTION START: 2025-Jul-16 04:00 PM PDT  
INSPECTION COMPLETE: 2025-Jul-16 09:27 PM PDT

VEHICLE JUR: British Columbia REGI: 13987010 VIN: 2M5931610M1191576  
PLATE #: 36805K UNIT/FLEET#: V1005 OWNER/LESSEE NAME: CWB NATIONAL LEASING INC.  
(LESSOR), TRANSHUB LOGISTICS LTD.  
LICENCED GVW(kg): 0 BODY STYLE: Van Trailer ADDRESS: PO BOX 98057 SCOTTSDALE PO  
VEHICLE YEAR: 2021 ODOMETER: Delta, British Columbia  
MAKE: MANAC HUB ODOMETER: V4E3M9, Canada  
MODEL: BRAKE TYPE: Air  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

## Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	34	13	7	8	16	
2	Clamp	30	Automatic	35	34	16	14	8	10	

Comment:

Comment:

## Air Brake Camshaft Rotation (degrees)

## Brake Lining/Pad (mm)

## Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	50	Lining (Shoe)	14	15	Drum		
2	40	65	Lining (Shoe)	17	13	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.


## Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SANDHU, SHAMSHER SINGH

Signature: 

This Inspection Report was submitted to CVSE on 2025-Jul-16 09:28 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE014

7/16/2025 9:28:07 PM PDT

Commercial Vehicle  
Inspection ReportDecal Number: GK34387  
Decal Expiry Date: 2026-Jul-31  
Inspection Number: 21428349

Inspection Result:

PASS

FACILITY: ARSARA DIESEL TRUCK / S5708 INSP. TYPE: Complete INSP. START: 2025-Jul-16 04:00 PM PDT  
INSPECTOR: SANDHU, SHAMSHER SINGH / 114059 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Jul-16 09:27 PM PDT  
WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 13987010 VIN: 2M5931610M1191576  
PLATE #: 36805K UNIT/FLEET#: V1005 OWNER/LESSEE NAME: CWB NATIONAL LEASING INC.  
(LESSOR), TRANSHUB LOGISTICS LTD.  
LICENCED GVW(kg): 0 BODY STYLE: Van Trailer ADDRESS: PO BOX 98057 SCOTTSDALE PO  
VEHICLE YEAR: 2021 ODOMETER: Delta, British Columbia  
MAKE: MANAC HUB ODOMETER: V4E3M9, Canada  
MODEL: BRAKE TYPE: Air  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34	34
2	Clamp	30	Automatic	35	34

Comment:

## Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13	7	8	16	
16	14	8	10	

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	50
2	40	65

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	15
Lining (Shoe)	17	13

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

## Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SANDHU, SHAMSHER SINGH

Signature:

This Inspection Report was submitted to CVSE on 2025-Jul-16 09:28 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE014

7/16/2025 9:28:07 PM PDT

E04-3


**BRITISH  
COLUMBIA**

# Commercial Vehicle Inspection Report

 Decal Number: GD29584  
 Decal Expiry Date: 2025-Jul-31  
 Inspection Number: 20998294

Inspection Result:

**PASS**

FACILITY: ARSARA DIESEL TRUCK / S5708      INSP. TYPE: Complete      INSP. START: 2024-Jul-09 03:00 PM PDT  
 INSPECTOR: SANDHU, SHAMSHER SINGH / 114059      INSP. CLASS: Class 3 - Trailer and Semi-Trailer      INSP. COMPLETE: 2024-Jul-10 12:07 AM PDT  
 WORK ORDER #:      INSP. REASON: Annual

VEHICLE JUR: British Columbia      REGI: 13987010      VIN: 2M5931610M1191576  
 PLATE #: 36805K      UNIT/FLEET#: V1005      OWNER/LESSEE NAME: CWB NATIONAL LEASING INC. (LESSOR), TRANSHUB LOGISTICS LTD.(LESSEE)  
 LICENSED GVW(kg): 0      BODY STYLE: Van Trailer      ADDRESS: PO BOX 98057 SCOTTSDALE PO  
 VEHICLE YEAR: 2021      ODOMETER: Delta, British Columbia  
 MAKE: MANAC      HUB ODOMETER: V4E3M9, Canada  
 MODEL:      BRAKE TYPE: Air  
                                  FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed 1XL BOTH SHOCK REPLACED
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34	34
2	Clamp	30	Automatic	35	34

Comment:

## Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15	15	15	15	
15	15	14	15	

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	53	45
2	35	60

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	17
Lining (Shoe)	19	15

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

## Inspection Comments:

 Was this Vehicle been road tested? No  
 Inspector: SANDHU, SHAMSHER SINGH

Road Test Date:

Signature:

Road Tester:

This inspection Report was submitted to CVSE on 2024-Jul-10 12:08 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, ISCVP at the Commercial Vehicle Safety Enforcement

2/SE0014

7/10/2024 12:08:22 AM PDT