

03860905

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATEManitoba Box 45064 Regent Postal Cx.
Winnipeg, MB R2C 5C7
1-204-985-0920Manitoba 
A839202

Date Inspection Started	23	08	24	Station Number	A4185	ROAD RIG PARTS & SERVICE LTD.
Date Inspection Completed	23	08	24	Mechanic Number	M10279	Station Name
Inspection Expiry Date	31	08	25	Station Phone Number 2043314744		
Vehicle Owner				WILSON FARMS		
Address				City	Province	Postal Code
				CRYSTAL CITY	MB	R0K 0N0
				Phone 204-245-1134		
☒ Pass/Safe Vehicle	Licence Number		TB-22-48		Prov.	MB
☒ Fail/Unsafe Vehicle	Vehicle Identification Number		2TVHP283QLD000009		NSC #	
☐ Fail/Hazardous	Confirmed legible Vehicle Identification Number on vehicle		☒		Odometer Reading	
	Make		TRAILER		Model	TITAN
	Year		2020		Unit #	0009

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bu

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A																																																																						
		Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C ☒ E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11/16</td> <td>3/4</td> <td>1.654</td> <td>1.678</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>3/4</td> <td>3/4</td> <td>1.681</td> <td>1.663</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>5/8</td> <td>5/8</td> <td>1.662</td> <td>1.663</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11/16	3/4	1.654	1.678			2	3/4	3/4	1.681	1.663			3	5/8	5/8	1.662	1.663			4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	11/16	3/4	1.654	1.678																																																																				
2	3/4	3/4	1.681	1.663																																																																				
3	5/8	5/8	1.662	1.663																																																																				
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any)																																																																						
		X-1L LICENCE PLATE LAMP INOPERATIVE																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>13</td> <td>12</td> <td>9</td> <td>12</td> <td>91</td> <td>90</td> <td>90</td> <td>90</td> </tr> <tr> <td>3</td> <td>14</td> <td>14</td> <td>13</td> <td>14</td> <td>93</td> <td>90</td> <td>92</td> <td>90</td> </tr> <tr> <td>4</td> <td>12</td> <td>10</td> <td>12</td> <td>12</td> <td>90</td> <td>91</td> <td>91</td> <td>90</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1									2	13	12	9	12	91	90	90	90	3	14	14	13	14	93	90	92	90	4	12	10	12	12	90	91	91	90	5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1																																																																								
2	13	12	9	12	91	90	90	90																																																																
3	14	14	13	14	93	90	92	90																																																																
4	12	10	12	12	90	91	91	90																																																																
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not