

03860906

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Box 45064 Regent Postal Cn.
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba
A839203

Date Inspection Started 23 DAY 08 MO 24 YR	Station Number A4185	ROAD RIG PARTS & SERVICE LTD.	
Date Inspection Completed 23 DAY 08 MO 24 YR	Mechanic Number M10279	Mechanic Signature 	Station Phone Number 2043314744
Inspection Expiry Date 31 DAY 08 MO 25 YR	Vehicle Owner WILSON FARMS		
	Address CRYSTAL CITY	Province MB	Postal Code R0K 0N0
			Phone 204-245-1134
☐ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number 3-22-49	Prov. 	NSC #
	Vehicle Identification Number 2TVHP282XLD000011	Make TRAILER	Model TITAN
	☐ Confirmed legible Vehicle Identification Number on vehicle	Year 2020	Unit # 0011
		Odometer Reading 	Odom. Type km ☐ mi ☐

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☐ Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3E Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>5/8</td> <td>5/8</td> <td>1.682</td> <td>1.662</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>3/4</td> <td>3/4</td> <td>1.663</td> <td>1.674</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	5/8	5/8	1.682	1.662			2	3/4	3/4	1.663	1.674			3							4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	5/8	5/8	1.682	1.662																																																																				
2	3/4	3/4	1.663	1.674																																																																				
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any)																																																																						
		X-1L LICENCE PLATE LAMP INOPERATIVE																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X	X	Section 8 - Body: Defects (if any)																																																																						
		X-21A LEFT SIDE MUDFLAP CONDITION																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>13</td> <td>18</td> <td>18</td> <td>16</td> <td>91</td> <td>90</td> <td>92</td> <td>90</td> </tr> <tr> <td>3</td> <td>17</td> <td>17</td> <td>12</td> <td>14</td> <td>90</td> <td>94</td> <td>90</td> <td>90</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1									2	13	18	18	16	91	90	92	90	3	17	17	12	14	90	94	90	90	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1																																																																								
2	13	18	18	16	91	90	92	90																																																																
3	17	17	12	14	90	94	90	90																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not