Commercial Vehicle Inspection Report

Decal Number: GR01806
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21973740

Inspection Result: PASS

FACILITY:	MADROCK ENTERPRISES LTD. / S20367	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Oct-29 02:00 PM MST
INSPECTOR:	STEWART, PEARCE Hunter / 201510	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Oct-29 04:00 PM MST
WORK ORDER #:		**INSP. REASON:**	Semi-annual		

VEHICLE JUR:	British Columbia	**REGI:**	15185875	**VIN:**	3BK1L40X6TF987733
PLATE #:	XJ4089	**UNIT/FLEET#:**	20203	**OWNER/LESSEE NAME:**	SAGE CREEK OILFIELD, NA
LICENCED GVW(kg):	63500	**BODY STYLE:**	Truck Tractor	**ADDRESS:**	1111 ENTERPRISE WAY
VEHICLE YEAR:	2026	**ODOMETER:**	49251 KM		Fort St John, British Columbia
MAKE:	KENWORTH	**HUB ODOMETER:**			V1J 8C9, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	**Repaired (same day)**	reverse lights LHS steer axle shock
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Repaired (same day)**	rear tortion bar bolts loose
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Not Applicable	0	0
2	Clamp	20	Not Applicable	0	0
3	Clamp	20	Not Applicable	0	0

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15			14	✔
17	15	16	15	
16	17	15	15	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	0	0
3	0	0

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	17	17.78
Pad	17	18
Pad	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Rotor	44.70	45.60
Rotor	44.60	44.50
Rotor	44.70	44.70

Comment:

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: STEWART, PEARCE Hunter **Signature:**

This Inspection Report was submitted to CVSE on 2026-Oct-30 11:05 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

10/30/2026 11:06:02 AM MST