

04058953

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba E05-16

Vehicle Safety
Box 45064 Regent
Winnipeg, MB, R2C
1-800-387-3877

DECAL
MANITOBA
C052634

Date Inspection Started: 210 12 215
Date Inspection Completed: 210 12 215
Inspection Expiry Date: 31 12 216

Station Number: A161101
Mechanic Number: 11017148
Vehicle Owner: TRANSPORT LTD.
Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____

Station Name: MID CANADA
Mechanic Signature: _____ Station Phone Number: _____

Pass/Safe Vehicle ☒
Fail/Unsafe Vehicle ☐
Fail/Hazardous ☐

Licence Number: 7H411613
Vehicle Identification Number: 11UYNIS215132G101091107
Confirmed legible Vehicle Identification Number on vehicle ☒

ISC #: _____ Odometer Reading: _____ Odometer Type: ☐ km ☐ mi
Make: 0600 Model: _____ Year: 2016 Unit #: CR3110

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
		Section 1 - Power Train: Defects (if any)																																																																							
Y		Section 2 Suspension: Defects (if any)																																																																							
Y		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>718</td><td>718</td><td>16.516</td><td>16.515</td><td>1.25</td><td>1.21</td></tr><tr><td>2</td><td>718</td><td>718</td><td>16.512</td><td>16.518</td><td>1.25</td><td>1.25</td></tr><tr><td>3</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	718	718	16.516	16.515	1.25	1.21	2	718	718	16.512	16.518	1.25	1.25	3							4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	718	718	16.516	16.515	1.25	1.21																																																																			
2	718	718	16.512	16.518	1.25	1.25																																																																			
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
		Section 4 - Steering: Defects (if any)																																																																							
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
		Section 6 - Lamps: Defects (if any)																																																																							
		Section 7 - Electrical System: Defects (if any)																																																																							
		Section 8 - Body: Defects (if any)																																																																							
		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th></th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>9</td><td>9</td><td>8</td><td>8</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>2</td><td>7</td><td>7</td><td>7</td><td>6</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	9	9	8	8	100	100	100	100	2	7	7	7	6	100	100	100	100	3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	9	9	8	8	100	100	100	100																																																																	
2	7	7	7	6	100	100	100	100																																																																	
3																																																																									
4																																																																									
5																																																																									
		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: De torque all truck after 100-150 km

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature: _____ Date: _____

445022-01 (06/25) Ce document peut être obtenu en français sur demande.

COPIES OF THIS CERTIFICATE ARE SIGNED - NOT FOR REGISTRATION