Reference #: AIP-1 Rev.1
Initiation Date: 18-Aug-2026
Engineer of Record: Dan Downey
Altec Job #: 260793

ALTEC INSPECTION LTD.

Client: Sage Creek Oilfield Services
Contact: Eric Lister
Equipment: Cat D7G c/w side boom
Unit # 68202
(make, model, unit, SN#, etc.)

Equipment Inspection and Certification Inspection Plan

(In accordance with Engineers & Geoscientists BC, Good Engineering Practices and/or Annual Equipment Inspection and Certification Guidelines, as applicable)

This "Inspection Plan" will form the basis of work to be completed throughout the inspection and certification process. It is a working document that will be completed by the Engineer of Record (EOR) as the necessary sections data/results are compiled. Sections will be completed in sequential order (Sections 1 through 4) unless otherwise instructed by the EOR. Data and results from each previous section will determine the depth of inspections required for the following section and ultimately the completion of the "Safe for Use" certification. Specific inspection requirements for each section will be communicated directly to the Client by the EOR and will be recorded in the "section notes".

Section 1 - Equipment History (documentation to be supplied by Client).

☒ Reviewed relevant equipment documentation.

☐ Documentation was incomplete or unavailable for review.

Section 1 Notes: Updated documentation to be maintained

Section 1 completion date: 18-Aug-2026
EOR initials:

Section 2 - Mechanical and Controls Inspection as per OHSR, applicable codes/standards and Manufacturers specifications.
(Inspection report to be submitted to Altec Inspection Ltd. EOR by Client or representative of)

☐ Mechanical and Controls Inspection Reports - completed by qualifed person
Mechanical and Controls Inspection Report Reference ID:

☒ Not Applicable :

Section 2 Notes: Not required by OHSR

Section 2 completion date: 18-Aug-2026
EOR initials:

Section 3 - Structural Inspection as per OHSR, applicable codes/standards and best engineering practices.
(Structural Inspection will be completed by Altec Inspection Ltd.)

☒ Structural Inspection Report - completed by qualifed person
Structural Report ID: S-DD 180826-3

Section 3 Notes: No deficiencies found at the time of inspection

Section 3 completion date: 18-Aug-2026
EOR initials:

Section 4 - Final Certification

☒ All documentation and inspections provided were found to be in compliance with the Engineers & Geoscientists BC, Good Engineering Practices and/or the Annual Equipment Inspection and Certification Guidelines. Issue "Safe for Use" certification.
Certification (Report ID): C-DD 180826-3

☐ All documentation and/or inspections were not satisfactory. Certification cannot be issued.

Section 4 Notes: Satisfactory. Maintain equipment and documentation as per OEM, OHSR and EGBC Guidelines
The referenced mast is to be used only with the referenced machine

Section 4 and self check completion date: 19/08/26
EOR initials:

OQM document review and acceptance.
Reviewed by:
Date: August 26 2026

13020 271 Rd
BOX 283
CHARLIE LAKE, B.C.
V0C 1H0

ALTEC INSPECTION LTD.

PH: (250) 785-6295
FAX: (250) 785-4395
www.altecinspection.ca

SAFE FOR USE CERTIFICATE

Inspection Plan Ref.: AIP-1 Rev.1 **Report ID: C-DD 180826-3**

CLIENT:	Sage Creek Oilfield Services
MAKE & MODEL:	Cat D7G c/w side boom assembly, including mast
SERIAL NUMBER:	Crawler: 44W00495 Mast: 68202
UNIT:	68202
LOCATION:	Fort St. John, B.C.
CERTIFICATE DATE:	August 18, 2026 **CERTIFICATE EXPIRATION DATE:** August 18, 2027
STRUCTURAL INSPECTION REF.:	S-DD 180826-3 Completed by Altec Inspection Ltd.
MECH. & CONTROLS INSPECTION REF.:	Not applicable

The Structural Inspection documents were prepared in accordance with the *Professional Practice Guidelines – Annual Equipment Inspection and Certification in British Columbia*.

Based on the information provided in the referenced inspection reports, it is my considered opinion that the above referenced equipment is Safe for Use within the OEM recommendations.

Any change to the "Safe Working Condition" of the equipment, will render this certification invalid.

The above has been completed as required by the *Occupational Health and Safety Regulations (B.C. Reg 296/97)*.

PROFESSIONAL ENGINEER PROVINCE OF BRITISH COLUMBIA D. DOWNEY 25480

Dan Downey, P. Eng.

Qualified Engineering Professional of Record
(in the Province of British Columbia)
Altec Inspection Ltd EGBC PP # 1001837

ALTEC INSPECTION LTD.

SIDE BOOM STRUCTURAL INSPECTION

DD 180826 - 3

Inspection Plan Ref. # AIP-1 Rev.1

Report ID # S-

EQUIPMENT BACKGROUND INFORMATION		
CLIENT:	Sage Creek	
DATE:	Aug 18 '18	
MAKE / MODEL / CAPACITY:	Cat D7G	
SERIAL NUMBER:	4WW00495	
UNIT	68202	
SCOPE of WORK:	☑ Annual Inspection ☐ Modification Inspection ☐ Repair Inspection	Components Included with Inspection: ☑ Mast, SN# 68202 ☐ Stringing Jib, SN# ☐ Jib, SN# ☐ Other:
Acceptance Critera (Codes / Standards):	☑ OHSR Part 14 ☐ OHSR Part 15 ☐ Other: ☐ OHSR Part 16 ☑ ASME B30.14 - 2004	

CRITICAL AREAS of INSPECTION (can include but are not limited to)		INSPECTION COMMENTS
BOOM	☑ Boom ☑ Cross member ☑ Pins & Ears	Good
BLOCK & HOOK	☑ Hook ☑ Safety Latch ☑ Pin & Bushing	Good
SHEAVES:	☑ Wear/Fatigue ☑ Boom Sheaves ☑ Hook Sheaves	Good
CABLE & GUIDES:	☑ Wear ☑ Placement ☑ Bushings	Good
COUNTER WEIGHT ASSEMBLY:	☑ Pins & Ears ☑ Safety Handle	Good
PEDESTAL MOUNT:	☑ Flanges ☑ Pins & Ears ☑ Bolts & Spacers	Good
PLACARDS:	☑ Load Chart ☑ Overhead Elect. ☑ Control Levers	✓
CABLE:	☑ Worn/Frayed ☑ Lubrication ☑ Winch Attach.	Good
UNDERCARRIAGE:	☑ Frame ☑ Bolts	Good
R.O.P.S	☑ Welds ☑ Bolts ☑ Frame Connections	Good
OTHER COMMENTS: (repairs, recommendations, non-critical deficiencies, additional equipment observations, etc.)		Satisfactory

NOTE: If the equipment is not fully disassembled some structural components may not be accessible to inspection.

Additional EOR Structural Inspection Report to follow: ☐ Yes ☒ No

INSPECTED BY:	Dan Downey (PRINT)	(SIGNATURE)	Inspectors Qualifications: ☑ Engineer and/or ☑ CSA W178.2 Reg# 5000273 ☑ CAN/CGSB 48.9712 MT2 Reg# 12510
SELF-CHECKED BY:	Dan Downey (PRINT)	(SIGNATURE)	18/08/26 (DATE)
DIRECT SUPERVISION BY: (if applicable)	(PRINT)	(SIGNATURE)	(DATE)