Reference #: AIP-1 Rev.1
Initiation Date: 25-Jun-2026
Engineer of Record: Varga Aghdasi
Altec Job #: 260622

ALTEC INSPECTION LTD.

Client: Sage Creek Oilfield Services Ltd.
Contact: Eric Lister
Equipment: Cat D7G/ MW M60C Side Booom, Unit: 68203
(make, model, unit, SN#, etc.)

Equipment Inspection and Certification Inspection Plan

(In accordance with Engineers & Geoscientists BC, Good Engineering Practices and/or Annual Equipment Inspection and Certification Guidelines, as applicable)

This "Inspection Plan" will form the basis of work to be completed throughout the inspection and certification process. It is a working document that will be completed by the Engineer of Record (EOR) as the necessary sections data/results are compiled. Sections will be completed in sequential order (Sections 1 through 4) unless otherwise instructed by the EOR. Data and results from each previous section will determine the depth of inspections required for the following section and ultimately the completion of the "Safe for Use" certification. Specific inspection requirements for each section will be communicated directly to the Client by the EOR and will be recorded in the "section notes".

Section 1 - Equipment History (documentation to be supplied by Client).

☒ Reviewed relevant equipment documentation.

☐ Documentation was incomplete or unavailable for review.

Section 1 Notes: Equipment information

Section 1 completion date: 25-Jun-2026
EOR initials: VA

Section 2 - Mechanical and Controls Inspection as per OHSR, applicable codes/standards and Manufacturers specifications.
(Inspection report to be submitted to Altec Inspection Ltd. EOR by Client or representative of)

☐ Mechanical and Controls Inspection Reports - completed by qualifed person
Mechanical and Controls Inspection Report Reference ID: _____

☒ Not Applicable : _____

Section 2 Notes: Not required as per OHSR.

Section 2 completion date: 25-Jun-2026
EOR initials: VA

Section 3 - Structural Inspection as per OHSR, applicable codes/standards and best engineering practices.
(Structural Inspection will be completed by Altec Inspection Ltd.)

☒ Structural Inspection Report - completed by qualifed person
Structural Report ID: S-VA250626-3

Section 3 Notes: The equipment was in good condition as per OHSR requirements.

Section 3 completion date: 09-Jul-2026
EOR initials: VA

Section 4 - Final Certification

☒ All documentation and inspections provided were found to be in compliance with the Engineers & Geoscientists BC, Good Engineering Practices and/or the Annual Equipment Inspection and Certification Guidelines. Issue "Safe for Use" certification.
Certification (Report ID): C-VA250626-3

☐ All documentation and/or inspections were not satisfactory. Certification cannot be issued.

Section 4 Notes: The equipment was in good condition and was safe for use.
Maintain the equipment with documentation to OHSR and OEM requirements.

Section 4 and self check completion date: 09-Jul-2026
EOR initials: VA

OQM document review and acceptance.
Reviewed by: _____
Date: July 10, 2026

13020 271 Rd
BOX 283
CHARLIE LAKE, B.C.
V0C 1H0

ALTEC INSPECTION LTD.

PH: (250) 785-6295
FAX: (250) 785-4395
www.altecinspection.ca

SAFE FOR USE CERTIFICATE

Inspection Plan Ref.: AIP-1 Rev.1 **Report ID: C-VA250626-3**

CLIENT: Sage Creek Oilfield Services Ltd.

MAKE & MODEL: Caterpillar D7G/ Midwestern M60C Side Boom Assembly without mast, Max Load capacity 60,000 lbs

SERIAL NUMBER: 72W00502/11933590

UNIT: 68203

LOCATION: Near the triangle road in Northeastern, BC

CERTIFICATE DATE: June 25, 2026 **CERTIFICATE EXPIRATION DATE:** June 25, 2027

STRUCTURAL INSPECTION REF.: S-VA250626-3
Completed by Altec Inspection Ltd. Representative.

MECH. & CONTROLS INSPECTION REF.: N/A

The Structural Inspection documents were prepared in accordance with the *Professional Practice Guidelines – Annual Equipment Inspection and Certification in British Columbia.*

Based on the information provided in the referenced inspection reports, it is my considered opinion that the above referenced equipment is Safe for Use within the OEM recommendations.

Any change to the "Safe Working Condition" of the equipment, will render this certification invalid.

The above has been completed as required by the *Occupational Health and Safety Regulations (B.C. Reg 296/97).*

PROFESSIONAL ENGINEER
PROVINCE OF BRITISH COLUMBIA
V. AGHDASI
46651

July 9, 2026

Varga Aghdasi, P. Eng.

Qualified Engineering Professional of Record
(in the Province of British Columbia)
Altec Inspection Ltd. EGBC PP# 1001837

ALTEC INSPECTION LTD.

SIDE BOOM STRUCTURAL INSPECTION

Inspection Plan Ref. # AIP-1 Rev.1

Report ID # S- VA250626-3

EQUIPMENT BACKGROUND INFORMATION			
CLIENT:	SAGE CREEK		
DATE:	June 25 2026	CAP 60,000 lbs	
MAKE / MODEL / CAPACITY:	CAT D7G / MW M60C SIDE BOOM ASSEMBLY		
SERIAL NUMBER:	72W00502 / 119 3590		
UNIT:	68203		
SCOPE of WORK:	☒ Annual Inspection ☐ Modification Inspection ☐ Repair Inspection	Components Included with Inspection: ☒ Mast, SN#_____ ☐ Jib, SN#	☐ Stringing Jib, SN#_____ ☐ Other:
Acceptance Critera (Codes / Standards):	☐ OHSR Part 14 ☐ OHSR Part 16	☐ OHSR Part 15 ☐ ASME B30.14 - 2004	☐ Other:

CRITICAL AREAS of INSPECTION (can include but are not limited to)		INSPECTION COMMENTS
BOOM	☐ Boom ☐ Cross member ☐ Pins & Ears	N/A
BLOCK & HOOK	☐ Hook ☐ Safety Latch ☐ Pin & Bushing	OK
SHEAVES:	☐ Wear/Fatigue ☐ Boom Sheaves ☐ Hook Sheaves	OK
CABLE & GUIDES:	☐ Wear ☐ Placement ☐ Bushings	OK
COUNTER WEIGHT ASSEMBLY:	☐ Pins & Ears ☐ Safety Handle	OK
PEDESTAL MOUNT:	☐ Flanges ☐ Pins & Ears ☐ Bolts & Spacers	OK
PLACARDS:	☐ Load Chart ☐ Overhead Elect. ☐ Control Levers	OK
CABLE:	☐ Worn/Frayed ☐ Lubrication ☐ Winch Attach.	OK
UNDERCARRIAGE:	☐ Frame ☐ Bolts	OK
R.O.P.S	☐ Welds ☐ Bolts ☐ Frame Connections	OK
OTHER COMMENTS: (repairs, recommendations, non-critical deficiencies, additional equipment observations, etc.)		

NOTE: If the equipment is not fully disassembled some structural components may not be accessible to inspection.

Additional EOR Structural Inspection Report to follow: ☐ Yes ☒ No

INSPECTED BY:	MARCO.A (PRINT)	(SIGNATURE)	Inspectors Qualifications: ☒ Engineer and/or ☐ CSA W178.2 Reg# 1056865 ☐ CAN/CGSB 48.9712 MT2 Reg# 19187
SELF-CHECKED BY:	MARCO.A (PRINT)	(SIGNATURE)	July 9 2026 (DATE)
DIRECT SUPERVISION BY: (if applicable)	(PRINT)	(SIGNATURE)	(DATE)

Document Rev. Date: May 5, 2021


ALTEC
Inspection Ltd.
Inspection & Engineering
Contact:(250) 785-6295
STRUCTURAL INSPECTION TAG
VA250626-3
UNIT
G8203
Make: CAT / MW
Model #: D7G / M60C
Date: JUNE 25, 2026
Ser.# 7ZW00502 / M9535910
Inspector: VAL G/A