Commercial Vehicle Inspection Report

BRITISH COLUMBIA

Decal Number: GK44196
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21658530

Inspection Result: **PASS**

FACILITY:	MADROCK ENTERPRISES LTD. / S20367	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Feb-06 09:00 AM MST
INSPECTOR:	STEWART, PEARCE Hunter / 201510	**INSP. CLASS:**	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2026-Feb-06 11:00 AM MST
WORK ORDER #:		**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REGI:**	14658516	**VIN:**	2K9KB22599L052196
PLATE #:	06421L	**UNIT/FLEET#:**	21202	**OWNER/LESSEE NAME:**	SAGE CREEK OILFIELD SERVICES, N/A
LICENCED GVW(kg):	0	**BODY STYLE:**	Booster Trailer	**ADDRESS:**	11111 ENTERPRISE WAY
VEHICLE YEAR:	2009	**ODOMETER:**			Fort St John, British Columbia
MAKE:	K-LINE	**HUB ODOMETER:**			V1J8C9, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	**Repaired (same day)**	BOTH BRAKE VALVES NEED REPLACEING
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Repaired (same day)**	WELDED IN NEW CROSS RAIL
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	30	28
2	Clamp	30	Automatic	30	32

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14	12	7	7	
16	16	14	13	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	60
2	70	70

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	15
Lining (Shoe)	14	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: STEWART, PEARCE Hunter **Signature:**

This Inspection Report was submitted to CVSE on 2026-Feb-09 11:06 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

2/9/2026 11:06:28 AM MST