



Commercial Vehicle
Inspection Report

Decal Number: GL71538
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21738372

Inspection Result:
PASS

FACILITY:	PRESPTOU TRUCK / S6770	INSP. TYPE:	Complete	INSP. START:	2026-Apr-17 04:51 PM MST
INSPECTOR:	WALL, JEREMIA JACOB / 201439	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Apr-17 05:51 PM MST
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	14184865	VIN:	2A9TD1019NN125250
PLATE #:	06424L	UNIT/FLEET#:	21203	OWNER/LESSEE NAME:	SAGE CREEK OILFIELD SERVICES, SAGE CREEK OILFIELD SERVICES
LICENCED GVW(kg):	0	BODY STYLE:	Booster Trailer	ADDRESS:	11111 ENTERPRISE WAY Fort St John, British Columbia V1J8C9, Canada
VEHICLE YEAR:	2022	ODOMETER:			
MAKE:	ASPEN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	41	41	20	20	20	20	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	30	Lining (Shoe)	19	19	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: WALL, JEREMIA JACOB Signature: *Jeremy Wall*

This Inspection Report was submitted to CVSE on 2026-Apr-17 05:51 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.