



Commercial Vehicle Inspection Report

Decal Number: GM80850
Decal Expiry Date: 2027-Oct-31
Inspection Number: 21960548

Inspection Result:
PASS

FACILITY: MADROCK ENTERPRISES LTD. / S20367
INSPECTOR: STEWART, PEARCE Hunter / 201510
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 3 - Trailer and Semi-Trailer
INSPECTION REASON: Annual
INSPECTION START: 2026-Oct-19 12:00 PM MST
INSPECTION COMPLETE: 2026-Oct-19 01:30 PM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 27810L
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2006
MAKE: BWS
MODEL:
REGI: 10027043
UNIT/FLEET#: 21207
BODY STYLE: High Boy Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
VIN: 2B953HF3261006934
OWNER/LESSEE NAME: SAGE CREEK OILFIELD, NA
ADDRESS: 1111 ENTERPRISE WAY
Fort St John, British Columbia
V1J 8C9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) ALL SIX AIR BAGS WEATHERED
Section 3 - Brake System	Repaired (same day) #3 RIGHT WHEEL SEAL
Section 3A - Air Brakes	Repaired (same day) #1 LEFT BRAKE POT
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30L	Automatic	45	45	7	7	7	7	
2	Clamp	30L	Automatic	44	45	9	8	8	8	
3	Clamp	30L	Automatic	45	45	7	6	6	7	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	52	51
2	42	56
3	56	56

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	14
Lining (Shoe)	16	16
Lining (Shoe)	18	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: STEWART, PEARCE Hunter
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Oct-20 01:31 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

10/20/2026 1:31:21 PM MST