

04078806

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



Eos-5

Vehicle Safety
Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



C070376

Date Inspection Started DAY: 05 MO: 03 YR: 26	Station Number 76319	Station Name Winnipeg Central Fleet	City Winnipeg
Date Inspection Completed DAY: 06 MO: 03 YR: 26	Mechanic Number 710692	Mechanic Signature [Signature]	Station Phone Number 204-999-2893
Inspection Expiry Date DAY: 31 MO: 03 YR: 27	Vehicle Owner TRIPLE LEASING CAPITAL CORPORATION		
Address		City	Province
Postal Code		Phone	
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number CRJ326	Prov. MB	NSC # MB1713249
Vehicle Identification Number 3AKN6L1D56G5GW9UBR		Make FLY	Model Capra
☒ Confirmed legible Vehicle Identification Number on vehicle		Odometer Reading 2036910	Odom. Type ☒ km ☐ mi
		Year 16	Unit # 1810

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X	X	Section 2 Suspension: Defects (if any) 700 All shock fail 491 Rear trailing ball loose																																																																							
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>518</td><td>518</td><td>43.8</td><td>43.5</td><td>DISC</td><td>DISC</td></tr><tr><td>2</td><td>518</td><td>1116</td><td>44.01</td><td>44.3</td><td>DISC</td><td>DISC</td></tr><tr><td>3</td><td>518</td><td>518</td><td>44.02</td><td>44.30</td><td>DISC</td><td>DISC</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	518	518	43.8	43.5	DISC	DISC	2	518	1116	44.01	44.3	DISC	DISC	3	518	518	44.02	44.30	DISC	DISC	4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	518	518	43.8	43.5	DISC	DISC																																																																			
2	518	1116	44.01	44.3	DISC	DISC																																																																			
3	518	518	44.02	44.30	DISC	DISC																																																																			
4																																																																									
5																																																																									
Final Measurement																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X	X	Section 7 - Electrical System: Defects (if any) 2101 Battery Post need to be clean																																																																							
X	X	Section 8 - Body: Defects (if any) 1810 Left Driver Side glass cracked 2110 Passenger Side Rear Fender missing																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th></th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td></td><td>14 14</td><td></td><td></td><td>100</td><td>100</td><td></td><td></td></tr><tr><td>2</td><td>10 10</td><td>11 8</td><td></td><td></td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>8 8</td><td>11 11</td><td></td><td></td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1		14 14			100	100			2	10 10	11 8			100	100	100	100	3	8 8	11 11			100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1		14 14			100	100																																																																			
2	10 10	11 8			100	100	100	100																																																																	
3	8 8	11 11			100	100	100	100																																																																	
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: All MYEL need to be Replac AFTER 60 KM
All work done by G M R Transport

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

