Date: October 19, 2026

Company Name	Sage Creek Oilfield	Make	Diamond Back
Equipment Type	Highboy Trailer	Vin #	2B953HF3261006934
Model	BW5	Kilometers	
Hours		Unit #	21207
Year	2006	Reg/Plate	10027043

Brought the unit into the shop and began going over the unit as per cvip inspection list, making a list of repairs required to pass inspection. Took all measurements and prepared a quote for the customer. Once the customer had approved, ordered and picked up parts for repairs and returned to the shop.

1st axle LHS removed and replaced brake chamber. 1st axle LHS removed and replaced wheel seal. 1st axle LHS removed and replaced air bag. Removed remaining airbags and replaced with new. Removed and replaced 3rd axle RHS wheel seal. Removed dolly leg brace and welded new brace to install onto the unit. Cleaned up around the unit and installed dust covers with new bolts. Prepared CVIP paperwork and applied the decal to the unit. Contacted customer for pick up.

16.5hr