Commercial Vehicle Inspection Report

Decal Number: GR01802
Decal Expiry Date: 2027-Oct-31
Inspection Number: 21965433

Inspection Result: PASS

FACILITY:	MADROCK ENTERPRISES LTD. / S20367	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Oct-22 12:00 PM MST
INSPECTOR:	STEWART, PEARCE Hunter / 201510	**INSP. CLASS:**	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2026-Oct-22 01:30 PM MST
WORK ORDER #:		**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REGI:**	11494662	**VIN:**	2B953HF31E1001187
PLATE #:	27818L	**UNIT/FLEET#:**	21208	**OWNER/LESSEE NAME:**	SAGE CREEK OILFIELD, NA
LICENCED GVW(kg):	999999	**BODY STYLE:**	High Boy Trailer	**ADDRESS:**	1111 ENTERPRISE WAY
VEHICLE YEAR:	2014	**ODOMETER:**			Fort St John, British Columbia
MAKE:	BWS	**HUB ODOMETER:**			V1J 8C9, Canada
MODEL:	53HF3	**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed		
Section 1 - Power Train	Not Applicable		
Section 2 - Suspension	Passed		
Section 3 - Brake System	**Repaired (same day)**	WHEEL SEALS #2 AND#3	
Section 3A - Air Brakes	**Repaired (same day)**	#2 LEFT AND RIGHT BRAKE CHAMBER REPLACED	
Section 3H - Hydraulic Brakes	Not Applicable		
Section 4 - Steering	Passed		
Section 5 - Instruments and Auxiliary Equipment	Passed		
Section 6 - Lamps	Passed		
Section 7 - Electrical System	Passed		
Section 8 - Frame and Body	Passed		
Section 9A - Tires	Passed		
Section 9B - Wheels	Passed		
Section 10 - Coupling Devices	Passed		
Section 11 - Other Vehicle Components	Passed		

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	41.3	41.3
2	Clamp	30	Automatic	38.1	50.8
3	Clamp	30	Automatic	38.1	34.9

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15	14	14	12	
17	14	12	15	
12	16	15	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	34	42
2	29	40
3	35	33

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	18
Lining (Shoe)	19	19
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:**

Inspector: STEWART, PEARCE Hunter **Signature:** **Road Tester:**

This Inspection Report was submitted to CVSE on 2026-Oct-23 02:53 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

10/23/2026 2:53:34 PM MST