

Date	Maintenance Item	Description
July 13 2025	Inspection Repair	See work order in equipment folder
July 23 2025	Inspection Repair	See work order in equipment folder
August 13 2025	Welding	Rig welder torched all rotten cross members
August 14 2025	Steel	Total material cost for replacement steel
August 14 2025	Welding	Two rig welders completed torching, welded majority of replacement cross members
October 14 2025	Blast/coat	ArcTech welding completed blasting and coating bumper to bumper
October 15 2025	Deck boards	
October 23 2025	Centre Left Hub Cap	Install middle left hub cap, top up all hub oil, secure loose harness, install trailer cord plug, repair air leak from quick release valve
January 14 2026	Brake Repair	See work order in equipment folder
October 27 2026	Inspection Repair	See work order in equipment folder