



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0939

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / No	REPAIR: <input checked="" type="radio"/> Yes / No	COMPLETE: <input checked="" type="radio"/> Yes / No
DATE: 26-11-25	LOCATION: yard		
MAKE: Broadcrown	MODEL: BCC550-50EC	HOURS: 11022	
UNIT ID: m.31.500.11	ENGINE MODEL: Cummins	ENGINE SERIAL No.:	
JOB DESCRIPTION: - Carry out service as Req.			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		80 Litres	
Engine Oil Filter		✓	x1 P559000
Air Filter		✓	x1 P613333
Coolant	✓	Litres	
Coolant Filter	✓		
Check Belts	✓		
Check Engine Mounts	✓		
Check Exhaust System	✓		
Check Battery	✓		
Fuel Filter		✓	x1 P551047 x1 P552040
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
* Needs wash & Del	Technician's Signature:	Date: 26-11-25	
	NAME IN BLOCK LETTERS: Janie		
	Customer's Signature:	Date:	
	NAME IN BLOCK LETTERS:		



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0910

Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / <input type="radio"/> No	REPAIR: Yes / <input checked="" type="radio"/> No	COMPLETE: <input checked="" type="radio"/> Yes / <input type="radio"/> No
DATE: 10-06-25	LOCATION: 1004 Hampton		
MAKE: Broadcross	MODEL: BCC 550	HOURS: 10669	
UNIT ID: hm-31.500.11	ENGINE MODEL: Cummins	ENGINE SERIAL No.:	
DESCRIPTION: - carry out service as per			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		90 Litres	
Engine Oil Filter		✓	X1P559000
Air Filter	✓		
Coolant	✓	Litres	
Coolant Filter	✓		
Check Belts	✓		
Check Engine Mounts	✓		
Check Exhaust System	✓		
Check Battery	✓		
Fuel Filter		✓	X1P5510017 X1P5570041
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	17:00	2:30	1hr
Technician's Signature: <i>[Signature]</i>		Date: 10-6-25	
NAME IN BLOCK LETTERS: Jamie			
Customer's Signature: <i>[Signature]</i>		Date:	
NAME IN BLOCK LETTERS:			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0496

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	REPAIR: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	COMPLETE: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
DATE: 6-5-25	LOCATION: Leon Hampton		
MAKE: BroadCrown	MODEL: BCC 550 - 56E2	HOURS: 10402	
UNIT ID: M.31.560.11	ENGINE MODEL: Cummins	ENGINE SERIAL No.:	34053826
JOB DESCRIPTION: top up engine oil supply 20lt top up oil			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		3 Litres	
Engine Oil Filter			
Air Filter			
Coolant		Litres	
Coolant Filter			
Check Belts			
Check Engine Mounts			
Check Exhaust System			
Check Battery			
Fuel Filter			
Check for Oil Leaks			
Tighten Hose Clamps			
Check Hose Condition			

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	1.00	2.00	1hr
Technician's Signature:		Date:	
<i>[Signature]</i>		6-5-25	
NAME IN BLOCK LETTERS:			
Janie			
Customer's Signature:		Date:	
<i>[Signature]</i>			
NAME IN BLOCK LETTERS:			
Chris Nicault			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0284

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: Yes <input type="radio"/> No <input checked="" type="radio"/>	REPAIR: Yes / No <input checked="" type="radio"/>	COMPLETE: Yes / No <input checked="" type="radio"/>
DATE: 5-4-25	LOCATION: 4 Widdop Crescent Hampton East		
MAKE: Broad Crown	MODEL:	HOURS: 10253	
UNIT ID: M.31.500.11	ENGINE MODEL: QSX15-G8	ENGINE SERIAL No.:	79476835
JOB DESCRIPTION: Replaced coolant hose at coolant header tank			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil	<input checked="" type="checkbox"/>	Litres	
Engine Oil Filter			
Air Filter			
Coolant	<input checked="" type="checkbox"/>	Litres	
Coolant Filter			
Check Belts			
Check Engine Mounts			
Check Exhaust System			
Check Battery			
Fuel Filter			
Check for Oil Leaks			
Tighten Hose Clamps			
Check Hose Condition			

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	10.00	11.00	1 hour
Technician's Signature: S. Divil		Date: 5-4-25	
NAME IN BLOCK LETTERS: STEVE			
Customer's Signature:		Date:	
NAME IN BLOCK LETTERS:			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

0478

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / No	REPAIR: <input checked="" type="radio"/> Yes / No	COMPLETE: <input checked="" type="radio"/> Yes / No
----------------------	--	---	---

DATE: 19-03-25 LOCATION: Yard

MAKE: Broadcrown MODEL: BCC550-5062 HOURS: 10245

UNIT ID: 3m.31.500 ENGINE MODEL: Cummins ENGINE SERIAL No.: 34053826

JOB DESCRIPTION:

- Carry out service as Req
- load bank
- clean
- Replaced battery

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		80 Litres	
Engine Oil Filter		✓	x1P559000
Air Filter	✓		Cleaned
Coolant	✓	Litres	
Coolant Filter	✓		
Check Belts	✓		
Check Engine Mounts	✓		
Check Exhaust System	✓		
Check Battery		✓	Replaced
Fuel Filter			x1P551047
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
Technician's Signature: <i>[Signature]</i>			Date: 20-03-25
NAME IN BLOCK LETTERS: <i>Jamie</i>			
Customer's Signature:			Date:
NAME IN BLOCK LETTERS:			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0377

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:		SERVICE: <input checked="" type="radio"/> Yes <input type="radio"/> No	REPAIR: <input checked="" type="radio"/> Yes <input type="radio"/> No	COMPLETE: Yes / No
DATE: 3-4-24	LOCATION: Yard			
MAKE: Broadcrown	MODEL: Bcc550-50G2	HOURS: 9852		
UNIT ID: m-31-500-11	ENGINE MODEL: Cummins	ENGINE SERIAL No.:		
JOB DESCRIPTION:				
<p>- carry out service as Req - Clean Radiator & Intercooler • load Genk</p>				

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		70 Litres	
Engine Oil Filter		✓	+1 P559000
Air Filter		✓	+1 P613333
Coolant	✓	Litres	
Coolant Filter	✓		
Check Belts	✓		
Check Engine Mounts	✓		
Check Exhaust System	✓		
Check Battery	✓		
Fuel Filter		✓	+1 P551047 +1 P552044
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
Technician's Signature: <i>[Signature]</i>		Date: 6-5-24	
NAME IN BLOCK LETTERS: Janie			
Customer's Signature:		Date:	
NAME IN BLOCK LETTERS:			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0306

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:		SERVICE: Yes / <input checked="" type="radio"/> No	REPAIR: <input checked="" type="radio"/> Yes / No	COMPLETE: <input checked="" type="radio"/> Yes / No
DATE: 28-9-23	LOCATION: Danids epping			
MAKE: Broadcrown	MODEL:	HOURS: 8921		
UNIT ID: m.31.500.11	ENGINE MODEL: Cummins	ENGINE SERIAL No.:		
JOB DESCRIPTION:				
- Glow white smoke checked found Fuel filter block changed test all OK				

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		Litres	
Engine Oil Filter			
Air Filter			
Coolant		Litres	
Coolant Filter			
Check Belts			
Check Engine Mounts			
Check Exhaust System			
Check Battery			
Fuel Filter			X1 P858040 X1 P551047
Check for Oil Leaks			
Tighten Hose Clamps			
Check Hose Condition			

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	9.00	11.00	30-min
Technician's Signature:			Date: 28-9-23
NAME IN BLOCK LETTERS:		Denise	
Customer's Signature:			Date:
NAME IN BLOCK LETTERS:			

Acoustic Packages

STANDARD PRODUCT RANGES 6kVA–2000kVA

Acoustic Containers

Our acoustic containers are attractive, robust, easy to transport and deliver effective acoustic performance.

These container packages are based on standard ISO 20 ft and 40 ft high cube shipping containers for ease of transport by sea or land.

Construction

Our acoustic containers are fully welded and fitted with rock wool and a perforated zintec steel lining to achieve greater acoustic performance. The internally mounted silencers are custom designed to reduce exhaust noise. A two-pack polyurethane paint system provides a durable finish and all doors are fitted with high-security locks.

Fuel tank

Some models (dependent on engine type) can be supplied with integral fuel tank.

Options include

- Interior lighting and small power
- Motorised air inlet/outlet dampers
- External fuel connections
- External auxiliary power connections
- Lub oil make-up tank
- CSC Plating

	Enclosure Type	Dimensions (mm) (L x W x H)	Weight (kg)*	Typical Sound Pressure Level		Fuel Tank Capacity (litres)		Single Centre Point Lift
				dB(A)@1m	dB(A)@7m	Integral	Bunded	
M1	Midi 1 Canopy	1810 x 950 x 1190	125	73	63	55	—	●
M2	Midi 2 Canopy	2110 x 890 x 1240	195	74	64	95	—	○
C1	Canopy 1	2270 x 890 x 1620	235	77	67	115	100	○
C2	Canopy 2	2800 x 1110 x 1790	450	78	68	240	200	○
C3	Canopy 3	3550 x 1160 x 1800	725	80	70	460	400	
C4	Canopy 4	3940 x 1300 x 1940	770	80	70	570	500	
C4A	Canopy 4A	4000 x 1440 x 2120	1150	80	70	665	615	
C5	Canopy 5	5200 x 1740 x 2200	2400	77	67	985	895	○
C6	Canopy 6	5500 x 1740 x 2360	2950	80	70	1025	895	○
C7	Canopy 7	5900 x 2040 x 2480	3520	80	70	1430	1300	○
ISO-20	ISO 20ft Container	6060 x 2440 x 2770	—	80	70	—	—	
ISO-20 HC	ISO 20ft Container 'High Cube'	6060 x 2440 x 3075	—	80	70	—	—	
ISO-40 HC	ISO 40ft Container 'High Cube'	12200 x 2440 x 3075	—	80	70	—	—	

Typical SPL is a mean level, measured in free field conditions, with no contributory background noise.

● Standard Equipment

○ Available as an option

* Indicative weight additional to open set

broadcrown[®]

Diesel Generating Set ISO 8528

BCC550-50E2

Plant No: 571311
Build Date: Dec 2011
PRP kVA 500
PRP kW 400
Volts: 415
Amps: 696
Frequency: 50Hz
Phase: 3-Ph
P.F. Cos Φ : 0.8
r/min: 1500
Winding: Star 311
Insul. Class: H
Perf. Class: G2

Broadcrown Ltd

Airfield Industrial Estate, Hixon
Stafford, Staffs ST18 0PF, England
tel: +44 (0) 1889 272200
email: info@broadcrown.co.uk

www.broadcrown.com

Member of the
Association of Manufacturers
of Power Generating Systems



Manufactured in the United Kingdom

broadcrown[®]

For spare parts and service please contact:

Broadcrown Ltd

Airfield Industrial Estate, Hixon, Stafford, Staffs ST18 0PF
England

tel: +44 (0)1889 272200 fax: +44 (0)1889 271968

email: service@broadcrown.co.uk

www.broadcrown.com

Use of spare parts not approved by Broadcrown Ltd may invalidate the warranty.

Tax Invoice 00296054

MCG CRANES PLEASE PROVIDE ORDER NUMBER!
PO Box 63
Campbellfield Vic 3061

MCG CRANES PLEASE PROVIDE ORDER NUMBER!
258 Mahoneys Road
Thomastown Vic 3074

Date 31/08/2021
Your No. 8903
Terms Net 30 after EOM
Rep Billal

QTY	ITEM NO.	DESCRIPTION	Unit Price	Total (Inc-GST)
2	SCMF31-931	31-931 TRUCK BATTERY	\$204.545	\$450.00

12 months warranty

Sale Amt.:	\$409.09
Freight:	\$0.00
GST:	\$40.91
Total Amt.:	\$450.00
Paid Today:	\$0.00

Name: _____ Signature: _____

Balance Due: **\$450.00**



258 Mahoneys Road Thomastown Vic 3074

Tel: 03 9462 8400

Fax: 03 9462 3496

Mob: 0499 624 624

Email: accounts@mcgcranes.com

GENERATOR WORK ORDER

01205

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / No	REPAIR: <input checked="" type="radio"/> Yes / No	COMPLETE: <input checked="" type="radio"/> Yes / No
DATE: 10-08-21	LOCATION: Yard		
MAKE:	MODEL: Brodowau	HOURS: 8773	
UNIT ID: 004	ENGINE MODEL:	ENGINE SERIAL No.:	
JOB DESCRIPTION:			
<p>- Carry Out Service as Req - bad Gank - Clean Intercooler & Rad</p>			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		83 Litres	
Engine Oil Filter		✓	P550949
Air Filter		✓	P613333
Coolant		Litres	
Coolant Filter		✓	P550866
Check Belts	✓		
Check Engine Mounts			
Check Exhaust System	✓		
Check Battery	✓		
Grease	N/A		
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		
Fuel Filter		✓	P551047 / P55 2040

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
Technician's Signature: <i>[Signature]</i>		Date: 27-08-21	
NAME IN BLOCK LETTERS: Jamil			
Customer's Signature:		Date:	
NAME IN BLOCK LETTERS:			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0939

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / No	REPAIR: <input checked="" type="radio"/> Yes / No	COMPLETE: <input checked="" type="radio"/> Yes / No
DATE: 26-11-25	LOCATION: yard		
MAKE: Broadcrown	MODEL: BCC550-50EC	HOURS: 11022	
UNIT ID: m.31.500.11	ENGINE MODEL: Cummins	ENGINE SERIAL No.:	
JOB DESCRIPTION: - Carry out service as Req.			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		80 Litres	
Engine Oil Filter		✓	x1 P559000
Air Filter		✓	x1 P613333
Coolant	✓	Litres	
Coolant Filter	✓		
Check Belts	✓		
Check Engine Mounts	✓		
Check Exhaust System	✓		
Check Battery	✓		
Fuel Filter		✓	x1 P551047 x1 P552040
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
* Needs wash & Del			
Technician's Signature:		Date: 26-11-25	
NAME IN BLOCK LETTERS: Janic			
Customer's Signature:		Date:	
NAME IN BLOCK LETTERS:			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0910

Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / <input type="radio"/> No	REPAIR: Yes / <input checked="" type="radio"/> No	COMPLETE: <input checked="" type="radio"/> Yes / <input type="radio"/> No
----------------------	--	---	---

DATE: 10-06-25 LOCATION: 1004 Hampton

MAKE: Broadcross MODEL: BCC 550 HOURS: 10669

UNIT ID: hm-31-500-11 ENGINE MODEL: Cummins ENGINE SERIAL No.:

DESCRIPTION:
 - carry out service as per

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		90 Litres	
Engine Oil Filter		✓	X1P559000
Air Filter	✓		
Coolant	✓	Litres	
Coolant Filter	✓		
Check Belts	✓		
Check Engine Mounts	✓		
Check Exhaust System	✓		
Check Battery	✓		
Fuel Filter		✓	X1P551017 X1P557041
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	17.00	2.30	1hr
	Technician's Signature: <i>[Signature]</i>		Date: 10-6-25
	NAME IN BLOCK LETTERS: <i>Janie</i>		
	Customer's Signature: <i>[Signature]</i>		Date:
	NAME IN BLOCK LETTERS:		



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0496

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	REPAIR: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	COMPLETE: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
----------------------	--	---	---

DATE: 6-5-25 LOCATION: Leon Hampton

MAKE: BroadCrown MODEL: BCC 550 - 56E2 HOURS: 10402

UNIT ID: m.31.500.11 ENGINE MODEL: Cummins ENGINE SERIAL No.: 34053826

JOB DESCRIPTION:
 top up engine oil
 supply 20lt top up oil

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		3 Litres	
Engine Oil Filter			
Air Filter			
Coolant		Litres	
Coolant Filter			
Check Belts			
Check Engine Mounts			
Check Exhaust System			
Check Battery			
Fuel Filter			
Check for Oil Leaks			
Tighten Hose Clamps			
Check Hose Condition			

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	1.00	2.00	1hr
Technician's Signature:		Date:	
<i>[Signature]</i>		6-5-25	
NAME IN BLOCK LETTERS:			
Chris			
Customer's Signature:		Date:	
<i>[Signature]</i>			
NAME IN BLOCK LETTERS:			
CHRIS NICOLET			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0284

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: Yes <input type="radio"/> No <input checked="" type="radio"/>	REPAIR: Yes <input type="radio"/> No <input checked="" type="radio"/>	COMPLETE: Yes <input type="radio"/> No <input checked="" type="radio"/>
DATE: 5-4-25	LOCATION: 4 Widdop Crescent Hampton East		
MAKE: Broad Crown	MODEL:	HOURS: 10253	
UNIT ID: M.31.500.11	ENGINE MODEL: QSX15-G8	ENGINE SERIAL No.:	79476835
JOB DESCRIPTION: Replaced coolant hose at coolant header tank			

Check	OK	Changed	Part No. / Supplier / Notes...
Engine Oil	<input checked="" type="checkbox"/>	Litres	
Engine Oil Filter			
Air Filter			
Coolant	<input checked="" type="checkbox"/>	Litres	
Coolant Filter			
Check Belts			
Check Engine Mounts			
Check Exhaust System			
Check Battery			
Fuel Filter			
Check for Oil Leaks			
Tighten Hose Clamps			
Check Hose Condition			

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	10.00	11.00	1 hour
Technician's Signature: S. Duval		Date: 5-4-25	
NAME IN BLOCK LETTERS: STEVE			
Customer's Signature:		Date:	
NAME IN BLOCK LETTERS:			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0478

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / No	REPAIR: <input checked="" type="radio"/> Yes / No	COMPLETE: <input checked="" type="radio"/> Yes / No
----------------------	--	---	---

DATE: 19-03-25 LOCATION: Yard

MAKE: Broadcrown MODEL: BCC550-5062 HOURS: 10245

UNIT ID: 3m.31.500 ENGINE MODEL: Cummins ENGINE SERIAL No.: 34653826

JOB DESCRIPTION:

- Carry out service as Req
- load bank
- clean
- Replaced battery

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		80 Litres	
Engine Oil Filter		✓	x1P559000
Air Filter	✓		Cleaned
Coolant	✓	Litres	
Coolant Filter	✓		
Check Belts	✓		
Check Engine Mounts	✓		
Check Exhaust System	✓		
Check Battery		✓	Replaced
Fuel Filter			x1P551047
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
Technician's Signature: <i>[Signature]</i>			Date: 20-03-25
NAME IN BLOCK LETTERS: Jamie			
Customer's Signature:			Date:
NAME IN BLOCK LETTERS:			



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0377

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / <input type="radio"/> No	REPAIR: <input checked="" type="radio"/> Yes / <input type="radio"/> No	COMPLETE: Yes / No
DATE: 3-4-24	LOCATION: Yard		
MAKE: Broadcrown	MODEL: Bcc550-50G2	HOURS: 9852	
UNIT ID: m-31-500-11	ENGINE MODEL: Cummins	ENGINE SERIAL No.:	
JOB DESCRIPTION: - carry out service as Req - Clean Radiator & Intercooler - load bank			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		70 Litres	
Engine Oil Filter		✓	x1 P559000
Air Filter		✓	x1 P613333
Coolant	✓	Litres	
Coolant Filter	✓		
Check Belts	✓		
Check Engine Mounts	✓		
Check Exhaust System	✓		
Check Battery	✓		
Fuel Filter		✓	x1 P551047 x1 P552044
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	Technician's Signature: <i>[Signature]</i>	Date: 6-5-24	
	NAME IN BLOCK LETTERS: <i>Janic</i>		
	Customer's Signature:	Date:	
	NAME IN BLOCK LETTERS:		



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au

GENERATOR WORK ORDER

0306

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:		SERVICE: Yes / <input checked="" type="radio"/> No	REPAIR: <input checked="" type="radio"/> Yes / No	COMPLETE: <input checked="" type="radio"/> Yes / No
DATE: 28-9-23	LOCATION: Danids epping			
MAKE: Broadcrown	MODEL:	HOURS: 8921		
UNIT ID: m-31-500-11	ENGINE MODEL: Cummins	ENGINE SERIAL No.:		
JOB DESCRIPTION: - Glow white smoke checked found fuel filter block changed best all ok				

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		Litres	
Engine Oil Filter			
Air Filter			
Coolant		Litres	
Coolant Filter			
Check Belts			
Check Engine Mounts			
Check Exhaust System			
Check Battery			
Fuel Filter			X1 P558040 X1 P551047
Check for Oil Leaks			
Tighten Hose Clamps			
Check Hose Condition			

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	9.00	11.00	30-min
Technician's Signature:		Date: 28-9-23	
NAME IN BLOCK LETTERS: Dennis			
Customer's Signature:		Date:	
NAME IN BLOCK LETTERS:			

Acoustic Packages

STANDARD PRODUCT RANGES 6kVA–2000kVA

Acoustic Containers

Our acoustic containers are attractive, robust, easy to transport and deliver effective acoustic performance.

These container packages are based on standard ISO 20 ft and 40 ft high cube shipping containers for ease of transport by sea or land.

Construction

Our acoustic containers are fully welded and fitted with rock wool and a perforated zintec steel lining to achieve greater acoustic performance.

The internally mounted silencers are custom designed to reduce exhaust noise. A two-pack polyurethane paint system provides a durable finish and all doors are fitted with high-security locks.

Fuel tank

Some models (dependent on engine type) can be supplied with integral fuel tank.

Options include

- Interior lighting and small power
- Motorised air inlet/outlet dampers
- External fuel connections
- External auxiliary power connections
- Lub oil make-up tank
- CSC Plating

	Enclosure Type	Dimensions (mm) (L x W x H)	Weight (kg) *	Typical Sound Pressure Level		Fuel Tank Capacity (litres)		Single Centre Point Lift
				dB(A)@1m	dB(A)@7m	Integral	Bunded	
M1	Midi 1 Canopy	1810 x 950 x 1190	125	73	63	55	—	●
M2	Midi 2 Canopy	2110 x 890 x 1240	195	74	64	95	—	○
C1	Canopy 1	2270 x 890 x 1620	235	77	67	115	100	○
C2	Canopy 2	2800 x 1110 x 1790	450	78	68	240	200	○
C3	Canopy 3	3550 x 1160 x 1800	725	80	70	460	400	
C4	Canopy 4	3940 x 1300 x 1940	770	80	70	570	500	
C4A	Canopy 4A	4000 x 1440 x 2120	1150	80	70	665	615	
C5	Canopy 5	5200 x 1740 x 2200	2400	77	67	985	895	○
C6	Canopy 6	5500 x 1740 x 2360	2950	80	70	1025	895	○
C7	Canopy 7	5900 x 2040 x 2480	3520	80	70	1430	1300	○
ISO-20	ISO 20ft Container	6060 x 2440 x 2770	—	80	70	—	—	
ISO-20 HC	ISO 20ft Container 'High Cube'	6060 x 2440 x 3075	—	80	70	—	—	
ISO-40 HC	ISO 40ft Container 'High Cube'	12200 x 2440 x 3075	—	80	70	—	—	

Typical SPL is a mean level, measured in free field conditions, with no contributory background noise.

- Standard Equipment
- Available as an option
- * Indicative weight additional to open set

broadcrown[®]

Diesel Generating Set ISO 8528

BCC550-50E2


Plant No: 571311
Build Date: Dec 2011
PRP kVA 500
PRP kW 400
Volts: 415
Amps: 696
Frequency: 50Hz
Phase: 3-Ph
P.F. Cos Φ : 0.8
r/min: 1500
Winding: Star 311
Insul. Class: H
Perf. Class: G2

Broadcrown Ltd

Airfield Industrial Estate, Hixon
Stafford, Staffs ST18 0PF, England
tel: +44 (0) 1889 272200
email: info@broadcrown.co.uk

www.broadcrown.com

Member of the
Association of Manufacturers
of Power Generating Systems



Manufactured in the United Kingdom

broadcrown[®]

For spare parts and service please contact:

Broadcrown Ltd

Airfield Industrial Estate, Hixon, Stafford, Staffs ST18 0PF
England

tel: +44 (0)1889 272200 fax: +44 (0)1889 271968

email: service@broadcrown.co.uk

www.broadcrown.com

Use of spare parts not approved by Broadcrown Ltd may invalidate the warranty.

Tax Invoice 00296054

MCG CRANES PLEASE PROVIDE ORDER NUMBER!
 PO Box 63
 Campbellfield Vic 3061

MCG CRANES PLEASE PROVIDE ORDER NUMBER!
 258 Mahoneys Road
 Thomastown Vic 3074

Date 31/08/2021
 Your No. 8903
 Terms Net 30 after EOM
 Rep Billal

QTY	ITEM NO.	DESCRIPTION	Unit Price	Total (Inc-GST)
2	SCMF31-931	31-931 TRUCK BATTERY	\$204.545	\$450.00

004

12 months warranty

Sale Amt.:	\$409.09
Freight:	\$0.00
GST:	\$40.91
Total Amt.:	\$450.00
Paid Today:	\$0.00

Name: _____ Signature: _____

Balance Due: \$450.00



258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8400
 Fax: 03 9462 3496
 Mob: 0499 624 624
 Email: accounts@mcgcranes.com

GENERATOR WORK ORDER

01205

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: <u>Yes</u> / No	REPAIR: <u>Yes</u> / No	COMPLETE: <u>Yes</u> / No
DATE: <u>10-08-21</u>	LOCATION: <u>Yard</u>		
MAKE:	MODEL: <u>BROADBANK</u>	HOURS: <u>8773</u>	
UNIT ID: <u>004</u>	ENGINE MODEL:	ENGINE SERIAL No.:	
JOB DESCRIPTION:			
<p>- Carry Out Service as Req - bad Gank - Clean Intercooler & Rad</p>			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil		<u>83</u> Litres	
Engine Oil Filter		✓	<u>P550949</u>
Air Filter		✓	<u>P613333</u>
Coolant		Litres	
Coolant Filter		✓	<u>P550866</u>
Check Belts	✓		
Check Engine Mounts			
Check Exhaust System	✓		
Check Battery	✓		
Grease	<u>N/A</u>		
Check for Oil Leaks	✓		
Tighten Hose Clamps	✓		
Check Hose Condition	✓		
<u>Fuel Filter</u>		✓	<u>P551047 / P55 2040</u>

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	Technician's Signature: <u>[Signature]</u>		Date: <u>27-08-21</u>
	NAME IN BLOCK LETTERS: <u>Jamir</u>		
	Customer's Signature:		Date:
	NAME IN BLOCK LETTERS:		

	MAKE: Broadcrown 2011	MODEL: 500kVA	SERIAL :571331
	Eng make: Cummins	Eng Model: QSX15-G8	Eng # 79476835
	AIR OUTER	RS4993	AF25708M (\$133.20) ✓
boathouse	FUEL		FS1040 (\$64.35) ✓
from 12.05.18	FUEL SEPARATOR		FS20402 (\$23.22) ✓
	WATER FILTER	BW5086	WF2126 (\$77.71) ✓
	ENG OIL - 80 ltrs		LF9070 (\$61.38) ✓
	BELTS	FAN: 3106099	ALT: 3100141

Hamilton Marino site

Joseph Rd , Footscray

Enter from Hopkins st

Contact: NATHAN

0421 224 799



The Trustee for Martin Ciceralo Group Business Trust ABN 56 600 457 088

258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8400
 Fax: 03 9462 3496
 Mob: 0499 624 624
 Email: accounts@mcgcranes.com

GENERATOR WORK ORDER

01105

MAINTENANCE REQUEST:	SERVICE: <input checked="" type="radio"/> Yes / No	REPAIR: Yes / <input checked="" type="radio"/> No	COMPLETE: <input checked="" type="radio"/> Yes / No
LOCATION:	HAMILTON MARINO SITE		
DATE:	MAKE: 6/11/19	MODEL: BROADCROWN	HOURS: 7958H
UNIT ID: GENSET 004	ENGINE MODEL: CUMMINS	ENGINE SERIAL No.:	3
JOB DESCRIPTION: SERVICE			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil	<input checked="" type="checkbox"/>	87 Litres	RECAL AROUND TOP OF TANK
Engine Oil Filter	<input checked="" type="checkbox"/>	87 LITRES	REAR ENGINE MOUNTS WORN
Air Filter	<input checked="" type="checkbox"/>		
Coolant	<input checked="" type="checkbox"/>	2 Litres	
Coolant Filter	<input checked="" type="checkbox"/>		
Check Belts	<input checked="" type="checkbox"/>		
Check Engine Mounts	<input checked="" type="checkbox"/>		
Check Exhaust System	<input checked="" type="checkbox"/>		
Check Battery	<input checked="" type="checkbox"/>		
Grease	<input checked="" type="checkbox"/>		
Check for Oil Leaks	<input checked="" type="checkbox"/>		
Tighten Hose Clamps	<input checked="" type="checkbox"/>		
Check Hose Condition	<input checked="" type="checkbox"/>		
FUEL FILTER	<input checked="" type="checkbox"/>		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	Technician's Signature: <i>[Signature]</i> Date: 6/11		
	NAME IN BLOCK LETTERS: JAKE		
	Customer's Signature: _____ Date: _____		
NAME IN BLOCK LETTERS: _____			

file

copy file

TAX INVOICE

MCG Cranes

Invoice Date
06 Nov 2019

Account Number

Invoice Number
INV-1753

Reference
GENSET 004

ABN
43 927 388 561



Diesel Mechanics Australia Pty Ltd
20 Norwich Avenue
Thomastown VIC 3074

ABN: 43 927 388 561
ACN: 615 180 704

Description	Quantity	Unit Price	GST	Amount
TS, Cummins Broadcast Generator 2011 / 7958hr's / Serial no GENSET 004 Serviced Generator onsite in Footscray and conducted safety inspection. Replaced engine oil, fuel and oil filters. Replaced air filter. Checked belts and checked for leaks. Adjusted clutch. Checked all levels and checked coolant glycol percentage 38% good.				
RECOMMENDATIONS: Diesel on top of fuel tank - appears to be from when it was filled up. Rear engine mounts - rubber coming out, requires replacement.	1.00	770.00	10%	770.00
BREAKDOWN OF COSTS: Labor \$660 2 litres coolant \$33 8 litres of engine oil \$77				
			Subtotal	700.00
			Total GST 10%	70.00
			Invoice Total AUD	770.00
			Total Net Payments AUD	0.00
			Amount Due AUD	770.00

Due Date: 22 Nov 2019

PAYMENT ADVICE

Via Mail to: Diesel Mechanics Australia Pty Ltd
20 Norwich Avenue
Thomastown VIC 3074

Direct Credit: Diesel Mechanics Australia Pty Ltd
BSB: 033 284
Account Number: 375365

Customer	MCG Cranes
Invoice Number	INV-1753
Amount Due	770.00
Due Date	22 Nov 2019
Amount Enclosed	

Enter the amount you are paying above

REPAIR SHEET

ADDRESS:

1st 19

DATE:

GENERATOR SERVICE

Unit Number	4	Unit Hours	7230 HRS
Location	FOOTSCRAY	Date	22/7/17

Task	Ok	Us	Changed	Notes
Oil Change			✓	
Oil Filter Change			✓	
Fuel Filter Change			✓	
Coolant Filter Change			✓	
Coolant Check	✓			
Radiator Check	✓			
Fuel System Check	✓			
Fan Belt Check	✓			
Air Cleaner Clean/Replace	✓		✓	
Hose Clamp Check	✓			
Hose Condition Check	✓			
Exhaust System Check	✓			
Intake System Check	✓			
Mounting and Bolt Check	✓			
Battery Check	✓			
Oil Leak Check	✓			
Check/Change Gbox Oil	N/A			

Notes

SIGNATURE	<i>[Signature]</i>	Date 22/7/17
CUSTOMER SIGNATURE		Date

workfile
copy

TAX INVOICE

MCG Cranes

Invoice Date
22 Jul 2019

Account Number

Invoice Number
INV-1555

Reference
GENSET 4

ABN
43 927 388 561



Diesel Mechanics Australia Pty Ltd
20 Norwich Avenue
Thomastown VIC 3074

ABN: 43 927 388 561
ACN: 615 180 704

Description	Quantity	Unit Price	GST	Amount
CAT Engine - Broadcrown Generator / 7230hr's / GENSET 4 Drove to Footscray, performed safety inspection & service. Replaced engine oil, fuel, air & oil filters. Checked coolant percentage 45% good. Checked belts, checked engine mounts & pipes + hoses. Checked battery terminals, ran & tested good. Drove back to workshop.	1.00	572.00	10%	572.00
Labor \$550 Consumables \$22				
			Subtotal	520.00
			Total GST 10%	52.00
			Invoice Total AUD	572.00
			Total Net Payments AUD	0.00
			Amount Due AUD	572.00

Due Date: 06 Aug 2019

PAYMENT ADVICE

Via Mail to: Diesel Mechanics Australia Pty Ltd
20 Norwich Avenue
Thomastown VIC 3074

Direct Credit: Diesel Mechanics Australia Pty Ltd
BSB: 033 284
Account Number: 375365

Customer MCG Cranes

Invoice Number INV-1555

Amount Due 572.00

Due Date 06 Aug 2019

Amount Enclosed

Enter the amount you are paying above

TAX INVOICE

MCG Cranes

Invoice Date
15 Apr 2019

Account Number

Invoice Number
INV-1384

Reference
Unit no 004

ABN
43 927 388 561



Diesel Mechanics Australia Pty Ltd
20 Norwich Avenue
Thomastown VIC 3074

ABN: 43 927 388 561
ACN: 615 180 704

Description	Quantity	Unit Price	GST	Amount
Generator / 6855hr's / Unit no 004 Drove to MCG depo, serviced generator, replaced engine oil, air, fuel & oil filters. Tightened battery terminals, checked all engine mounts, tightened / checked intercooler pipes & clamps. Removed covers washed out intercooler & radiator, washed down engine. Checked coolant percentage - 40%. Good. Drove back to workshop.				
Recommendations Noticed negative terminal for A/C power nut missing - informed Kerry - fitted new nut & washer.	1.00	407.00	10%	407.00
Breakdown of costs Labor \$385 Consumables \$22				
			Subtotal	370.00
			Total GST 10%	37.00
			Invoice Total AUD	407.00
			Total Net Payments AUD	0.00
			Amount Due AUD	407.00

Due Date: 08 May 2019

PAYMENT ADVICE

Via Mail to: Diesel Mechanics Australia Pty Ltd
20 Norwich Avenue
Thomastown VIC 3074

Direct Credit: Diesel Mechanics Australia Pty Ltd
BSB: 033 284
Account Number: 375365

Customer MCG Cranes

Invoice Number INV-1384

Amount Due 407.00

Due Date 08 May 2019

Amount Enclosed

Enter the amount you are paying above

file

Jewl Transport Repairs Pty Ltd

ABN 20 158 927 185
Phone: 0424-789-126 Fax: 9744-1602
Email: jewltrans01@yahoo.com.au

INVOICE

Invoice No: 13267
Date: 14/03/2018

MCG CRANES

VEHICLE	REGISTRATION	KILOMETERS	VIN NUMBER
GENSET	DK 004		

DESCRIPTION

QTY

AMOUNT

GST

TOTAL

O.S.C GEN SET NOT STARTING, CHECKED AND
FOUND NOT GETTING SIGNAL TO STARTER,
JUMP POWER TO START NEEDS FURTHER
ATTENTION. RETURNED NEXT MORNING TO TO
JUMP POWER TO START AGAIN

LABOUR

\$200.00

\$20.00

\$220.00

Total excluding GST \$200.00
GST \$20.00
Total including GST \$220.00

Invoice Balance \$220.00

ALL PAYMENTS ARE TO BE MADE WITHIN 7 DAYS OF INVOICE DATE
CHEQUES TO BE SENT TO PO BOX 2148 SUNBURY 3429
OR DIRECT DEPOSIT TO JEWL TRANSPORT REPAIRS
BSB: 063-620 ACC:10701650

THANK-YOU FOR USING JEWL TRANSPORT REPAIRS



Cummins South Pacific Pty. Ltd.

ABN NO. 42006332949

Laverton
191-195 Boundary Road
Laverton North Vic 3026
Ph: 03 8368 0800
Fax: 03 9360 0438

WORKSHOP TAX INVOICE

INVOICE NUMBER 8125843
INVOICE DATE 23/03/19
PAGE 1

Invoice To
Account Number 322SERV
CASH SALES SERVICE - LAVERTON
LAVERTON
SERVICE CASH SALES

Customer
MCG CRANES
258 MAHONEY'S ROAD
THOMASTOWN
VIC
3074

Engine Model:	SIGNATURE/SX/QSX	Eng No:	79476835	Equip Make:	GEN SET
FleetNo:		Reg No:	C550D5	Cust Ord NO:	
Date In Service:		KLMS:		HRS:	5
Repair Date:	14/03/19	Chassis NO:	MCG Cranes	Currency:	AUD
C.O.No.	6363655	Work ordNo.	2509838	Facility	322

Job description

Investigate fail to start issue
QSX15 | 79476835

Cause: Faulty pilot relay

Coverage: Retai;

Correction:

- Travel to pick up parts
- Travel to site
- Perform JSA
- Locate genset at battery isolator and E stop
- Remove old faulty pilot relay and wiring
- Replace new pilot relay and connect wiring
- Unisolate battery isolator and remove E stop
- Start and run genset to test, OK
- Paperwork, clean up and pack up

By CLK

Description	Operation	Unit price	Qty	Extension
-------------	-----------	------------	-----	-----------

Labour

7 4.00

Subcontract

5162590 visa - parts 1

SUB-TOTAL 1000.00

G.S.T 100.00

INVOICE TOTAL 1100.00

TAX INVOICE

MCG Cranes

Invoice Date
03 Sep 2018

Account Number

Invoice Number
INV-1037

Reference
UNIT NO 004

ABN
43 927 388 561



Diesel Mechanics Australia Pty Ltd
20 Norwich Avenue
Thomastown VIC 3074

ABN: 43 927 388 561
ACN: 615 180 704

Description	Quantity	Unit Price	GST	Amount
-------------	----------	------------	-----	--------

Cummins QSX15-G8 Generator 2011 / 5538hr's / Serial no: E79476835
/ Unit no 004

Drove to Footscray, serviced engine, checked/tightened engine mounts & conducted safety inspection. Replaced engine oil, fuel & oil filters. Checked air filter, checked belts, checked for leaks, checked all levels & checked coolant glycol percentage 35%. Ran & tested unit, Good. Drove back to workshop.

Recommendations

Overdue for service (Sticker 5,076)

1.00

600.00

10%

600.00

Found low oil level in engine

Air filter not supplied - needs to be replaced

Breakdown of costs

Labour \$550

2 litres coolant \$22

3 litres Diesel \$6

Consumables \$22

Subtotal 545.45

Total GST 10% 54.55

Invoice Total AUD 600.00

Total Net Payments AUD 0.00

Amount Due AUD 600.00

Due Date: 18 Sep 2018

PAYMENT ADVICE

Customer MCG Cranes

Invoice Number INV-1037

Amount Due 600.00

Due Date 18 Sep 2018

Amount Enclosed

Enter the amount you are paying above

TAX INVOICE

MCG Cranes

Invoice Date
03 May 2018

Account Number

Invoice Number
INV-0815

Reference
Genset #004


ABN
43 927 388 561



Diesel Mechanics Australia Pty Ltd
20 Norwich Avenue
Thomastown VIC 3074

ABN: 43 927 388 561
ACN: 615 180 704

Description	Quantity	Unit Price	GST	Amount
TS, Cummins QSX15-G8 Generator 2011 / 4826hr's / Generator Ref no: AO287496 / Job ref # 004 Drove to Thomastown & Serviced generator and conducted safety inspection. Replaced engine oil, fuel and oil filters. Air filter on order to be replaced. Checked belts. Checked all levels and checked coolant glycol percentage 35%. Removed back cover & radiator covers, Washed coolers & radiator also washed inside. Replaced both drive belts as they were cracked. Refitted shroud & covers. Drove back to workshop.				



NO JOB TOO BIG OR SMALL

- Mobile Diesel Repairs
- Truck Tractor Trailer Servicing and Repairs
- Compressor and Generator Repairs

The Mobile Truck Doctor

pty ltd

Phone: 0455460003

mobiletruckdoctor@gmail.com

ABN: 612 766 471

Invoice: IV00000000177

Tax Invoice

Invoice date: 28/02/2018

Bill to:
 MCG Cranes
 PO Box 1087
 Altona Gate Vic 3025

Due:
 28/02/2018

ITEM	DESCRIPTION	UNITS	UNIT PRICE (ex GST)	TAX TYPE	AMOUNT (ex GST)
1 24/2/18	Onsite generator servicing of gen 11,23,4 travel to site check over gensets replace filters and oil check for any loose bolts worn engine mounts fanbelts	Hrs			
1	Travel to little Lonsdale Watpac site check generator for shutting down due to over heating went right over it found all ok ran generator whilst lift was operating wouldn't shut down	Hrs			
10	Consumables	Qty			

Notes

How to pay
 Due 28/02/2018

Bank Deposit

Pay using EFT:

Bank: ANZ

Name: The Mobile Truck

Doctor pty ltd

BSB: 013299

AC#: 300437191

Ref#: IV00000000177

Sonny Mobile Mechanic

ABN 84 898 353 205

REPAIR REPORT

71 Girgarre Street, Broadmeadows VIC 3047 Tel: 0412 623 007

5576

CUSTOMER

Name: M. C. G. CRANES. Order No.:

Address: 15 DAVID ST. RICHMOND.

(charged HMB)

Contact: Mobile:

Plant ID	Make	Model	Serial No.	Kilometres	Upper Deck Hrs	Lower Deck Hrs
<u>004</u>	<u>Cummins</u>	<u>CE3255666CC</u> <u>-4-</u>	<u>0385476</u>		<u>4187</u>	

Date	Ex Depot	On Site	Meal Break	Ex Site	Depot	Total Hours
<u>20/12/17</u>	<u>11:30</u>		<u>NO</u>	<u>5:30</u>	<u>8</u>	

Col. Maint / Fault: USING part DIRTY. Block up fuel filter. Long smoking
ASKING FOR WAITING AFTER lunch until 5:30 pm

Details of Repair completed: REPAIR AS REQUIRED AND inspection
REPLACE NEW FILTER. (go out pick up part. at
Quinn's LAVERTON. COME BACK part in on

Parts Used:

Part Description	Unit	Quantity
<u>FUEL FOR Separator</u>	<u>FS20402</u>	<u>1</u>

Additional Comments / Information: Will change fuel filter in January

All service and repair work and the provision of parts is undertaken strictly in accordance with Sonny Mobile Mechanic's Terms and Conditions of Trading.
 By signing below, the customer agrees that the work carried out, the times recorded and the parts supplied are to the customer's satisfaction.
 All service and repair work and the provision of parts will be chargeable at the current rates

Client / Agent:
 Name: Helen McCarthy LRPO
 Date: 20/12/17
 Signature: [Signature]

Mechanic:
 Name: Sonny Dault
 Date: 20/12/17
 Signature: [Signature]

Sonny Mobile Mechanic

ABN 84 898 353 205

71 Girgarre Street, Broadmeadows VIC 3047 Tel: 0412 623 007

REPAIR REPORT

5551

CUSTOMER

Name: MCG CRANES Order No.:
Address: 803 DANDENONG RD MALVERN EAST

Contact: Mobile

Plant ID	Make	Model	Serial No.	Kilometres	Upper Deck Hrs	Lower Deck Hrs
<u>GANSBT 004</u>	<u>BROADCROWN</u>	<u>500KVA</u>	<u>571331</u>		<u>3635</u>	

Date	Ex Depot	On Site	Meal Break	Ex Site	Depot	Total Hours
<u>04/09/17</u>	<u>2:30 pm</u>			<u>6:30 pm</u>		<u>4</u>
				<u>TRAVEL TIME.</u>		

Complaint / Fault:

Details of Repair completed: SERVICE AS REQUIRED.
CHANGE OIL, ^{80LIT.} OIL FILTER, FUEL FILTER. AIR FILTER CLEANED.
CHECK COOLANT, BATTERY CCA 970 - 9.65 CHARGE 27.5 VOLTS.

Parts Used:

Part Description	Unit	Quantity
<u>AIR FILTER</u>	<u>AF25708M</u>	<u>1</u>
<u>FUEL FILTER</u>	<u>FS20402</u>	<u>2</u>
<u>OIL FILTER</u>	<u>FS1040</u>	<u>1</u>
	<u>LF9070</u>	<u>1</u>

Additional Comments / Information:

All service and repair work and the provision of parts is undertaken strictly in accordance with Sonny Mobile Mechanic's Terms and Conditions of Trading.
By signing below, the customer agrees that the work carried out, the times recorded and the parts supplied are to the customer's satisfaction.
All service and repair work and the provision of parts will be chargeable at the current rates

Client / Agent: Name: Date: Signature:
Mechanic: Name: SONNY DANU Date: 04/09/17 Signature: [Signature]

Original

TAX INVOICE* / STATEMENT*

(* DELETE AS APPROPRIATE)

76

DATE 21-03-17

TO TO MUCK MCG CRANES
GENSET-00410015

ABN (of Recipient) _____ ORDER NO. _____

FROM SONNY BABIL MECHANIC

ABN (of Supplier) _____

QTY	DESCRIPTION	PRICE	G.S.T.	TOTAL
①	Drop off to Campbellfield Radiator Repair.			
②	Drop off Eppin Radiator to repair NW: Good. Bring back			
③	Call out to 803 DADENONG RD. EAST. MVERN. CHECK. INSPECTION AND REPLACE AIR FILTER REPLACE RADIATOR CAP.			
	LAB + PART			380 00

SON DANG
 71 Sydney Street Brookwood VIC 3017
 0412 623 007
 ABN: 84898353205

TOTAL INCLUSIVE OF G.S.T.

Total includes G.S.T. of



HEAD OFFICE & Melbourne Depot:
99 Fitzgerald Road, North Laverton,
3026.
PO Box 444, Altona North, 3025.

Geelong Depot:
Cnr Seabeach Pde & Madden Ave, North Shore, 3214.
PO Box 180, North Shore, 3214.
Phone: (03) 5275 8595

SERVICE REPORT

5417.

CUSTOMER

Name: MCG Cranes
Address: Mahoneys rd
Thomastown.
Contact: Tony.

Docket No.
S 500507
Order No.

Plant ID	Make	Model	Serial Number	Kilometres	Upper Deck Hours	Lower Deck Hours
084	Broderick	—	✓	—	1667	—

Date	Ex Depot	On Site	Meal Break	Ex Site	Depot	Total Hours
06/07/16	—	13:30	—	17:30	—	4

- ENGINE:**
- Check/Change oil & filters
 - Check coolant level & condition
 - Check belt tension & condition
 - Check pulleys
 - Check/Change air filter
 - Check/Change fuel filters

- BOOM:**
- Grease boom if required
 - Visual inspection for cracks
 - Check rope rollers/sheaves
 - Check anti 2 block switch
 - Check all wiring plugs
 - Check luff cylinders
 - Check wear pad adjustments

- WINCH:**
- Check/Change oil
 - Check pawl if fitted
 - Check rope lay on drum
 - Check rope condition
 - Check wiring winch

- CARRIER:**
- Check all uni/slip joints
 - Grease driveline
 - Check all susp components
 - Check all linkages
 - Check centre bearing
 - Check all mounts & bushes
 - Check all hoses for rubbing
 - Check all wiring harness
 - Check chassis for cracks
 - Check tyre condition
 - Check wheel bearing play
 - Check steering components
 - Check brake linings & adjustment
 - Check brake operation
 - Check battery condition
 - Grease all nipples

- CABIN:**
- Check all lights
 - Check dash lights
 - Check heater & A/C
 - Check horn operation
 - Check seat condition
 - Check seatbelt
 - Check wipers & washer

- OILS:**
- Check/Change diff oil
 - Check/Change planetary oil
 - Check/Change transmission oil & filter
 - Check/Change transfer case oil
 - Check brake fluid

COMMENTS:

- All service and repair work and the provision of parts is undertaken strictly in accordance with Quinlan Plant Services Pty Ltd terms and conditions of trading.
- By signing below, the customer agrees that the work carried out, the times recorded and the parts supplied are to the customer's satisfaction.
- All service and repair work and the provision of parts will be chargeable at the current rates.

Client or Agent:
Name: Tony
Signature: [Signature]
Date: 6-7-16

Mechanic:
Name: Tim LeMarshall
Signature: [Signature]
Date: 06/07/16

SERVICE REPORT

CUSTOMER

Name: MCH cranes
Address: 188 whitehorse road Balwyn
Contact: _____

Docket No.
S 500851
Order No.

Plant ID	Make	Model	Serial Number	Kilometres	Upper Deck Hours	Lower Deck Hours
<u>204</u>	<u>Broadcrann</u>	<u>BCCSS0-SDE2</u>	<u>571311</u>			<u>643</u>

Date	Ex Depot	On Site	Meal Break	Ex Site	Depot	Total Hours
<u>7:00 am</u>		<u>7:00 am</u>		<u>10:15 am</u>	<u>11:00 am</u>	<u>4 hrs</u>
<u>23/12/15</u>						

- ENGINE:**
- Check/Change oil & filters
 - Check coolant level & condition
 - Check belt tension & condition
 - Check pulleys
 - Check/Change air filter
 - Check/Change fuel filters

- BOOM:**
- Grease boom if required
 - Visual inspection for cracks
 - Check rope rollers/sheaves
 - Check anti 2 block switch
 - Check all wiring plugs
 - Check luff cylinders
 - Check wear pad adjustments

- WINCH:**
- Check/Change oil
 - Check pawl if fitted
 - Check rope lay on drum
 - Check rope condition
 - Check wiring winch

- CARRIER:**
- Check all uni/slip joints
 - Grease driveline
 - Check all susp components
 - Check all linkages
 - Check centre bearing
 - Check all mounts & bushes
 - Check all hoses for rubbing
 - Check all wiring harness
 - Check chassis for cracks
 - Check tyre condition
 - Check wheel bearing play
 - Check steering components
 - Check brake linings & adjustment
 - Check brake operation
 - Check battery condition
 - Grease all nipples

- CABIN:**
- Check all lights
 - Check dash lights
 - Check heater & A/C
 - Check horn operation
 - Check seat condition
 - Check seatbelt
 - Check wipers & washer

- OILS:**
- Check/Change diff oil
 - Check/Change planetary oil
 - Check/Change transmission oil & filter
 - Check/Change transfer case oil
 - Check brake fluid

COMMENTS:

- All service and repair work and the provision of parts is undertaken strictly in accordance with Quinlan Plant Services Pty Ltd terms and conditions of trading.
- By signing below, the customer agrees that the work carried out, the times recorded and the parts supplied are to the customer's satisfaction.
- All service and repair work and the provision of parts will be chargeable at the current rates.

Client or Agent:
Name: No Representative
Signature: Available
Date: Jan 2017

Mechanic:
Name: Nathan Allman
Signature: Nathan
Date: 23/12/15



The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

Hammerhead Luffer Mobile Crawler Generator (Tick Type being Serviced)

Service Technician DARREN
 Crane Serial Number BROADEROWN #004
 Site MCG CRANES YARD
 Date 06.08.2015

PO Box 1087 Altona Gate 3025
 Tel: 03 9314 9992
 Fax: 03 9314 9952
 Mob: 0403 988 793
 Email: glenn@mcgcranes.com
SERVICE REGISTER

TOWER CRANE		SERVICED @ 1.1 hrs	
Service Procedures	Comments / Action	OK	Comments / Action
Check Bolted Connection Feet	Pig's Ears, Pulleys, Temp Pendant Bridle secure		
Tower Bolts to Feet	Trolley Sheaves and Wheels checked for Noise and Slop		
Tower Bolts check c/w side whole way up Tower	Jib Idler Sheaves checked		
Supply Cable protected 2m up from base of Crane	Hoist Sheaves at Jib, Ham Bone, Swivel, Wire Cable,		
Ladders and Platforms checked	4 Fall Bracket checked		
Highest Tie inspected, Bolts inspected, Welds and Wedges checked	Bridle for Fixed Pendants checked		
Supply Cable and Sock inspected at Slew Ring	Top of A-Frame checked, all Sheaves checked and greased		
Slew Ring inspected for Noise, Slop, Grease	A-Frame Hoist Fleet Angle checked for Grease and Movement		
Slip Ring and Junction Box inspected	Monkey inspected		
Cab Tray connection Bolts and Pins checked	Hook inspected and Swivel greased		
Cab Interior Clean, Logbooks, Grease Gun, Grease Cartridges, Operators and Electrical Manual	FURTHER INSPECTION CARRIED OUT		
Check Controls, Luff / Trolley limits, Load moment, Hoist limits, Horn, Slew Brake, Free Slew etc.	1. FUEL ENGINE SERVICE, REPLACE ALL FILTERS		
Connecting Pin / Bolt connection between Slew Ring and A-Frame Butt or Cathead	2. + ENGINE OIL, FIT OIL TANK & OIL TOP UP		
Connecting Pins to Counter Jib / Machine Deck	3. SYSTEM, FIT NEW WATER SEPARATOR SYSTEM		
Hoist Motor, Luff Motor and Trolley Motor connected to crane correctly	4. TOP UP WITH COOLANT, FIT NEW BATTERYS +		
Luff Motor checked, Oil, Secondary Brake checked, Cables checked, condition of Rope	5. WIRING TO START & ISOLATER, MAKE NEW FUEL PICKUP & GENERATOR INSPECTION		
Hoist Motor checked, Oil, Secondary Brake checked, Cables checked, condition of Rope	6. PANICLE FRAME, MAKE NEW FUEL PICKUP & OIL AND WATER LEVELS		
Trolley Motor checked, Oil, Brake checked, Cables checked, condition of Rope	SUPPLY CABLE CHECKED		
Counter weights sitting correctly, Basket checked	EXHAUST EMISSIONS OK		
Back Stays and A-Framed Pendants checked	AIR FILTER, FUEL FILTER CHECKED / CHANGED		
Cables run correctly and secure	ITEMS NEEDING ATTENTION NEXT SERVICE		
All connecting Split Pins checked	1. FUEL FILTER		
Sign checked if installed	2. AIR FILTER		
Jib connection Pin / Pins checked	3. COOLANT FILTER		
Jib connection Bolts and Pins checked	4. OIL FILTER		
Monkey and Fixed Pendants inspected	5. BOLT ENGINE OIL LOW-HO		
	6.		
	Technician Signature <u>D. Babianis</u>		



M-Power Generators Pty. Ltd.
 ABN 15 660 795 068
 258 Mahoneys Road Thomastown Vic 3074
 Tel: 03 9462 8484
 Email: info@m-powergenerators.com.au


GENERATOR WORK ORDER

0719

The Trustee for Martin Cicerale Group Business Trust ABN 56 600 457 088

MAINTENANCE REQUEST:	SERVICE: Yes / No	REPAIR: Yes / No	COMPLETE: Yes / No
DATE: 07-05-26	LOCATION: Yard		
MAKE: Broadsword	MODEL:	HOURS: 11022	
UNIT ID: m-31-500/1	ENGINE MODEL: Cummins	ENGINE SERIAL No.:	
JOB DESCRIPTION: - Carry out Pre sale check over found to be operating as req			

Check	OK	Changed	Part No. / Supplier / Notes....
Engine Oil	/	Litres	
Engine Oil Filter	/		
Air Filter	/		
Coolant	/	Litres	
Coolant Filter	/		
Check Belts	/		
Check Engine Mounts	/		
Check Exhaust System	/		
Check Battery	/		
Fuel Filter	/		
Check for Oil Leaks	/		
Tighten Hose Clamps	/		
Check Hose Condition	/		

Parts / Work Required :	ARRIVE SITE:	LEAVE SITE:	TRAVEL EACH WAY:
	Technician's Signature: 		Date: 7-6-26
	NAME IN BLOCK LETTERS: Jamie		
	Customer's Signature:		Date:
	NAME IN BLOCK LETTERS:		