



Vehicle History Summary

Fleet #	XQ78OW
Registration	XQ78OW
Make	Mercedes
Model	Actros
VIN / Chassis #	WDB96342420324204
Build Date	2020

Date	Reading / Units	Type / Repairer Notes	Repairer
17/07/2025		axle 1, mudguard R-2547 Axle 2 - driver side new mudguard installed , Axle 1 axle new tyre installed	workshop
14/07/2025		new lights R-2546 new cover lights installed.	workshop
28/06/2025		mudflap, mudguard, reflector palte R-2548 Passenger side mudguard installed, Passenger side new mudflap installed , new reflector plate installed	workshop
28/05/2025		new tyre T-779 Fixed	D&G Mechanic
20/04/2025		Panel Repairs R-2526 Fixed	D&G Mechanic
20/04/2025		worn tread R-2525 Fixed	D&G Mechanic
11/04/2025		mirror R-2207 Fixed	D&G Mechanic
23/02/2025		interior clean R-1922 Fixed	D&G Mechanic
13/02/2025		mudguard R-1827 MUDGUARD RERA BAR REPAIR	Gora Truck & Trailer
13/02/2025		Tyre Repair T-678 FLAT TYRE REPAIR	Gora Truck & Trailer
11/02/2025		headlight bulb R-1802 HEADLIGHT BULB REPLACE	Gora Truck & Trailer
11/02/2025		air dryer R-1800 AIR DRYER CLEAN LABOUR	Gora Truck & Trailer
06/02/2025		bulbs R-1764 Electrical System light out on dash Fog light impacted, not covered under best basic Replaced parker bulb, cleared faults	Daimler
24/01/2025	833,529 kms	B - B SERVICE S-1135	

Date	Reading / Units	Type / Repairer Notes	Repairer
		BASIC SERVICE KM 833529 SERVICE KIT (CUSTOMER) OIL FILTER REPLACE FUEL FILTER REPLACE FUEL/WATER SEPEARTOR FILTER REPLACE ENGINE OIL REPLACE CLEAN AIR FILTER CHECK AIR DRYER FILETR CHECK ALL MUDGUARDS AND BRACKETS CHECK ALL TYRE PRESSURE CHECK TURNABLE FOR ANY PLAY AND GREASED UP GREASE KING PINS, JACK SHAFT INSPECTED ALL BUSHES ANY EXCESSIVE PLAY CHECK WASHER FLUID CHECK TENSIONS ON ALL TANK STRAPS 1.00 300.00 10% 300.00 ENGINE OIL 10W 40 40.00 6.50 10% 260.00 HEAD LIGHT BULB LEFT SIDE REPLACE RIGHT SIDE HIGH BEAM REPLACE HEADLIGH ALLIGNMENT SETTING 1.00 100.00 10% 100.00 HEDLIGHT BULB HIGH BEAM 1.00 12.00 10% 12.00 INJECTER SEAL LEAK NO 3,4,5	
20/01/2025		fuel tank R-1695 FUEL TANK MIDDLE ANGLE CHANGE NUTBOLT MISSING FITTED BACK AT 8:PM	Gora Truck & Trailer
15/01/2025		Panel Repairs R-2230 Fixed	D&G Mechanic
15/01/2025		roller bearing R-1656 ROLLER THRUST BEARING TAPERED ROLLER BEARING HANDLING FEE	Daimler
15/01/2025		rolling bearing R-1654 ROLLER THRUST BEARING - MISSING TAPERED ROLLER BEARING	Daimler
14/01/2025		axle brake pad R-1645 4 BRAKE DISK 2 BRAKE PAD SET CUSTOMERKM 789717 5 LT DIF OIL 2ND AXLE BOTH SIDE BRAKE DISK REPLACE 3RD AXLE BOTH SIDE BRASKE BOOSTER REPLACE 2ND AXLE BRAKE PAD REPLACE 3RD AXLE BRAKE PAD REPLACE	Gora Truck & Trailer
13/01/2025		adblue filter R-1844 ADBLUE FILTER AND RUBBER CAP KIT ADBLUE FILTER REPLACE WATER PUMP NEEDS TO REPLACE	Gora Truck & Trailer
06/12/2024		Registration O-382	TMR - 32246
16/11/2024		beam light, headlight, park light R-1529 2 PARK LIGHT 2 HEAD LIGHT 1 BEAM LIGHT	Gora Truck & Trailer
17/09/2024	786,186 kms	REPLACE T-259 Remove, Strip & Refit front axle drive tyres.	D&G Mechanic
04/09/2024		Registration O-297	TMR - 32246
26/08/2024	775,673 kms	B - B SERVICE S-924 B Service as per attached Service Sheet.	D&G Mechanic
24/08/2024	775,673 kms	Wheel Alignment R-1438 Wheel Alignment on old tyres + road test	D&G Mechanic
10/08/2024	771,758 kms	air filter, Axle, Wheel Nut R-1385 Bring into Workshop & Set up for tyre Replacement - Remove & Replace 4 x 11R Drive Tyres on 3rd Axle. Refit & torque Wheel Nuts. Remove left Rear Damaged Mudguard & Replace with new. Attach scan tool & clear Air Filter maintenance light. Filter replaced last week.	D&G Mechanic
10/07/2024	760,390 kms	tread bolts R-1250 Bring into W/S. Remove RH Lower Step. Fit new step. Modify to gain access to Top Step tread bolts to tighten.	D&G Mechanic
09/07/2024	760,390 kms	Repair, Tyres T-186 Remove LH Front due to leak. Found value U/S. Replaced both steer tyres due to Non Matching & Leak in LH Front.	D&G Mechanic
05/06/2024		Registration O-188	TMR - 32246
23/05/2024	745,530 kms	Headlight bulb R-1109 Replace RH Headlight Bulb	D&G Mechanic
29/04/2024	733,056 kms	Brake pads R-1038	D&G Mechanic

Date	Reading / Units	Type / Repairer Notes	Repairer
		Bring into workshop, Jack up and remove wheels from center axle, remove brake Pads & fit new. Adjust and reassemble. Jack up front axle, remove wheels - remove brake pads and fit new pads. Adjust and re fit wheels and lower. Re-set Brake pad wear on laptop. Test Drive and park up top.	
29/04/2024	733,056 kms	mudguard R-1041 Replace 2 x Mudguards Modify Bullbar sides.	D&G Mechanic
26/04/2024		mudguards R-1032 Mudguard rear bar repair.	Gora Truck & Trailer
24/04/2024		headlight R-683 BEAU RAISED WITH AJAY - AJAY SPOKE TO GORA TRUCK & TRAILERS TO TAKE A LOOK AT HEADLIGHT DRIVER IS DOING CHANGEOVER AT KEMPSEY 5/12/2023 AND WONT BE BACK UNTIL 6/12/2023 AND DRIVING AT NIGHT REQUIRES THE HEADLIGHT TO BE FIXED	Gora Truck & Trailer
24/04/2024		Flat Tyre T-101 Flat Tyre Repair	Gora Truck & Trailer
24/04/2024	733,056 kms	Brakes R-1027 Took XQ31WK and swapped assets with the driver. Cleared debris around brake caliper on right rear and returned to workshop. Prep for brake change, rear brakes 18%, remaining brakes 60-80% Fitted new brake pads & reset rear axle on laptop.	D&G Mechanic
02/04/2024	715,033 kms	B - B SERVICE S-738 B Service as per attached Service Sheet	D&G Mechanic
22/03/2024	695,033 kms	Flat Tyre T-76 Jack up Axle, rear left remove tyre and change valve, pump up and refit.	D&G Mechanic
05/03/2024		Registration O-132	TMR - 32246
04/12/2023		Registration O-45	
10/11/2023		tyres R-580 DRIVER PARMINDER - GOT TYRES REPLACED AND WAS PAID BY INHOUSE ACCOUNTANT	TYRE RIGHT
06/11/2023	434,706 kms	accident damage, Lights, mudguards, seat R-388 "RH Foglight Broken - Ordered New Assembly Both Fuel Caps Damages - Replaced with 2 from Stock. RH Tank Touching Guard - Loosened Strap, Nuts, Move Tank towards exhaust, Tighten strap nuts. Repaired electrical 7 Pin Plug. inspect turntable."	
30/10/2023	631,631 kms	REPAIRS R-546 VEHICLE REPAIRS AS PER ATTACHED VEHICLE REPAIR SHEET	D&G Mechanic
13/09/2023	602,066 kms	Repairs R-376 SERVICE DUE - REPLACED BOTH BATTERIES - 2 XMF200L	D&G Mechanic
10/08/2023	584,222 kms	fuel tank R-291 Repaired with filler , refitted tank, lines and adjusted straps. Replaced left hand head light globe.	DG Mechanic
22/07/2023		Lights R-238 Will require new taillight	robert parkinson
25/03/2023		coolant R-208 Filled Coolant	DG Mechanic
27/01/2023	464,000 kms	B - Basic Service S-445 service completed	Workshop
30/09/2022	302,519 kms 12 hrs	Fault Report I-15	
07/09/2022	345,007 kms	B - B SERVICE S-147	Daimler

Date	Reading / Units	Type / Repairer Notes	Repairer
we will keep record from now			
30/06/2022	300,842 kms 12 hrs	Fault Report I-12	
04/05/2022	160,000 kms	B - B SERVICE S-146 Don't know, we will keep record from now	Daimler
31/01/2022	1 kms	tank lights R-182	
23/11/2021		C - C SERVICE S-120	Daimler
19/08/2021	120,607 kms	B - B SERVICE S-119 B Service	Daimler
15/07/2021	82,438 kms	A S-86 Service B	Daimler
19/04/2021	40,038 kms	B - B SERVICE S-79	mercedes
21/12/2020		Turn Table Lock R-35 Fit turn table lock	Diesel Spec Mechanical

Signed: _____

Name: _____

Date: _____