



Commercial Vehicle Inspection Report

PUP

Decal Number: PY28492
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21727432

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: BENNETT, NOEL DAVID / 202370
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Apr-09 10:45 AM MST
INSP. COMPLETE: 2026-Apr-09 11:45 AM MST

VEHICLE JUR: British Columbia
PLATE #: 78287U
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2008
MAKE: LANGFAB
MODEL:
REGI: 03477357
UNIT/FLEET#:
BODY STYLE: Pup Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2L9PPA6C38S014173
OWNER/LESSEE NAME: Uujo Contracting LTD , Uujo Contracting LTD
ADDRESS: PO BOX 247
Fort St John, British Columbia
V1J6W7, Canada

E06-3

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) #2 Right brake and drum
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) #2 Left inside rock drilled
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Repaired (same day) Safety Chains Worn
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	37	34	6	6	7	9	
2	Clamp	30	Automatic	34	34	10	10	11	10	
3	Clamp	30	Automatic	38	38	12	13	9	11	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	62	Lining (Shoe)	12	12	Drum		
2	75	90	Lining (Shoe)	10	7	Drum		
3	30	32	Lining (Shoe)	18	18	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: BENNETT, NOEL DAVID

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-09 12:57 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

4/9/2026 12:57:36 PM MST