



BRITISH  
COLUMBIA

# Commercial Vehicle Inspection Report

Decal Number: GC59644  
Decal Expiry Date: 2025-Dec-31  
Inspection Number: 21388517

Inspection Result:

**PASS**

FACILITY: CULLEN DIESEL POWER LTD. / S16600  
INSPECTOR: BELLAMY, BRODY JON-HENRY / 201409  
WORK ORDER #: 9436  
INSP. TYPE: Complete  
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
INSP. REASON: Semi-annual  
INSP. START: 2025-Jun-12 12:44 PM PDT  
INSP. COMPLETE: 2025-Jun-12 01:44 PM PDT

VEHICLE JUR: British Columbia  
PLATE #: KJ5999  
LICENCED GVW(kg): 44000  
VEHICLE YEAR: 2005  
MAKE: FREIGHTLIN  
MODEL:  
REGI: 02951795  
UNIT/FLEET#: HT129  
BODY STYLE: Dump Truck  
ODOMETER: 29664 KM  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE: Diesel  
VIN: 1FVHALCK85DV06615  
OWNER/LESSEE NAME: TRANSPORT L, LITTLE MOUNTAIN  
ADDRESS: 25-1343 ALBERNI HWY  
Parksville, British Columbia  
V9P2B9, Canada  
**Unit #129**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day)
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	32	32
2	Clamp	30	Automatic	35	34
3	Clamp	30	Automatic	36	32

Comment:

## Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
11.1			11.9	✓
9.5	7.9	8.7	9.5	
7.9	4.8	3.2	5.6	

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	80	70
2	90	75
3	95	35

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	16
Lining (Shoe)	14	16
Lining (Shoe)	13	21

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. NEW DRUM 3R

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: BELLAMY, BRODY JON-HENRY

Road Test Date:  
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-12 01:45 PM PDT.  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/12/2025 1:45:42 PM PDT