



Commercial Vehicle Inspection Report

Decal Number: GN51751
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21934187

Inspection Result:
PASS

FACILITY: JOHNSON RADIATOR SERVICES LTD. / S20512
INSPECTOR: GILOWSKI, TRAVIS GORDON / 200472
WORK ORDER #: 232730
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Sep-24 09:00 AM -07
INSP. COMPLETE: 2026-Sep-28 06:20 AM -07

E08-4

VEHICLE JUR: British Columbia
PLATE #: 81393K
REGI: 12732064
UNIT/FLEET#: 306
VIN: 2F9FHL130K1101529
OWNER/LESSEE NAME: STONE CREEK VENTURES LTD, STONE
LICENCED GVW(kg): 0
VEHICLE YEAR: 2019
MAKE: FREFLYT
MODEL:
BODY STYLE: LOGGING TRAILER
ADDRESS: 6528 WILDMARE SUB, PO BOX 636
Chetwynd, British Columbia
V0C1J0, Canada
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	40	40
2	Clamp	30	Automatic	40	40
3	Clamp	30	Automatic	40	40

Comment:

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	40	11	10	11	12	
2	Clamp	30	Automatic	40	40	10	8	11	14	
3	Clamp	30	Automatic	40	40	7	8	10	7	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	30	20
2	60	65
3	65	60

Comment:

Brake Lining/Pad (mm)

Axles	Left	Right	Lining/Pad	Left	Right
1	30	20	Lining (Shoe)	19	19
2	60	65	Lining (Shoe)	14	12
3	65	60	Lining (Shoe)	14	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	20	Lining (Shoe)	19	19	Drum		
2	60	65	Lining (Shoe)	14	12	Drum		
3	65	60	Lining (Shoe)	14	13	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: GILOWSKI, TRAVIS GORDON

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Sep-28 06:38 AM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

9/28/2026 6:38:13 AM -07