



Commercial Vehicle Inspection Report

Decal Number: GN75913
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21788796

E60-3
Inspection Result:
PASS

FACILITY: L M DIESELS TRUCK & TRAILER REPAIR LTD. / S14470
INSPECTOR: SINGH, RAVINDERPAL / 202620
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-May-26 09:14 AM PDT
INSP. COMPLETE: 2026-May-26 11:00 AM PDT

VEHICLE JUR: British Columbia
PLATE #: 98269K
REGI: 14641965
UNIT/FLEET#: VIN: 2L9PPA6C7RS014291
OWNER/LESSEE NAME: CLEAN ENERGY PRODUCTION CORP.,
LICENCED GVW(kg): 0
VEHICLE YEAR: 2024
MAKE: LANGFAB
MODEL: BODY STYLE: Dump Trailer
ADDRESS: 201-33832 SOUTH FRASER WAY
Abbotsford, British Columbia
V2S 2C5, Canada
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) BRAKES ADJUSTED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	36
2	Clamp	30	Automatic	37	36
3	Clamp	30	Automatic	36	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13.5	13.5	12.7	13.5	
12.7	13.5	12.7	13.5	
13.5	13.5	13.5	13.5	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	38	40
2	45	48
3	46	50

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	20	20
Lining (Shoe)	19	19
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SINGH, RAVINDERPAL
Road Test Date: *Ravinderpal Singh*
Signature: *Ravinderpal Singh*
Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-27 09:14 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

5/27/2026 9:14:43 PM PDT