



Commercial Vehicle Inspection Report

Decal Number: GH03005
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21394261

E13-1
Inspection Result:
PASS

FACILITY: CALVER AUTOMOTIVE / S7130 INSP. TYPE: Complete INSP. START: 2025-Jun-17 11:00 AM PDT
INSPECTOR: VIRK, MANPREET SINGH / 114386 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2025-Jun-17 01:00 PM PDT
WORK ORDER #: 5399 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 11829814 VIN: 1M1AW09Y0BM013614
PLATE #: UNIT/FLEET#: OWNER/LESSEE NAME: LOAD WARRIOR LOGISTICS, LTD.
LICENCED GVW(kg): 12900 BODY STYLE: Truck Tractor ADDRESS: 45233 WATSON RD
VEHICLE YEAR: 2011 ODOMETER: 864747 KM Chilliwack, British Columbia
MAKE: MACK HUB ODOMETER: V2R 2G4, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) INTERMEDIATE DRIVE SHAFT , #1 ,#2 UJOINTS REPALCED
Section 2 - Suspension	Repaired (same day) SUSPENSION LEVELING VALVE REPALCED
Section 3 - Brake System	Repaired (same day) BRAKES ADJUSTED
Section 3A - Air Brakes	Repaired (same day) #2 ,#3 BOTH SIDES BRAKES AND DRUMS REPALCED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) STEERING OIL LEAK REPAIRED
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) D/S STEP SECURED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	25.4	25.4	6			6	✓
2	Clamp	30	Automatic	44.5	38.1	4	4	5	5	
3	Clamp	30	Automatic	47.6	44.5	7	4	5	5	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	62	68
2	45	40
3	65	50

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	13	13
Lining (Shoe)	21	21
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: VIRK, MANPREET SINGH

Signature:

This Inspection Report was submitted to CVSE on 2025-Jun-17 07:39 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV P at the Commercial Vehicle Safety Enforcement

CVSE014

6/17/2025 7:40:35 PM PDT