

Commercial Vehicle Inspection Report

Decal Number: RD07176
Decal Expiry Date: 2025-Sep-18
Inspection Number: 21484619

E15-2 Inspection Result:
FAIL

FACILITY: Velocity Truck Centres / S20451 **INSP. TYPE:** Complete **INSP. START:** 2025-Sep-04 07:33 AM PDT
INSPECTOR: NAIRN, COLBY JAMES / 110624 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW **INSP. COMPLETE:** 2025-Sep-04 09:46 AM PDT
WORK ORDER #: 6880 **INSP. REASON:** Annual

VEHICLE JUR: British Columbia **REGI:** 09909736 **VIN:** 1FVACWU9BDAU9860
PLATE #: 58557P **UNIT/FLEET#:** **OWNER/LESSEE NAME:** transsource freightways ltd, transsource freightways ltd
PERMITTED GVW(kg): 14969 **BODY STYLE:** Van **ADDRESS:** 1659 fosters way
VEHICLE YEAR: 2011 **ODOMETER:** 626623 KM **Delta, British Columbia**
MAKE: FREIGHTLIN **HUB ODOMETER:** v3m6s7, Canada
MODEL: **BRAKE TYPE:** Hydraulic
FUEL TYPE:

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Failed	rear brakes worn out both sides (pads and rotors)
Section 4 - Steering	Failed	suction line leaking
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Failed	windshield broken, lh bumper wing falling off, rh splash fender behind steer tire broken and falling off
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	10.3			10.3	✓	Pad	15.9	15.9	Rotor	36.73	36.60
2	15.9	15.9	16.7	16.7		Pad	4.8	4.8	Rotor	35.61	35.71
Comment:						Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**
Inspector: NAIRN, COLBY JAMES **Signature:** _____

This Inspection Report was submitted to CVSE on 2025-Sep-04 09:50 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

1/4/2025 9:50:43 AM PDT