



ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au



Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:
 [Redacted]
 [Redacted]
 [Redacted]

Deliver To:
 [Redacted]
 [Redacted]
 [Redacted]

Document No.:	609929
Invoice To:	7773
Document Date:	26/06/2024
Repair Order No.:	324750
Rego No.:	EJE851865
Make/Model:	CASE IH OPTUM 270 CVX
Serial No.:	EJE851865
Hours:	5931
P/Order No.:	

General

CUSTOMER REPORTS ENGINE KNOCKING NOISE.

Labour Total \$17,508.02

8/11/2023- travel to property and investigate knock. found nothing outstanding/no codes on EST. returned to workshop traveled back to property and removed and replaced oil filter and oil. remove and replac fuel filters. removed turbo piping and inspected turbo and foubd excessive movment on turbo shaft, refit piping replaced hose clamps on overflow bottle. recomended tractor delivered to workshop for further inspection.

cut open oil filter and inspected element, found ferrous and non ferrous material. removed turbo, disassembled and inspect found unservicable.

10/11/2023- removed air filter system and exhaust system

remove rocker cover and inspect

removed oil filterand cut open found excessive materials drained oil and found fragments of bearing shell.

disconnect bonnet wiring loom and remove bonnet

disconnect ad blue system and fuel lines

remove fuel tanks

drain and removed radiator

vac down air con system

disconnect and removed condensor

and receiver dryer

remove front weights

jack up front of tractor

Disconnect front axle drive lines

Hydraulic and electrical conections

Remove seized front suspension pins

Remove front axle

Manifactor lifting points for engine

Disconnect engine loom

Take weight of engine with fork lift by manufactured lift points

Remove bell housing bolts

Removed engine





ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au



Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

Invoice To:
 [Redacted]
 [Redacted]
 [Redacted]

Deliver To:
 [Redacted]
 [Redacted]
 [Redacted]

SERVICE TAX INVOICE

Document No.:	609929
Invoice To:	7773
Document Date:	26/06/2024
Repair Order No.:	324750
Rego No.:	EJE851865
Make/Model:	CASE IH OPTUM 270 CVX
Serial No.:	EJE851865
Hours:	5931
P/Order No.:	

General

Dissassembled engine
 Remove vslve train and clean
 Remove cylinder head
 Lift and rotate engine
 Remove sump and clean
 Remove pistons and con rods
 Remove cam shaft
 Remove oil pump
 Remove crank shaft
 Clean and inspect parts
 Found bearing spun on big end no.5
 Cam has had lack of oil and damaged as has rocker gear
 Test cylinder head and found majority of valves not sealing/seating
 Removed pick up filter and found blockage of bearing of bearing shell
 have had slight seizure in cylinders
 DEEMED MAJOR ENGINE FAIURE DUE TO HIGH HEAT AND LACK OF OIL/OIL PRESSURE
 measure and check specs found cam and ll valve train require replacement
 Measure crank and will require grind or replacement
 Check cylinder bores and will require boring or replacement
 Ducto servre damage though out
 Recommend replacing engine with long block

Part Number	Part Description	Quantity	Nett Value	Total Cost
5802001326	Misc	1.00	18,023.68	18,023.68
10W-40	No.1 Eng Oil 10W40 73394624	40.00	10.88	435.20
B2480	Misc	2.00	1.80	3.60





ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au



Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:
 [Redacted]
 [Redacted]
 [Redacted]

Deliver To:
 [Redacted]
 [Redacted]
 [Redacted]

Document No.:	609929
Invoice To:	7773
Document Date:	26/06/2024
Repair Order No.:	324750
Rego No.:	EJE851865
Make/Model:	CASE IH OPTUM 270 CVX
Serial No.:	EJE851865
Hours:	5931
P/Order No.:	

General					
CONS	WORKSHOP CONSUMABLES		1.00	29.50	29.50
Parts Totals:			44.00		\$18,491.98

Advisor: Neil Street

Sub Total for All:	\$36,000.00
Rounding:	\$0.00
GST:	\$3,600.00
Total:	\$39,600.00

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

Bank Account Details for Direct Payments:

Bank: BBL Branch: TRAFALGAR
 BSB: 633000 Account No.: 118215821 Account Name: TRAF TRACTOR & MACHINERY PTY LTD





ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au



Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:
 Internal Used
 Stock No. 200957

Deliver To:

Document No.: 616759
Invoice To:
Document Date: 25/10/2024
Repair Order No.: 330676
Rego No.:
Make/Model: SE IH OPTUM 270 CVX TRACTOR
Serial No.: DBDOP270EJE851865
Hours: 5932
P/Order No.:

General

REINSTALL ENGINE

Labour Total \$23,322.50

AS DISCUSSED BETWEEN SIMON AND HARROW THE CUSTOMER IS PAYING FOR THE CURREN WORK FOR ENGINE TO BE REMOVED FROMTRACTOR AND IS PAYING FOR THE NEW ENGINE FOR THE TRACTOR AS DISCUSSED WITH ALL WILL BE CHARGED OUT 26/6/24 AND WHEN NEW ENGINE TURNS UP TTMI/STOCK NUMBER WILL TAKE THE COST OF PUTTING THE NEW ENGINE BACK INTO THE TRACTOR
 FITTED OLD FLYWHEEL TO NEW ENGINE FITTED NEW ENGINE TO TRANSMISSION OF TRACTOR, FITTED STARTED MOTOR, STARTED RUNNING ENGINE WIRING HARNESS
 FITTED FRONT DIFF ASSEMBLY TO THE TRACTOR, FITTED DRIVELINE TO TRACTOR
 FITTED FAN HUB AND FAN BELT, FITTED AIR BOX BRACKET AND BONNET SUPPORT,
 STARTED FITTING HYDRAULIC/FUEL/COOLANT LINES
 FITTED AIRBOX TO FRAME AND COOLANT RESEVOIR, FITTED DOC UNIT AND COOLANT LINES
 FITTED COOLER ASSEMBLIES, STARTED FITTING FUEL AND ADBLUE TANKS
 COMPLETED FITTING STEERING AND SUSPENSION HYDRAULIC LINES, FINISHED FITTING FUEL AND ADBLUE TANKS
 FITTED BRASCKETS FOR SCR UNIT, FITTEDSCR UNIT TO TRACTOR, RAN WIRING HARNESS FOR SCR UNIT
 FITTED BATTERY BOX, TESTED BATTERY, FINISHED RUNNING ENGINE WIRING HARNESXS, STARTED PUTTING ON SOME COVERS
 FITTED ALTERNATOR AND HYDRALIC LINES TO COOLER, FULE LINESTO COOLER AND RADIATOR LINES
 CONNECTED FUEL AND ADBLUE LINES, REMOVED ADBLUE DOSING INJECTORS AND CLEANED READY FOR TESTING
 TESTED ADBLUE SYSTEM, FITTED REAR WHEEL, STARTED TRACTOR , FITTED BONNET
 CHANGED ADBLUE FILTERS, FITTED NEW ADBLUE HOSE, FITTED FLARES ONTO REAR GUARDS, WASHED TRACTOR
 REMOVED REAR PTO HOUSING ASSEMBLY, LISTED PARTS TO ORDER
 DISASSEMBLED PTO ASSEMBLY AND FITTED NEW PARTS
 INSTALLED PTO ASSEMBLY AND STARTED MAJOR SERVICE
 COMPLETED MAJOR SERVICE, CHECKED AND COMPLETED ENGINEFITMENT, FITTED REAR DUALS TO TRACTOR
 FITTED REMAINING COVERS AND GUARDS TO TRACTOR, RAN ON DYNO FOR A SHORT TIME





ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au



Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:
 Internal Used
 Stock No. 200957

Deliver To:

Document No.: 616759
Invoice To:
Document Date: 25/10/2024
Repair Order No.: 330676
Rego No.:
Make/Model: SE IH OPTUM 270 CVX TRACTOR
Serial No.: DBDOP270EJE851865
Hours: 5932
P/Order No.:

General

CHECKED CODES ON TRACTOR COMPUTER
 ALL OK

Part Number	Part Description	Quantity	Nett Value	Total Cost
47723590	Misc	1.00	101.28	101.28
47715391	FILTER, HYDRAULIC OI	1.00	214.63	214.63
47531260	BELT	1.00	106.73	106.73
47482160	Misc	1.00	34.43	34.43
47364243	MAIN FILTER KIT DENOX	1.00	151.91	151.91
14459881	Seal	1.00	2.88	2.88
00571045	M10 X 45 BOLT	3.00	0.94	2.82
S.19218	Misc	3.00	7.15	21.45
PX56521	PTEX HIPER THR SEALANT 50ML	1.00	14.64	14.64
HY-TRAN	HY-TRAN ULTRACTION 73394634	85.00	7.55	641.75
FREIGHT	FREIGHT	1.00	2,820.45	2,820.45
04075710	M10 FLAT WASHER	3.00	0.31	0.93
5175983	SEAL, RING	1.00	42.45	42.45
O-RING	MISC. O-RINGS	10.00	0.06	0.60
DIESEL	DIESEL - PER LT	105.00	2.00	210.00
47513121	BELT	1.00	27.58	27.58
10W-40	No.1 Eng Oil 10W40 73394624	8.00	7.41	59.28
B2482	25-51MM HOSE CLAMP	1.00	0.85	0.85
B2481	19-44MM HOSE CLAMP	2.00	0.83	1.66
47801578	Misc	1.00	47.60	47.60
B2478	Misc	2.00	0.80	1.60
TDCT305BKCD	CABLE TIE BLK 300X5MM PK100	1.00	9.00	9.00
90433749	FILTER, HYDRAULIC OI	1.00	83.80	83.80





ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au



Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:
 Internal Used
 Stock No. 200957

Deliver To:

Document No.: 616759
Invoice To:
Document Date: 25/10/2024
Repair Order No.: 330676
Rego No.:
Make/Model: SE IH OPTUM 270 CVX TRACTOR
Serial No.: DBDOP270EJE851865
Hours: 5932
P/Order No.:

General

87726675	FILTER, CAB 47863571	2.00	44.02	88.04
87517154	PRIMARY AIR FILTER	1.00	109.43	109.43
87517153	FILTER, AIR	1.00	91.32	91.32
84340074	SENSOR	1.00	307.75	307.75
84328598	FILTER - FUEL	1.00	6.18	6.18
82016943	Misc	1.00	7.49	7.49
73394604	OAT EL ANTIFR. - PREMIX 20L	2.00	107.44	214.88
51447338	Misc	1.00	80.42	80.42
87726699	FILTER, CAB	1.00	30.16	30.16
48142163	FILTER, HYDRAULIC OI	1.00	100.44	100.44
48047602	FILTER, DEF	1.00	183.24	183.24
47887906	SEAL	1.00	212.87	212.87
Parts Totals:		249.00		\$6,030.54

Advisor: Neil Street

Sub Total for All:	\$29,353.04
Rounding:	\$0.00
GST:	\$0.00
Total:	\$29,353.04

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

Bank Account Details for Direct Payments:

Bank: BBL Branch: TRAFALGAR

BSB: 633000 Account No.: 118215821 Account Name: TRAF TRACTOR & MACHINERY PTY LTD

