

Multi Tyre Roller 24t

Make: Ammann
Serial: 4302472
Model: AP240

Works Order	Completed	Work Type	Hours	Task Description
55	10-Dec-2025	On/Off Hire Inspectn	3,937.0	
54	13-Aug-2025	On/Off Hire Inspectn	3,877.0	
53	31-Jul-2025	On/Off Hire Inspectn	3,865.0	
52	04-Jul-2025	250/500/1000 Hr Serv	3,853.0	CARRIED OUT SERVICE, REPLACED ENGINE OIL + FILTER, FILTERS, INNER AND OUTER AIR FILTERS, DRAINED OIL C CAN, GREASED, BLEW OUT RADIATOR, TOPPED UP ALL LEVELS. REPAIRED INDICATORS NOT WORKING
51	09-May-2024	On/Off Hire Inspectn	3,766.0	
50	25-Mar-2024	Repair - Internal	3,717.0	needs a check over to go back out, ignition barrel playing up rep carried out full inspection repaired lights done risk assessment
49	01-Mar-2024	Breakdown	3,716.0	INSPECTED MACHINE FOR NOT STARTING, TESTED OK FO CUSTOMER TURNING THE KEY TO FAR PAST START POSIT
48	23-Feb-2024	Repair - Internal	3,700.0	INSTALLED ELECTRIC FUEL PUMP AS HAND PRIMER NOT WORKING, TESTED OK, FIT OIL CATCH CAN Parts/Labour: electric fuel pump Parts/Labour: hose fittings # OR-S073827
47	22-Jan-2024	Repair - Internal	3,700.0	CARRIED OUT INSPECTION TOPPED UP ALL LEVELS, REPLACED L/H DOOR GLASS AS SMASHED ON SITE. REPA INDICATORS.
46	22-Dec-2023	On/Off Hire Inspectn	3,614.0	
45	14-Dec-2023	On/Off Hire Inspectn	3,604.0	
44	03-Nov-2023	On/Off Hire Inspectn	3,594.0	
43	01-Nov-2023	Repair - Internal	3,594.0	Blown Turbo, blowing Smoke, pulled turbo off sent away for warr WAITING FOR NEW TURBO, got oil sample back sent off to sup of turbo. Replace turbo, flush engine twice and test. All OK.
42	21-Apr-2023	On/Off Hire Inspectn	4,254.0	
41	12-Apr-2023	Breakdown	4,222.0	drove to site near mudgee. removed air compressor and replace drain hose oring reassembled and tested ok
40	31-Mar-2023	Breakdown	4,202.0	drove to site, adjusted a/c belt/ repaired battery door
39	29-Mar-2023	Sub Asset	5,050.0	New turbo. Item required to complete engine rebuild. Parts/Labour: New replacement Turbo & Fuel Stop Solenoid
38	20-Mar-2023	Breakdown	4,171.0	drove to site found has a blown turbo removed and replaced turb cleaned out intercooler tested ok
37	13-Feb-2023	250/500/1000HrOnsite	5,050.0	Carried out 500 hr service replaced engine oil + filter, 2x fuel filte inner and outer air filter, final drive and diff oils, carried out full inspection, blew out radiator, greased, topped up all levels
36	09-Feb-2023	Breakdown	3,585.0	Machine has electrial problem, found no comunication with ecu t found blown relay for ecu, got machine running found injector fau tested ecu and harness all tested ok found plug on #4 injector pi damaged repaired tested ok
35	20-Dec-2022	On/Off Hire Inspectn	3,583.0	
34	08-Dec-2022	On/Off Hire Inspectn	3,555.0	
33	24-Nov-2022	Registration Renewal	3,542.0	REGO RENEWAL

Multi Tyre Roller 24t

Make: Ammann
Serial: 4302472
Model: AP240

Works Order	Completed	Work Type	Hours	Task Description
				Parts/Labour: - 85822D
32	03-Nov-2022	On/Off Hire Inspectn	3,542.0	
31	25-Oct-2022	Repair - Internal	3,542.0	removed engine stripped down and carried out full rebuild got block and head full machined, replaced big and little end bearing crank bearings and thrust washers, pistions + pins and rings, ca bearings, full gasket kit, new water pump and thermostat, new oi pump, refit engine, filled engine oil, coolant and hyd oil, started a checked over machine all tested ok, replaced diff input shaft, rep diff oil and drop box oil, regassed a/c, checked over machine, replaced all filters Parts/Labour: diff seal, pressure switch
30	14-Oct-2022	Sub Asset	3,542.0	Engine Rebuild - remove engine for complete rebuild. Parts/Labour: Engine parts - Cummins QSB3.3 Parts/Labour: Parts - Cap & Plugs for engine/transmission Parts/Labour: Contract Mechanic. Inv # 961 Parts/Labour: Machine & Service Cylinder Head
29	01-Jun-2022	On/Off Hire Inspectn		
28	11-May-2022	Registration Renewal	3,542.0	Rego Renewal Parts/Labour: - 85822D
27	18-Mar-2022	On/Off Hire Inspectn		
26	25-Oct-2021	250/500/1000 Hr Serv	3,381.0	Carried out service replaced engine oil + filter outer air filter, carr out inspection, greased
25	22-Oct-2021	Plant Sell Machine	3,381.0	Plant - Sell Machine
24	22-Oct-2021	On/Off Hire Inspectn		
23	27-Aug-2021	On/Off Hire Inspectn		
22	01-Jun-2021	On/Off Hire Inspectn		
21	18-May-2021	On/Off Hire Inspectn		
20	07-May-2021	On/Off Hire Inspectn		
19	29-Apr-2021	On/Off Hire Inspectn		
18	24-Mar-2021	On/Off Hire Inspectn		
17	19-Feb-2021	On/Off Hire Inspectn		
16	11-Jan-2021	On/Off Hire Inspectn		
15	10-Dec-2020	On/Off Hire Inspectn		
14	24-Nov-2020	On/Off Hire Inspectn		
13	16-Nov-2020	On/Off Hire Inspectn		
12	11-Sep-2020	Registration Renewal	2,897.0	Parts/Labour: 2,897.0 Service
10	21-Jul-2020	250/500/1000 Hr Serv		Completed. Fuel Guage still needs repairs. No leaks located
11	21-Jul-2020	250/500/1000 Hr Serv	2,897.0	250 Hour Service Due. Check /Repair Fuel Guage. Check for coolant/Hydraulic Leak.

: Multi Tyre Roller 24t

Make: Ammann

Serial: 4302472

Model: AP240

Works Order	Completed	Work Type	Hours	Task Description
				No Leaks located. Service completed. Fuel Guage still not worki Will need repair when back in the yard.
9	21-Jul-2020	Repair - Internal	2,897.0	Bonnet Latch needs repair at run up. Is being checked for a coolant/hydraulic leak by mechanic. Fuel also not working.
				Mechanic Phil repaired bonnet latch.
8	29-May-2020	Repair - Onsite	1.0	new strut and door handle, UHF replacement Parts/Labour: new strut, door latch, uhf
7	12-Feb-2020	On/Off Hire Inspectn		
6	12-Dec-2019	On/Off Hire Inspectn		
5	06-Dec-2019	Repair - Onsite	2,715.0	New reverse camera Parts/Labour: new reverse camera fitted
4	12-Nov-2019	Repair - Onsite	2,715.0	new front windscreen Parts/Labour: new front windscreen
3	01-Nov-2019	Repair - Onsite	2,715.0	Compressor broke off Engine Block Parts/Labour: weld and refit air compressor
2	30-Oct-2019	On/Off Hire Inspectn		
1	30-Sep-2019	On/Off Hire Inspectn		