

03891811

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba



F02-1

Vehicle Standards and Inspection  
Box 45084 Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-965-0920

Manitoba



A870126

Date  
Inspection  
Started  
DAY MO. YR.  
26 09 24Date  
Inspection  
Completed  
DAY MO. YR.  
28 09 24Inspection  
Expiry  
Date  
DAY MO. YR.  
30 09 25Station  
Number

A513411

Station Name

S496633 Manitob

Mechanic  
Number

M77772

Mechanic Signature

City

Station Phone Number

204 999-3179

Vehicle Owner

Sandhu Farms International Co Ltd

1349 Charlwood RD Wpg MB R3S1C3 204-998

Address

City

Province

Postal Code

Phone

2264

- ☐ Pass/Safe Vehicle  
☐ Fail/Unsafe Vehicle  
☐ Fail/Hazardous

Licence  
Number

TH21249

Prov.

MB

NSC #

Odometer  
ReadingOdom.  
Type

km

mi

Vehicle Identification  
Number

2D1EGLD121091024578

Make

Dodge

Model

Dum

Year

2009

Unit #

G271

☒ Confirmed legible Vehicle Identification Number on vehicle

## THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A

Defects (if any) Circle Brake Type

16 D Adjust All Brakes

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	9/16	9/16			1/2	1/2
2	9/16	9/16			1/2	1/2
3						
4						
5						
Final Measurement						

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

1 (D) Left Side Stop Light not working

1 (L) Left Plate Light not working

2 (B) Both Side Mud/Lap Reflector Missing

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

4 (A) check all tire Air Pressure

1 (H) RFA Both Tire fail

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	8	9	2	3	90	80	90	90
2	8	7	8	9	40	90	85	90
3								
4								
5								

Section 10 - Coupling Devices: Defects (if any)

## - THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

All Repair Done by Sandhu Farms International Co Ltd.

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

495002-01-09/15

Ce document peut être obtenu en français sur demande.

COPY IN CAR. PLEASE ENSURE CERTIFICATE IS SIGNED. NOT FOR REGISTRATION