



Commercial Vehicle Inspection Report

Decal Number: GP05270
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21916030

Inspection Result:
PASS

FACILITY: BERK'S INTERTRUCK LTD. / S0134
INSPECTOR: CLIFFORD, JOSEPH RODERICK / 115150
WORK ORDER #: 16446

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Sep-09 08:00 PM PST
INSP. COMPLETE: 2026-Sep-11 02:30 PM PST

VEHICLE JUR: British Columbia
PLATE #: LY3461
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2020
MAKE: VOLVO
MODEL:

REGI: 13047621
UNIT/FLEET#: SF20
BODY STYLE: Truck Tractor
ODOMETER: 778489 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 4V4NC9EJ6LN241401
OWNER/LESSEE NAME: 0985821 B.C. Ltd., Shamrock Fuels
ADDRESS: 3775 Bayne Rd.
Cobble Hill, British Columbia
V0R 1L5, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPLACED REAR MOTOR MOUNTS, STEADY BEARING & EXH PIPE AT SCR
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPAIRED AIR LEAK AT FIREWALL
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) REPLACED DR. SEAT BELT
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPIRED X-MEMBER BEHIND CAB
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	24	20
2	Clamp	30	Automatic	27	25
3	Clamp	30	Automatic	30	29

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10			10	✓
5	8	8	6	
10	10	10	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	65	50
2	65	70
3	65	75

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	16
Lining (Shoe)	15	13
Lining (Shoe)	16	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:

Inspector: CLIFFORD, JOSEPH RODERICK Signature: _____

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Sep-11 02:48 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

10/6/2026 1:44:16 PM PST