

FACILITY:	BERK'S INTERTRUCK LTD. / S2211	INSR. TYPE:	Complete	INSR. START:	2026-Aug-14 01:30 PM PDT
INSPECTOR:	ATKINSON, BRANDON / 301341	INSR. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSR. COMPLETE:	2026-Aug-14 03:13 PM PDT
WORK ORDER #:	8795	INSR. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	12737915	VIN:	4V4NC9E12KN803490
PLATE #:	YA7986	UNIT/FLEET#:	19	OWNER/LESSEE NAME:	0985821 B.C. LTD, SHAMROCK FUELS
LICENCED GVW(kg):	83500	BODY STYLE:	Truck Tractor	ADDRESS:	3775 BAYNE RD, 3775 BAYNE RD
VEHICLE YEAR:	2019	ODOMETER:	821200 KM		Cobble Hill, British Columbia
MAKE:	VOLVO	HUB ODOMETER:			VOR 1L5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	28	28
2	Clamp	30	Automatic	28	28
3	Clamp	30	Automatic	28	28

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	13			13	✓
2	12	12	11	11	
3	20	20	20	20	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	30	30
2	25	55
3	40	35

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
1	Lining (Shoe)	20	20
2	Lining (Shoe)	21	14
3	Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
1	Drum		
2	Drum		
3	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: ATKINSON, BRANDON

Signature:



This Inspection Report was submitted to CVSE on 2026-Aug-14 05:22 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected for the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

8/14/2026 5:22:53 PM PDT