Commercial Vehicle Inspection Report

BRITISH COLUMBIA

Decal Number: GN89433
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21830043

Inspection Result: **PASS**

FACILITY:	BERK'S INTERTRUCK LTD. / S2211	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Jun-29 12:00 AM PDT
INSPECTOR:	MOYSE, TRISTAN EDWARD / 202424	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Jun-29 02:15 PM PDT
WORK ORDER #:	R108008555	**INSP. REASON:**	Semi-annual		

VEHICLE JUR:	British Columbia	**REGI:**	12491896	**VIN:**	5KJJALD13JPJX4534
PLATE #:	WJ4025	**UNIT/FLEET#:**		**OWNER/LESSEE NAME:**	0985821 B.C. LTD, SHAMROCK FUELS
LICENCED GVW(kg):	63500	**BODY STYLE:**	Truck Tractor	**ADDRESS:**	3775 BAYNE RD, 3775 BAYNE RD
VEHICLE YEAR:	2018	**ODOMETER:**	686879 KM		Cobble Hill, British Columbia
MAKE:	WESTERN ST	**HUB ODOMETER:**			V0R 1L5, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	**Repaired (same day)**	REPLACED LEAKING OUTPUT SEAL ON FORWARD DRIVE AXLE. REPLACED RIGHT FRONT HUB CAP. REPLACED FLEX PIPE TO STACK.
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	**Repaired (same day)**	REPLACED PASSENGER SIDE LOW BEAM LIGHT.
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Repaired (same day)**	REPLACED PASSENGER SIDE WINDSHEILD AND WIPER LINKAGE.
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	25.4	28.6
2	Clamp	30L	Automatic	31.8	31.8
3	Clamp	30L	Automatic	28.6	31.8

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
9.5			11.1	✔
18.3	18.3	18.3	18.3	
18.3	18.3	18.3	18.3	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	60	60
3	80	75

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	14	14
Lining (Shoe)	12	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: MOYSE, TRISTAN EDWARD **Signature:**

This Inspection Report was submitted to CVSE on 2026-Jun-29 03:54 PM PDT
The inspectors signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014
6/29/2026 3:54:22 PM PDT