

04105908

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

F02-3

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2G 5C7
1-204-985-0920

Manitoba

C088324

Date Inspection Started 17 06 26
Date Inspection Completed 29 06 26
Inspection Expiry Date 30 06 27

Station Number A6250 FORTRO TRUCK SERVICES LTD
Mechanic Number M8848
Vehicle Owner FRESCH PORK INC
Address SE 13-5-4E GRANTHAL MB
City Grantthal Province MB Postal Code R0A0R0
Station Phone Number 204-433-3379

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number TAD9139

Prov. MB

NSC #

Odometer Reading

Odom. Type km ml

Vehicle Identification Number

DIDELB5A310A110261114

Make DEPKER

Model GRAY LEAD

Year 10

Unit #

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 13A - ALL GLAD HANDS CORRODED 16A - LR BRAKES HANGING UP 13C - TIE UP AIR LINES 16D - LR SLACK ADJUSTER STRIPPED OUT Brake Inspection Type: A B C D E Circle appropriate letter for Internal Brake Component Inspection
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 1H - MARKER LIGHTS INOPERATIVE X3
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) SE - SIDE FRAME RAIL RUSTED THROUGH, 6C - REAR TAIL LIGHT CROSSMEMBER RUSTED THROUGH, 5J - FRONT HOPPER RUSTED THROUGH, 21A - LR FENDER AND BRACKET CRACKED
X		Section 9 - Tire & Wheel: Defects (if any)
X	X	Section 10 - Coupling Devices: Defects (if any) 7D - LUBE AND ADJUST FIFTH WHEEL LATCHING

Axle	Tread Depth 32ND				Air Pressure PSI			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	10	10	7	9	100	100	100	100
2	14	14	12	13	100	100	100	100
3	14	14	14	14	100	100	100	100
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

FV30022-01 (R 06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE