BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GM35787
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21667089

Inspection Result: **PASS**

FACILITY:	BERK'S INTERTRUCK LTD. / S2211	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Feb-17 02:55 PM PST
INSPECTOR:	PURCHASE, ANDREW / 300290	**INSP. CLASS:**	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2026-Feb-17 04:55 PM PST
WORK ORDER #:	7914	**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REG:**	12128220	**VIN:**	2AEARPAE67R000295
PLATE #:	70772U	**UNIT/FLEET#:**	SFT11	**OWNER/LESSEE NAME:**	0985821 B.C. LTD, SHAMROCK FUELS
LICENCED GVW(kg):	999999	**BODY STYLE:**	Tank Trailer	**ADDRESS:**	3775 BAYNE RD, 3775 BAYNE RD
VEHICLE YEAR:	2007	**ODOMETER:**			Cobble Hill, British Columbia
MAKE:	ADVANCE	**HUB ODOMETER:**			V0R 1L5, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	**Repaired (same day)**	REPLACED LININGS AND DRUMS ALL WHEEL ENDS
Section 3A - Air Brakes	**Repaired (same day)**	REPLACED #1 L AND #2 L AND R PIGGY BACKS
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	28	28
2	Clamp	30	Automatic	28	28

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
6	6	9	11	
6	5	6	6	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	15	15
2	15	15

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	22	22
Lining (Shoe)	22	22

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: PURCHASE, ANDREW **Signature:**

This Inspection Report was submitted to CVSE on 2026-Feb-17 04:56 PM PST
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Br. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014
2/17/2026 4:56:23 PM PST