



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GP63178
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21950101

Inspection Result:
PASS

FACILITY:	BERK'S INTERTRUCK LTD. / S2211	INSP. TYPE:	Complete	INSP. START:	2026-Oct-09 01:00 PM PDT
INSPECTOR:	ATKINSON, BRANDON / 301341	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Oct-09 02:50 PM PDT
WORK ORDER #:	9088	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	14418358	VIN:	4V4NC9EH6RN634482
PLATE #:	SA0410	UNIT/FLEET#:	SF23	OWNER/LESSEE NAME:	0985821 B.C. LTD, SHAMROCK FUELS
LICENCED GWW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	3775 BAYNE RD, 3775 BAYNE RD
VEHICLE YEAR:	2024	ODOMETER:	414156 KM		Cobble Hill, British Columbia
MAKE:	VOLVO	HUB ODOMETER:			VOR 1L5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axis	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	28	28	12			13	✓
2	Clamp	30L	Automatic	30	30	11	12	12	11	
3	Clamp	30L	Automatic	30	30	17	18	18	17	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axis	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	60	Lining (Shoe)	14	14	Drum		
2	75	60	Lining (Shoe)	14	14	Drum		
3	75	70	Lining (Shoe)	14	14	Drum		

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: ATKINSON, BRANDON

Road Test Date:

Signature:

Road Tester:

This inspection Report was submitted to CVSE on 2026-Oct-09 02:59 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and this National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

CVSE014

10/9/2026 2:59:06 PM PDT