



Commercial Vehicle Inspection Report

Decal Number: GR10638
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21950749

Inspection Result:
PASS

FACILITY: BERK'S INTERTRUCK LTD. / 60134
INSPECTOR: King, Douglas Robert / 105005
WORK ORDER #: 16752

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Oct-09 02:30 PM PDT
INSP. COMPLETE: 2026-Oct-10 11:15 AM PDT

VEHICLE JUR: British Columbia
PLATE #: WV3154
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2023
MAKE: VOLVO
MODEL:

REGI: 14169265
UNIT/FLEET#: SF22
BODY STYLE: Truck Tractor
ODOMETER: 497045 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 4V4NC9EJ5PN325750
OWNER/LESSEE NAME: 0985821 BC LTD. 0985821 BC LTD
ADDRESS: 3775 BAYNE RD.
Cobble Hill, British Columbia
V0R 1L5, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) REAR DRAG LINK END WORN
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) CLAMP LOOSE FOR PRODUCT PIPE CROSSING FRAME RAIL
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Stack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	22.2	22.2	12			12	
2	Clamp	30	Automatic	31.8	31.8	8	7	8	9	✓
3	Clamp	30	Automatic	28.8	28.8	11	10	10	10	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)
			Lining/Pad			Rotor/Drum
1	65	65	Lining (Shoe)	15.9	15.9	Left
2	45	50	Lining (Shoe)	17.5	17.5	Right
3	45	45	Lining (Shoe)	17.5	17.5	Drum

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: King, Douglas Robert

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Oct-10 11:10 AM PDT.

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCAVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

10/10/2026 11:19:59 AM PDT